AREA IN NEED OF REDEVELOPMENT STUDY

Block 10, Lots 4, 5, 9, 10, 18, 19 and 20 Borough of Bound Brook, New Jersey

Prepared for the Borough of Bound Brook in Accordance with the New Jersey Local Redevelopment and Housing Law (N.J.S.A. 40A:12A-1 et seq.)

The original of this report was signed and sealed on November 8, 2021 in accordance with Chapter 41 of Title 13 of the New Jersey State Board of Professional Planners

Carlos Rodrigues FAICP / PP New Jersey Professional Planner #5107

TABLE OF CONTENTS

- 1. Introduction and Background
- 2. Statutory Authority and Procedural Requirements
- 3. Location and Description of Study Area Properties
- 4. Analysis of Other Properties in Block 10
- 5. The Regional Planning Framework
- 6. The Municipal Planning Framework
- 7. Municipal Zoning and Land Development Regulations
- 8. Application of the Statutory Criteria to the Study Area
- 9. Findings and Recommendations

APPENDICES

Professional Qualifications for Carlos Rodrigues FAICP / PP

Bound Brook Borough Council - Resolution 2021-165

Study Area Properties – Site Photos and Description

Study Area – Property Record Cards for Study Area Properties

Building Use and Occupancy Survey of Other Properties in Block 10

Borough Building Department – Permit Records for Study Area Properties

Borough Police Department – Incident Report for Study Area Properties

Borough Fire Department – Incident Report for Study Area Properties

1. INTRODUCTION AND BACKGROUND

By Resolution 2021-165 (attached as Appendix 1) adopted on July 27 of 2021 the Bound Brook Borough Council directed that a Preliminary Investigation be undertaken to determine whether certain properties in the Borough, specifically Block 10, Lots 4, 5, 9, 10, 18, 19 and 20, qualify as an "area in need of redevelopment -- condemnation" pursuant to New Jersey's Local Redevelopment and Housing Law (LRHL), N.J.S.A. 40A:12A-1 et seq.

The purpose of the present study is to provide the Borough with the substantive information that will allow it to issue a formal determination as to whether the above-mentioned properties (hereinafter referred to as the "Study Area") meet the statutory requirements for designation as an "area in need of redevelopment".

In point of fact, the entirety of Block 10, including the Study Area properties, has been designated as an "area in need of redevelopment – condemnation" for many years, based on a <u>Redevelopment Study:</u> <u>Preliminary Investigation</u> dated November 1999, prepared by the Bound Brook Planning Board, with the assistance of John Cilo, Jr. Associates, Inc.

A <u>Redevelopment Plan for Area 1</u>, which includes the Study Area, was subsequently adopted, and has been revised a number of times over the years. Implementation of this Plan is on-going, with numerous redevelopment projects underway or already completed, but to date none in Block 10.

The original designation as an "area in need of redevelopment" was based exclusively on the application of criterion (f) in the statute (see Section 2 of this report) which applies to "Areas, in excess of five contiguous acres, whereon buildings or improvements have been destroyed, consumed by fire, demolished or altered by the action of storm, fire, cyclone, tornado, earthquake or other casualty in such a way that the aggregate assessed value of the areas has been materially depreciated". The 1999 Preliminary Investigation was conducted immediately following the tragic events of Hurricane Floyd, which completely flooded the downtown and destroyed numerous businesses.

Bound Brook's downtown had been subject to many flooding events over the years. The entire southern part of the Borough, including the Main Street area, lies within the Raritan River flood plain and its tributaries, the Middle Brook and the Bound Brook, that comprise the western and eastern boundaries of the Borough. In 1999, the downtown was devastated by Hurricane Floyd, when flood waters reached a 42-foot elevation. In 2007, the river reached 38 feet.

The Army Corps of Engineers addressed these flooding problems through the <u>Green Brook Flood Control Project</u>, designed to provide protection from a 150-year flood event. Flood control protection was put in place on either side of the downtown, with a system of levees, flood walls, flood gates, pumping stations and designated "over topping" areas.

Now, more than 20 years later, circumstances in the Borough's downtown have changed, in particular following the successful completion of the flood control project, which removed the downtown from the flood hazard area. The purpose of the current Preliminary Investigation is then to verify that the Study Area properties continue to satisfy the legal requirements for designation as an "area in need of redevelopment", and that such a designation is not predicated exclusively on criterion (f) in the statute.

The Study Area is located in the Borough's southern section, in the downtown, and has frontage on Maiden Lane (to the East), East Main Street (to the South), and Mountain Avenue (to the West). See Figure 1: Regional Location Map for Study Area and Figure 2: Parcel Map for Study Area and Immediate Surroundings.

In addition to the seven parcels previously identified, the Study Area also includes a 14-foot wide public alley, that connects Maiden Lane to Mountain Avenue, and therefore runs roughly parallel to East Main Street.

Lots 4 and 5 have frontage on Maiden Lane. Lot 5 also has frontage on the alley. Lots 9 and 10 have frontage on East Main Street, and abut the alley to the rear. Lots 18 and 19 have frontage on Mountain Avenue. Lot 18 also has frontage on the alley. Lot 20 is in the middle of the block and is landlocked – its only frontage is on the alley.

The combined area of the Study Area lots, plus the alley right-of-way, is approximately .92 acres.

In preparation for this study, the following documents were reviewed:

- Official tax maps of the Borough of Bound Brook
- Tax records for the seven parcels, as well as for all other parcels in Block 1
- Bound Brook Building Department records for the Study Area properties
- Bound Brook Fire Department records for the Study Area properties
- Bound Brook Police Department records for the Study Area properties
- Aerial photograph of the Study Area
- 2012 Downtown Urban Design Plan Master Plan Amendment
- 2017 and 2019 Master Plan Reexamination Reports
- 2019 Master Plan Land Use Element
- Borough of Bound Brook Land Development Regulations
- New Jersey State Development and Redevelopment Plan, 2001
- Somerset County Investment Framework, 2014
- Area 1 Redevelopment Study: Preliminary Investigation, 1999
- Redevelopment Plan for Area 1, 2000 with multiple subsequent amendments
- Sanborn Fire Insurance Map, 1927
- New Jersey Site Evaluator
- New Jersey Smart Growth Areas Map
- Google Maps.

The Study Area, and the exterior of the buildings, were physically inspected and photographed on October 11, 2021 by Ms. Julie Grof, PP / AICP. Photographs visually documenting the exterior conditions of the buildings and alley within the Study Area on that date can be found in the Section 3 of this report.

To establish context, all other buildings and properties in Block 10 were also researched and documented. These buildings and sites were physically inspected (exterior only) and photographed on October 11, 2021. The findings from this exercise are discussed in Section 4 of this report. Photographs visually documenting the exterior conditions of these buildings and sites on that date can also be found in Section 4 of this report.

A short description of the bona fides for Carlos Rodrigues FAICP / PP can be found at the end of this report.

2. STATUTORY AUTHORITY AND PROCEDURAL REQUIREMENTS

The Local Redevelopment and Housing Law (N.J.S.A. 40A:12A-5) provides that [a] delineated area may be determined to be in need of redevelopment if, after investigation, notice and hearing as provided in Section 6 of P.L.1992, c.79 (C.40A:12A-6), the governing body of the municipality by resolution concludes that within the delineated area any of the following conditions is found:

- a. The generality of buildings are substandard, unsafe, unsanitary, dilapidated, or obsolescent, or possess any of such characteristics, or are so lacking in light, air, or space, as to be conducive to unwholesome living or working conditions.
- b. The discontinuance of the use of a building or buildings previously used for commercial, retail, shopping malls or plazas, office parks, manufacturing, or industrial purposes; the abandonment of such building or buildings; significant vacancies of such building or buildings for at least two consecutive years; or the same being allowed to fall into so great a state of disrepair as to be untenantable.
- c. Land that is owned by the municipality, the county, a local housing authority, redevelopment agency or redevelopment entity, or unimproved vacant land that has remained so for a period of ten years prior to adoption of the resolution, and that by reason of its location, remoteness, lack of means of access to developed sections or portions of the municipality, or topography, or nature of the soil, is not likely to be developed through the instrumentality of private capital.
- d. Areas with buildings or improvements which, by reason of dilapidation, obsolescence, overcrowding, faulty arrangement or design, lack of ventilation, light and sanitary facilities, excessive land coverage, deleterious land use or obsolete layout, or any combination of these or other factors, are detrimental to the safety, health, morals, or welfare of the community.
- e. A growing lack or total lack of proper utilization of areas caused by the condition of the title, diverse ownership of the real properties therein or other similar conditions which impede land assemblage or discourage the undertaking of improvements, resulting in a stagnant and unproductive condition of land potentially useful and valuable for contributing to and serving the public health, safety and welfare, which condition is presumed to be having a negative social or economic impact or otherwise being detrimental to the safety, health, morals, or welfare of the surrounding area or the community in general.
- f. Areas, in excess of five contiguous acres, whereon buildings or improvements have been destroyed, consumed by fire, demolished or altered by the action of storm, fire, cyclone, tornado, earthquake or other casualty in such a way that the aggregate assessed value of the areas has been materially depreciated.
- g. In any municipality in which an enterprise zone has been designated pursuant to the New Jersey Urban Enterprise Zones Act, P.L. 1983, c. 303 (C.52:27H-60 et seq.) the execution of the actions prescribed in that act for the adoption by the municipality and approval by the New Jersey Urban Enterprise Zone Authority of the zone development plan for the area of the enterprise zone shall be considered sufficient for the determination that the area is in need of redevelopment pursuant to sections 5 and 6 of P.L. 1992, c. 79 (C.40A:12A-5 and 40A:12A-6) for the purpose of granting tax exemptions within the enterprise zone district pursuant to the

provisions of P.L. 1991, c. 431 (C.40A:20-1 et seq.) or the adoption of a tax abatement and exemption ordinance pursuant to the provisions of P.L. 1991, c. 441 (C.40A:21-1 et seq.). The municipality shall not utilize any other redevelopment powers within the urban enterprise zone unless the municipal governing body and planning board have also taken the actions and fulfilled the requirements prescribed in P.L. 1992, c. 79 (C.40A:12A-1 et al.) for determining that the area is in need of redevelopment or an area in need of rehabilitation and the municipal governing body has adopted a redevelopment plan ordinance including the area of the enterprise zone.

h. The designation of the delineated area is consistent with smart growth planning principles adopted pursuant to law or regulation.

The law also provides that individual properties that do not meet any of the statutory conditions may still be included within an area in need of redevelopment provided that within the area as a whole, one or more of the expressed conditions are prevalent. This provision is referred to as "Section 3" and is set forth in NJSA 40A:12A-3, which states in part that:

"a redevelopment area may include lands, buildings, or improvements which of themselves are not detrimental to public health, safety or welfare, but the inclusion of which is found necessary, with or without change in this condition, for the effective redevelopment of the area of which they are a part."

3. LOCATION AND DESCRIPTION OF STUDY AREA PROPERTIES

As previously mentioned, the Study Area under consideration (and possible re-confirmation) in this report as an "area in need of redevelopment - condemnation" encompasses seven tax parcels and a public right-of-way, all located within Block 10 on the Borough's tax maps.

The immediate surrounding area contains mostly two- and three-story mixed-use buildings, with ground-floor cafes, restaurants and other retail and service uses; a noted regional theater; the train station; commuter parking; and upper-level residential or office uses in mixed-use buildings. A substantial amount of new multi-family housing has been built, or is under construction, in the surrounding blocks.

Lot 4 is a roughly rectangular parcel, with 50¹ feet of frontage on Maiden Lane, and a depth of 141 feet. It measures .15 acres and is owned by Jax Maiden Ln, LLC. Its street address is 15-17 Maiden Lane. The lot is improved with a two-story brick building built in 1915, with a rectangular footprint of 2,280 square feet. There appear to be two businesses on the ground floor – T&R Insulation and Firestop, and Sole's Barber Shop. The second floor is residential, and has two apartments according to the tax records. Both are occupied, according to the Borough's rental records. The property has received three citations in the last few years for "accumulation of garbage". Nine construction permits have been pulled in the last 10 years, including for the 2014 conversion of the second floor into the two apartments. The police records indicate six incidents since 2014, including an "over-dose".

Lot 5 is an irregular shaped parcel, with 55.6 feet of frontage on Maiden Lane, 149.1 feet of frontage on the public alley, 76.3 feet of width to the rear, and 141 feet along the boundary it shares with lot 4. Its street address is 11 Maiden Lane. The owner of record is Phyllis Truppelli. The lot measures .18 acres. The building is a two-story brick building built in 1910, with a 4,192 square foot footprint. The ground floor is occupied by a business called Graphic Concepts. It is unclear how the second floor is used. The property has received eight citations in the last few years for "accumulation of garbage". Three construction permits for minor alterations have been pulled in the last 10 years. The police records indicate six incidents since 2012, for parking violations and three 911 calls.


<u>Lots 9 and 10</u> front on East Main Street and abut the alley in the rear. Both are rectangular, with a depth of 93 feet and 25 feet of frontage on East Main Street. Both lots measure .06 acres.


Lot 9 has a street address of 219 East Main Street. The owner of record is Skill Computing & Trading, LLC. The lot is occupied with a two-story brick building built in 1910, with a 2,050 square foot footprint. The building is apparently vacant. The second floor of the building was at one point used as a warehouse, according to the tax records. The property has received eight citations in the last few years for "accumulation of garbage". No construction permits have been pulled in the last 10 years. The police records indicate 52 incidents since 2006, mostly related to parking, but also "burglary", "unwanted person", "property damage" and "disorderly person". An "unsafe structure notice – outstanding violations" has been issued by the Borough fire marshal.

<u>Lot 10</u> has a street address of 217 East Main Street. The owner of record is Panaderia La Reina, LLC. Lot 10 is also occupied with a two-story brick building built in 1910, with a 2,200 square foot footprint. It

¹ All parcel dimensions taken from Sheet 30 of the 2007 Tax Assessment Map of the Borough of Bound Brook, prepared by Arnold W. Barnett.

Proposed Area in Need of Redevelopment






Produced by Design Solutions LLC October 2021

Proposed Area In
Need of Redevelopment

Parcels



also appears to be vacant. The second floor of the building was used as a warehouse, according to the tax records, and more recently as a rental apartment. It is currently vacant. The property has received 12 citations in the last few years for "accumulation of garbage". No construction permits have been pulled in the last 10 years. The property owner is behind on the property taxes and the Borough has initiated a tax lien sale. The police records indicate 13 incidents since 2005, including multiple code enforcement related incidents. An "unsafe structure notice – outstanding violations" has been issued by the Borough fire marshal.

<u>Lots 18 and 19</u> are also rectangular. Lot 18 has 27.5 feet of frontage on Mountain Avenue; lot 19 has 50 feet of frontage on Mountain Avenue. Both have a depth of 93.5 feet.

Lot 18 measures .06 acres. The street address is 16 Mountain Avenue. The owner of record is A & G Mac Inc. It is occupied by a two-story brick building built in 1910, with a 2,184 square foot footprint. The ground floor is occupied by a business – Lasered Effects LLC Trophies and Awards. There is an apartment on the second floor, which is occupied. No construction permits have been pulled in the last 10 years. The police records indicate 23 incidents since 2011, mostly for parking, but also "theft" and "harassment".

Lot 19 measures .11 acres. The street address is 18 Mountain Avenue. It is also occupied with a two-story brick building built in 1910, with a 1,380 square foot footprint. The owner of record is 18 Mountain Ave LLC. The ground floor is occupied by the Downtown Bound Brook Revitalization Partnership. The second floor is residential, with one apartment, which is occupied. The property has received 23 citations in the last few years for "accumulation of garbage" and other property maintenance violations. No construction permits have been pulled in the last 10 years. The police records indicate 23 incidents since 2011, including "criminal mischief", "burglary of motor vehicle", "theft" and "code enforcement".

Finally, <u>lot 20</u> is an irregular shaped parcel. It is landlocked in the middle of the block and is only accessible from the public alley. It has 98.24 feet of frontage on the alley, and a depth that varies from 103.6 feet to the East, and 91.85 feet, to the West. It measures .21 acres. The owner of record is A & G Mac Inc. Its street address is 209 East Main Street. It is occupied with one story garages used by E&N Towing. The building footprint is 2,266 square feet. The tax records indicate that there are 17 garage / storage units. The property has received four citations in the last few years for "accumulation of garbage". No construction permits have been pulled in the last 10 years.

The <u>public alley</u>, which links Maiden Lane to Mountain Avenue, is 14 feet wide and roughly 340 feet long.

The entire Study Area, including the public alley, encompasses roughly .92 acres.

The Study Area and its immediate surroundings appear on the January 1927 Sanborn Fire Insurance Map. This map shows that the Study Area has not changed much in the last 100 years. A majority of the buildings are still there, and the public alley is in the same location. Lot 18 housed the offices for "The Chronicle", a local newspaper, while lot 19 housed a machine shop. The other buildings are not identified by name, but the street addresses appear to be the same.

Table 1 provides information on parcel size (in acres) and ownership for the Study Area properties. Four properties are owned by Limited Liability Companies (LLCs). Six properties are owned by businesses. Only three properties, including the alley, are owned by entities with Bound Brook mailing addresses.



Table 1 – Ownership of Study Area Properties

Block	Lot	Area	Owner of Record	Owner Address
		(acres)		
10	4	.15	Jax Maiden Lane, LLC	15-17 Maiden Lane, Bound Brook, NJ
10	5	.18	Phyllis Truppelli	38 Beachtree Rd, West Caldwell, NJ
10	9	.06	Skill Computing & Trading,	14 Summerville Rd, Basking Ridge, NJ
			LLC	
10	10	.06	Panaderia La Reina, LLC	87 Harrison Av, North Plainfield, NJ
10	18	.06	A&G Mac Inc c/o	238 Grant Av, Seaside Heights, NJ
			Macchiaverna	
10	19	.1	18 Mountain Av, LLC	570 Windsor St, Bound Brook, NJ
10	20	.21	A&G Mac Inc c/o	238 Grant Av, Seaside Heights, NJ
			Macchiaverna	
10	alley	.1	Borough of Bound Brook	230 Hamilton St, Bound Brook, NJ
				08805

Source: Bound Brook Tax Assessor

Table 2 shows the street address and current occupancy (or lack thereof) for each of the Study Area properties, excluding the alley.

Table 2 – Street Address and Occupancy of Study Area Properties

Block	Lot	Area	Street Address	Occupancy
		(acres)		
10	4	.15	15-17 Maiden Lane	T+R Insulation and Firestop; Sole's Barber Shop
10	5	.18	11 Maiden Lane	Graphic Concepts
10	9	.06	219 East Main St	Vacant
10	10	.06	217 East Main St	Vacant
10	18	.06	16 Mountain Av	Lasered Effects LLC Trophies and Awards; 2 nd
				floor residential
10	19	.1	18 Mountain Av,	Downtown Bound Brook Revitalization
			LLC	Partnership
10	20	.21	209 East Main St	E&N Towing
10	alley	.1	Borough of Bound	230 Hamilton St, Bound Brook, NJ 08805
			Brook	

Source: Bound Brook Tax Assessor

Table 3 provides property classification, and assessed values for land, improvements and land plus improvements, from the Bound Brook tax assessor's records for 2020.

Table 3 also provides the ratio of the value of the improvements relative to the value of the land, ie the I/L ratio. This is an indicator that is frequently used in real estate to identify property under-utilization. Typically, if the I/L ratio is less than one, the property can be considered under-utilized. In this case, only

one of the Study Area properties (lot 18 - 16 Mountain Avenue) has an I/L ratio over 1. The other six properties all have extremely low I/L ratios, under .5, which means the improvements are valued at less than 50% of the value of the land.

The second edition (2011) of the <u>Redevelopment Handbook: A Guide to Rebuilding New Jersey's</u> <u>Communities</u>, written by Stan Slachetka and Dave Roberts, has this to say on the topic:

"One indicator used to measure the economic productivity of a property is the ratio of the assessed value of the improvements on the property to the value of the land. This ratio is called the "improvement ratio" or "improvement-to-land ratio" or "I/L" ratio. The assessed values of both land and improvements for a particular property are found in local property tax records.

An improvement-to-land ratio of 1:1 or less suggests that the land is not currently supporting a reasonable value of improvements or that the property would have a higher market value if the improvements were removed, which could be evidence of stagnation." (page 64)

Table 3 – 2020 Assessed Values of Study Area Properties and Improvements/Land Value Ratios

				2020 Asse	essed Value	
Block	Lot	Property	Land	Improvements	Total	Improvements /
		Classification				Land Ratio
10	4	4A	\$288,500	\$21,407	\$309,907	.07
10	5	4A	\$308,300	\$20,020	\$328,320	.06
10	9	4A	\$142,125	\$58,700	\$200,800	.41
10	10	4A	\$142,125	\$17,900	\$160,025	.13
10	18	4A	\$99,700	\$116,400	\$216,100	1.17
10	19	4A	\$179,250	\$65,800	\$245,100	.37
10	20	4A	\$253,500	\$1,900	\$255,400	.007

Source: Bound Brook Tax Assessor

Moreover, again according to the Borough tax assessor's records, these I/L ratios have been declining significantly over time. While land values have increased noticeably, the value of the improvements has either remained stable, or actually declined. Table 4 shows land and improvement values for the seven properties for the 2018 and 2022 valuation years, as well as the corresponding I/L ratios.

Table 4 – 2018 and 2022 Assessed Values of Study Area Properties

Block	Lot	Land	Improvements	I/L Ratio	Land	Improvements	I/L Ratio
		2018	2018	2018	2022	2022	2022
10	4	\$247,500	\$179,400	.72	\$288,500	\$179,400	.62
10	5	\$266,500	\$325,700	1.22	\$308,300	\$279,700	.91
10	9	\$114,400	\$80,500	.70	\$142,100	\$58,700	.41
10	10	\$114,400	\$37,500	.32	\$142,100	\$17,900	.13
10	18	\$81,000	\$134,000	1.65	\$99,700	\$116,400	1.17
10	19	\$125,000	\$90,000	.72	\$179,300	\$65,800	.37
10	20	\$221,300	\$28,700	.13	\$253,500	\$1,900	.01

Source: Bound Brook Tax Assessor

The only building in the Study Area that maintained its value between 2018 and 2022 was 15-17 Maiden Lane (Block 10, Lot 4). All other buildings lost value, in some cases quite a bit. This is reflected in the I/L ratios, which dropped precipitously over the same time period.

On the other hand, the land value of every property in the Study Area increased between 2018 and 2022, roughly between 15% and 40%.

The very low I/L ratios for the Study Area properties, along with the vacancies and the types of uses (such as the towing operation) indicate a striking level of underutilization for properties that are one block from the Bound Brook train station, as well as Main Street, and that are zoned for substantially more intensive development (see Section 6). The tallest building in the Study Area is two stories – the zoning allows six. Given the considerable redevelopment activity that has either already taken place, or is in the pipeline, for sites located within a few minutes walking distance from the Study Area properties, it is remarkable that no redevelopment activity whatsoever has been attempted with respect to these properties and that at least one property owner is struggling to pay the property taxes.

None of the seven properties are on NJDEP's Known Contaminated Sites list.

The property record cards, building photos, building permit history, police department records and fire department records for the seven Study Area properties are presented at the back of this report.

4. ANALYSIS OF OTHER PROPERTIES IN BLOCK 10

In order to better place the Study Area within the surrounding context, the other Block 10 properties not included in the Study Area were also analyzed. The detailed results of this survey are presented in an Appendix to this report: Building Use and Occupancy Survey of Other Block 10 Properties.

There are 20 tax parcels in Block 10 that are not part of the Study Area, but a number of those parcels (lots 7 and 8, lots 11 and 12, and lots 13 and 14) are adjacent parcels with a single building, and they are taxed jointly. So for the purposes of this analysis, the number of Block 10 properties that do not include the Study Area parcels is 17. Table 5 presents the property classification, street address and type of tenant for each of these properties.

Only one ground floor property (14 Mountain Avenue) appears to be vacant, although there may be upper floor residential vacancies that we are not aware of. Other properties in this group range from the US Post Office, multi-use buildings with offices and services, retail, grocery stores, upper floor residential, and a block of eight townhouses on East Second Street.

Table 5 - Other Properties in Block 10

Block	Lot	Property	Street	Tenant
		Classification	Address	
10	1	15F	24 Mountain Av	US Post Office
10	2	2	212-214 East 2 nd	Residential
			St	
10	3	2	218 East 2 nd St	Residential
10	3.01	2	220 East 2 nd St	Residential
10	3.02	2	222 East 2 nd St	Residential
10	3.03	2	224 East 2 nd St	Residential
10	3.04	2	226 East 2 nd St	Residential
10	3.05	2	228 East 2 nd St	Residential
10	3.06	2	230 East 2 nd St	Residential
10	3.07	2	232 East 2 nd St	Residential
10	6	4A	225-231 East	Multiple office and services
			Main St	
10	7 + 8	4A	223 East Main St	World Supermarket
10	11 + 12	4A	215 East Main St	Retail, AiT USA Institute 2nd floor
				residential
10	13 + 14	4A	211 East Main St	Restaurant
10	15	4A	205-207 East	Latino minimarket; 2 nd floor residential
			Main St	
10	16	4A	201-203 East	Retail / services; 2 nd and 3d floor
			Main St	residential
10	17	4A	14 Mountain Av	Vacant

Among the 17 properties, there is one single-story building (225-231 East Main Street) and one three-story building (201-203 East Main Street). All the other properties in Block 10 not included in the Study Area have two-story buildings.

Lot sizes are quite small, varying between .02 acres and .2 acres, which may help to explain the lack of redevelopment interest to date. A majority of these buildings are mixed-use.

There are no properties on NJDEP's Known Contaminated Sites list.

As might be expected, land values and building values vary widely, depending upon the size of the lot, the square footage of the building, and the number of floors in the building.

In the absence of square footage information for each building, it is not possible to standardize the assessed values for the buildings on a per square foot basis, for purposes of comparison.

Assessed land values range from \$465,800 for a .2-acre lot (the US Post Office property) to \$69,800 for a 1,742 square foot lot.

Assessed building (improvements) values range from \$835,900 for a two-story building on a .22-acre lot to \$57,500 for a two-story, 1,248 square feet townhouse on a 1,392 square foot.

Table 6 shows the assessed values of land and buildings (improvements), as well as the I/L ratios for each of the 17 properties.

Table 6 – Assessed Value and Improvements/Land Ratios for Other Properties in Block 10

				2018 Assess	ed Value	
Block	Lot	Property	Land	Improvements	Total	I / L Ratio
		Classification				
10	1	15F	\$416,800	\$835,900	\$1,252,700	2.0
10	2	2	\$45,900	\$375,700	\$421,600	8.2
10	3	2	\$39,900	\$69,900	\$109,800	1.8
10	3.01	2	\$40,900	\$73,600	\$114,500	1.8
10	3.02	2	\$40,900	\$71,500	\$112,400	1.7
10	3.03	2	\$40,900	\$57,500	\$98,400	1.4
10	3.04	2	\$40,900	\$80,600	\$121,500	2.0
10	3.05	2	\$40,900	\$64,800	\$105,700	1.6
10	3.06	2	\$40,900	\$67,400	\$108,300	1.6
10	3.07	2	\$40,900	\$67,200	\$108,100	1.6
10	6	4A	\$208,900	\$319,000	\$527,900	1.5
10	7 + 8	4A	\$208,900	\$710,000	\$918,900	3.4
10	11 + 12	4A	\$218,800	\$325,000	\$543,800	1.5
10	13 + 14	4A	\$248,500	\$120,000	\$368,500	.5
10	15	4A	\$228,700	\$258,400	\$487,100	1.1
10	16	4A	\$238,600	\$461,900	\$700,500	1.9
10	17	4A	\$69,800	\$80,000	\$149,800	1.1

Only one property (211 East Main Street) has an I/L ratio less than one (.5). All others have I/L ratios in excess of 1, in some cases reaching 2, 3 and even 8. Only one property – lot 6 – is in tax arrears. Altogether, the evidence suggests strongly that the seven Block 10 properties in the Study Area – with their very low I/L ratios -- are completely a-typical relative to the bulk of Block 10 properties, indicating quite clearly that they are under-invested.

5. THE REGIONAL PLANNING FRAMEWORK

There is a remarkable alignment in terms of the planning policies – emanating from the various relevant levels of government – with respect to development issues in Bound Brook in general, including with respect to the Study Area. We summarize these various programs below.

5.1 The New Jersey State Development and Redevelopment Plan

The New Jersey State Planning Commission adopted, most recently in 2001, the <u>New Jersey State</u> <u>Development and Redevelopment Plan</u>, (State Plan), a document that constitutes the state's official growth management framework. The Borough of Bound Brook has been recognized by the State Planning Commission for having a planning and regulatory framework that is largely consistent with the objectives and policies of the State Plan (see section 6.3 – Center Designation – below).

5.2 The Somerset County Investment Framework and State Strategic Plan

In 2014, the Somerset County Planning Board adopted a <u>County Investment Framework</u> (CIF) to "serve as the geographic basis for all county planning projects and initiatives, and support on-going regional and local smart growth, preservation, economic revitalization, sustainability and resiliency planning initiatives; to achieve tactical alignment of land use, infrastructure and preservation plans, resources, programs, policies and investment decisions; and to convey a clear investment strategy regarding local and regional land use priorities to both public and private sectors".

The County Investment Framework builds upon, and further elaborates the spatial policies contained in the 1992 and 2001 State Plans, in the draft 2011 <u>State Strategic Plan</u>, and to some extent in the <u>New Jersey Economic Opportunity Act of 2013</u>, also known as "Grow NJ", a legislative package that consolidates several of the state's economic development incentive programs and channels them to locations with certain features and according to certain criteria.

The Bound Brook Town Center is designated as <u>Priority Growth Investment Area</u> (PGIA) #10. PGIAs are "areas where primary economic growth and community development strategies enhance quality of life and economic competitiveness are preferred, and where appropriate, growth-inducing investments are encouraged". PGIAs are areas where development and infrastructure assets are already concentrated. They are prime locations for the vibrant, mixed-use, live-work environments within walking distance of transit and green space, and that many employers, workers and households desire".

The County Investment Framework provided the platform for the <u>County Strategic Plan's Guiding Principles</u>, <u>Objectives and Implementation Agenda</u>, which further developed these concepts.

6. THE MUNICIPAL PLANNING FRAMEWORK

6.1 The Municipal Master Plan – Downtown Urban Design Plan Element

The Study Area is part of Bound Brook's downtown. The downtown and surrounding areas were the subject of a detailed <u>Downtown Urban Design Plan</u>, completed in August of 2010 and prepared by the author of this report. The Bound Brook Planning Board adopted the Downtown Urban Design Plan as a formal element of the municipal Master Plan in January of 2012.

The downtown urban design plan provided an initial guiding framework for public improvements and policies as well as private investments in and around Bound Brook's downtown area. The plan was prepared in advance of the much-anticipated completion of the US Army Corps of Engineers' Green Brook flood control project, in order to take full advantage of the increased sense of confidence that serious flooding in the downtown would be a thing of the past. The expectation – which is now clearly materializing – was that increased confidence and a more vibrant real estate market would translate into much needed reinvestment in the downtown.

The plan proposed both large-scale, transformative interventions and small-scale, more intimate changes. It recognizes that while the scale and texture of Bound Brook's downtown should not be altered in radical ways, many parcels are seriously underutilized and many uses do not have a long-term future in a downtown. Thus, underutilized surface parking lots and single-use, utilitarian industrial or commercial structures, along with other smaller buildings with no apparent historic value can be replaced with benefit as the market strengthens and demand increases.

The plan also recognized that Bound Brook's downtown needs to attract additional patrons in order to thrive. The downtown is not centrally located within the community and must compete with nearby Route 28 businesses, which are more central. The downtown must also contend with Main Street's historic location — parallel to the railroad tracks and to the industrial and rail-related activities located on the south side of the tracks. There are only two blocks of residential to the south of the tracks. This means potential downtown patrons come from the north, and the South side of Main Street generates almost no foot traffic. The plan sought to address this in several ways: by creating new activities and attractions to the South of the tracks, by improving the opportunities to cross the tracks, and by seeking to attract additional patrons from the east (Middlesex Borough), from the south (South Bound Brook) and potentially from further away.

6.2 The Redevelopment Plan for Area 1

The Borough of Bound Brook adopted, in February of 2000, <u>Redevelopment Plans</u> for Area 1 (which includes the Study Area) and for Area 2, further to the West.

Redevelopment Area 1 is generally defined as the area South of Second Street, to the Raritan River; East of East Street to the Borough line; and East of Church Street, although a few additional parcels on the West side of Church Street are also included. Referring to the Borough's tax maps, it includes all lots in Blocks 2, 2.01, 8, 9, 10, 11 and 12, and lots 34-69 in Block 1.

The Redevelopment Plans for Area 1 and Area 2 were based on a <u>Redevelopment Study: Preliminary</u> <u>Investigation</u> dated November 1999, prepared by the Bound Brook Planning Board, with the assistance

of John Cilo, Jr. Associates, Inc. This Preliminary Investigation encompassed 29 blocks and roughly 200 acres.

Criterion "f" of the redevelopment statute was invoked as the substantive basis for declaring the area "in need of redevelopment":

Areas, in excess of five contiguous acres, whereon buildings or improvements have been destroyed, consumed by fire, demolished or altered by the action of storm, fire, cyclone, tornado, earthquake or other casualty in such a way that the aggregate assessed value of the area has been materially depreciated.

The Preliminary Investigation concluded that most of the area in question had been flooded as a result of Hurricane Floyd in September 16 and 17, 1999, and that the "aggregate assessed value of the area has been materially depreciated" (page 21).

The Preliminary Investigation reported that "695 residential units were severely impacted in such a manner as to not be habitable. These structures were either not safe, not sanitary, not secure or a combination thereof" (page 13). Approximately 145 downtown businesses were reported affected; 84 business owners indicated that they would not return (page 14).

The Preliminary Investigation contains an itemized assessment for each property in the area as to whether it had been affected by flood water, and whether damage had occurred to its plumbing, electrical or structure.

By resolution dated 1/26/2000, the Bound Brook Planning Board endorsed the results of the Preliminary Investigation and recommended that the areas under study be declared "in need of redevelopment".

In 2012, the Borough adopted an amendment to the Redevelopment Plan for Area 1, prepared by the author of this report. This amendment created a new Sub-district 1 within Redevelopment Area 1, located east of South Main Street and the South Main Street traffic circle; south of East Main Street; north of the NJ Transit Railroad tracks; and east of the Bound Brook channel and the Borough line. Sub-district 1 comprises Block 2, lots 1, 1.01, 2, 2.01, 2.02, 2.03 and 2.04.

This amendment provided a more fine-tuned and place-appropriate guiding framework for private investments and public improvements and policies within the new sub-district.

A residential development consisting of 240 units of rental housing was subsequently approved, and built, in sub-district 1. This project brought a substantial number of new residents to the Borough's downtown, and thus begin to partially fulfill many years of municipal and supra-municipal planning efforts.

The expansive area designated as Redevelopment Area 1 is quite disparate. It includes much of the Borough's traditional downtown, but also the lands south of the NJ Transit railroad tracks down to the Raritan River –mostly occupied with railroad and industrial uses – as well as an area east of East High Street which is mostly occupied by civic uses, including a large municipal park. The Downtown Urban Design Plan recommended a much more nuanced and fine-grained approach to redevelopment in this area. To address these concerns, the Redevelopment Plan was further amended to create three additional Sub-districts: 1.2, 1.3 and 1.4. Sub-districts 1.5 and 1.6 were subsequently added to the Plan.

6.3 The 2017 Master Plan Reexamination Report and 2019 Land Use Plan Element

In June of 2017, the Bound Brook Planning Board adopted a comprehensive re-examination of its Master Plan. This document contains a "deep dive" into the Borough's existing conditions, not just in terms of land use, but also circulation; parks, open space and recreation; community facilities and civic functions; population and demographics; economic and fiscal base; and housing.

The 2017 Master Plan Reexamination Report recommended, among many other things, that the Borough's land use framework be substantially updated and overhauled, including with a revised zoning scheme.

The 2017 Master Plan Reexamination Report was followed by a new Land Use Plan element, adopted in February 2019, that substantially changed the Borough's land use framework, creating a series of mixed-use designations, along with other land use designations that actually corresponded to how land was used.

Finally, in October of 2019, the Land Use Board adopted another Master Plan Reexamination Report, that focused almost exclusively on changes to the land use designations, as a foundation for changing the zoning. Most of the recommendations of this document have been implemented, and the Borough's zoning map is closely aligned with its future land use plan map.

6.4 Other Relevant Planning Actions: Center Designation, Transit Village Designation and Special Improvement District

In 2000, the Borough of Bound Brook, along with the Borough of South Bound Brook, received <u>Center Designation</u> from the NJ State Planning Commission. Center designation represents the recognition, on the part of the State Planning Commission, that a community's planning and zoning framework are consistent with the policies and principles for such an area defined in the 1992 (and subsequently the 2001) NJ <u>State Development and Redevelopment Plan</u> (State Plan) – see section 5.1 above.

Under the 2001 State Plan, Bound Brook is classified as a Designated Center in the Metropolitan Planning Area (PA1) – an area that is served by water, sewer and other relevant infrastructure, including transit, and is developed in a pattern that satisfies minimum density requirements. The State Plan envisions PA1 as the priority location for the state to continue to grow, primarily through redevelopment of previously developed sites, as well as through adaptive reuse of existing buildings previously dedicated to obsolete uses, infill of vacant parcels and refill of existing, vacant structures.

Center designation recognizes that a community's planning and zoning framework are consistent with the growth management role assigned to it by the State Planning Commission in the State Plan. The designation is intended to provide priority funding from state agencies for projects in the designated areas, as well as priority access to technical assistance from state agencies.

In 2003, the Borough of Bound Brook successfully petitioned the NJ Department of Transportation and NJ Transit to be recognized with <u>Transit Village</u> designation. The Transit Village program recognizes communities that have adopted planning and zoning frameworks — within a roughly ½ mile radius from a transit facility — that support and further encourage transit ridership. Designated Transit Village communities have priority access to state funding and technical assistance for projects within the designated Transit Village areas. The Bound Brook Transit Village encompasses a roughly ½ mile area

around the Bound Brook train station, thus encompassing the entire downtown area, including the Study Area defined in this report.

Finally, in 2014 the Borough revived and re-energized its downtown <u>Business Improvement District</u> (BID), which had in effect been dormant since Hurricane Floyd. Business Improvement Districts are partnerships between a municipality and downtown stakeholders (merchants, property owners, businesses and other interests) designed to revitalize and enhance downtown areas through actions such as providing increased security, street cleaning, joint advertising, promotional events, wayfinding schemes, tenant recruitment and retention and others. The revival of the downtown BID is another indication that the Borough is serious about revitalizing the downtown, attracting new businesses and residents, filling empty space in buildings, and pursuing physical improvements to the streetscape and to public spaces.

7. MUNICIPAL ZONING AND LAND DEVELOPMENT REGULATIONS

All of the Study Area parcels are zoned Business/Residential (B/R).

The 2010 <u>Downtown Urban Design Plan</u> recommended a number of changes to the Borough's Land Development Regulations, and in particular to the provisions governing the B-R District, which covers much of the downtown area. Borough Council adopted those zoning revisions in August of 2014. The Redevelopment Plan for Area 1 – Sub-area 1.4, which includes the Study Area, was subsequently amended to defer to the underlying B-R zoning provisions, with some exceptions.

The intent of the 2014 zoning amendments was to codify the vision outlined in the Downtown Urban Design Plan, to eliminate certain discrepancies identified in that document and to implement the recommended zoning changes.

The 2014 zoning amendments recognized that the character of the B-R District is not entirely uniform, and should not be treated as such in the zoning and associated land development standards. In order to better address the differences between sub-areas within the larger district, the 2014 B-R District amendments subdivided the expansive B-R district into three "place character districts": Main Street, Arts and Downtown Residential. Portions of the Study Area are located in each of these "place character districts".

Lots 9 and 10 are located in the Main Street "place character district". Lots 18, 19 and 20 are located in the Downtown Residential "place character district". And lots 4 and 5 are located in the Arts District "place character district".

While certain general standards apply throughout the entire B-R district, each of the three "place character districts" were also assigned their own distinct standards.

The zoning regulates permitted building types in the B-R district, in addition to permitted uses. Ten permitted building types are defined, and regulated by the "place character district". All three "place character districts" also contain architectural standards. In addition to universal façade design standards, a series of place-specific facade design "strategies" are also described.

A section on downtown-specific signage supplemented and amended Section 20-10.5.

Standards for sidewalk cafes – both temporary, as well as permanent – were adopted, along with standards for temporary outdoor displays, as well as outdoor public art displays.

The B-R zoning provides flexibility in meeting parking requirements, including a "fee-in-lieu of parking" option, and the ability to satisfy parking off-site through formal agreements with either the Borough's Parking Utility (leasing public parking spaces) or other private landowners. Off-site parking is allowed within 900 feet of the site. Minimum parking standards were calibrated to a downtown, pedestrian-oriented environment. A "grandfathering" formula was created for parking-deficient pre-existing uses seeking to expand or change. A formula for calculating parking reductions resulting from shared parking between different uses was put in place, as was a bonus for dedicated public parking. New surface parking facilities are not allowed. New curb cuts are discouraged. Provisions for improving pedestrian access to parking were also adopted.

In summary, the Study Area – along with the downtown around it -- is subject to a sophisticated, state-of-the-art set of zoning and land development regulations, carefully crafted to implement the vision and objectives of the Master Plan – Downtown Urban Design Plan Element, as well as the Land Use Plan element of the Master Plan, and to attract appropriate reinvestment in the downtown, while respecting the area's scale, character and architectural integrity.

8. APPLICATION OF THE STATUTORY REDEVELOPMENT CRITERIA TO THE STUDY AREA

This section draws on the substantive findings of the previous sections to determine whether the Study Area properties meet one or more of the statutory criteria for "area in need of redevelopment" designation. For ease of reference, we repeat here the statutory language for the applicable criteria.

Criterion (e) - A growing lack or total lack of proper utilization of areas caused by the condition of the title, diverse ownership of the real property therein or other conditions, resulting in a stagnant or not fully productive condition of land potentially useful and valuable for contributing to and serving the public health, safety and welfare.

While there does not appear to be an issue with the "condition of the title" or "diverse ownership" of the seven properties in the Study Area, there is no question, in my opinion, based on the record presented in this Preliminary Investigation, that there are "other conditions" resulting in "stagnant or not fully productive conditions of land potentially useful and valuable".

One can only speculate as to what those "other conditions" might be, but when property owners allow downtown properties situated one block from the train station and from the Borough's Main Street to deteriorate and, in some cases, to sit vacant and unattended, it would appear beyond dispute that those properties are not fully productive and therefore satisfy this criterion.

The Study Area properties are objectively under-utilized and are not contributing in a meaningful way to the revitalization of the downtown. The vacancies, and the use of a centrally-located property for a small towing/parking operation indicate under-utilization and under-investment.

The lack of investment in these properties, which is manifest in the absence of building permits requests in the last 10 years, compounded by the issuance of numerous citations for property maintenance-related issues, such as garbage and trash, and numerous incidents requiring a visit from the Borough's police force, including code enforcement-related visits also denote the property owners neglect of the properties.

The extremely low I/L ratios for the Study Area properties, significantly lower than all the other properties in Block 10, indicate that the problem is not with Block 10, but rather with the Study Area properties, which are a-typical and seriously under-performing.

Criterion (f) - Areas, in excess of five contiguous acres, where buildings or improvements have been destroyed, consumed by fire, demolished or altered by the action of storm, fire, cyclone, tornado, earthquake or other casualty in such way that the aggregate assessed value of the area has been materially depreciated.

This was the designation criterion invoked in the original <u>Redevelopment Study: Preliminary Investigation</u> from November of 1999. The statute does not indicate a time limit for the valid application of this criterion. It does not say "in the past year", or "in the past 5 years". To the extent that the negative effects of a past catastrophic event are still felt today, it would appear that this criterion can be legitimately invoked.

We believe this criterion is still valid today, as the entire downtown area was undeniably "altered by action of storm [..] in such way that the aggregate assessed value of the area has been materially

depreciated." I believe that Bound Brook's downtown has not fully recovered from the after effects of Hurricane Floyd.

Technically, this criterion requires an area "in excess of five contiguous acres" and is therefore not directly applicable to the seven properties, plus the alley, which total less than one acre. However, it is applicable to the <u>entirety</u> of Redevelopment Area 1, as designated in that study, and the Study Area is included in Redevelopment Area 1. We therefore believe that this criterion is also satisfied.

Criterion (h) - The designation of the delineated area is consistent with smart growth planning principles adopted pursuant to law or regulation.

Criterion "h" is perhaps the most nebulous criterion in the redevelopment statute. It is not clear whether it is intended to facilitate redevelopment of properties located in existing smart growth areas, or to facilitate the redevelopment of properties such that they may become part of future smart growth areas.

The statement of legislative intent adopted at the time of adoption of this amendment to the statute is not helpful, as it deals exclusively with other changes to the statute and is entirely silent with regard to this criterion.

Nevertheless, criterion (h) is a valid criterion under the law. And, as documented in Section ?? of this report, the Study Area – along with the rest of the Borough's downtown -- has long been recognized by the appropriate state entities as a "smart growth location." All of the parcels examined in this Preliminary Investigation, including the alley, are located within the Community Development Boundary that defines Bound Brook (along with South Bound Brook) as a Town Center designated by the New Jersey State Planning Commission.

Downtown Bound Brook qualifies as a "smart growth area" under the state's definition under two separate criteria: it is located in the Metropolitan Planning Area (PA1) and it is part of a Designated Town Center.

While the terminology is slightly different, Downtown Bound Brook in general, and the Study Area in particular, also qualify as "consistent with smart growth planning principles" under the Somerset County Strategic Plan.

This status is codified in New Jersey's State Planning Rules (N.J.A.C. 5-85), and is reflected in the status of the area under both the <u>NJ Site Evaluator</u> and the State's <u>Smart Growth Areas Map</u>.

Smart Growth Areas are recognized and given a privileged status by a number of New Jersey State Agencies – such as the Board of Public Utilities, the NJ Economic Development Authority, the NJ Housing Mortgage Finance Agency, the NJ Department of Community Affairs, the NJ Department of Transportation, the NJ Department of Environmental Protection and the NJ Treasury – in terms of both administrative regulations and funding programs.

As such, we conclude that the Study Area qualifies as an "area in need of redevelopment" under criterion (h) of the statute, as it is "consistent with smart growth planning principles" at both the local, county and state levels.

Section 3 -- "a redevelopment area may include lands, buildings, or improvements which of

themselves are not detrimental to public health, safety or welfare, but the inclusion of which is found necessary, with or without change in this condition, for the effective redevelopment of the area of which they are a part."

This provision applies to the <u>alley</u>, which in and of itself is not "detrimental to the public health, safety or welfare", and does not qualify under the other criteria, but which is absolutely essential for the effective redevelopment of the other properties in a planned, comprehensive fashion.

The alley is the parcel that connects the other seven properties, and is critical for unlocking their redevelopment potential. The inclusion of the alley in the broader redevelopment area is key to the comprehensive planning of the entire Study Area, one of the stated objectives of the redevelopment statute.

9. FINDINGS AND RECOMMENDATIONS

It is the recommendation of this Preliminary Investigation that the Study Area properties qualify as an "area in need of redevelopment -- condemnation" under multiple criteria.

On the basis of the material evidence presented earlier in this report, we find that the Study Area properties, also known as Block 10, Lots 4, 5, 9, 10, 18, 19 and 20, along with the public alley, do qualify for re-designation as an "area in need of redevelopment – condemnation" under the Local Redevelopment and Housing Law, insofar as they meet the statutory criteria (e), (f), and (h).

In addition, the re-designation of the alley as an "area in need of redevelopment" is valid under "Section 3" of the statute (NJSA 40A:12A-3), which states that individual properties that do not meet any of the statutory conditions may still be included within an area in need of redevelopment provided that within the area as a whole, one or more of the expressed conditions are prevalent.

The alley is the right-of-way that connects the seven properties, and in the case of Lot 20, it is the only means of access to that parcel. Without the alley, there would be nothing connecting the seven parcels. With the inclusion of the alley, the seven parcels can be developed as a whole, comprehensively, which is a stated objective of the redevelopment statute.

As such, we recommend that the designation of the seven properties plus the alley as "in need of redevelopment -- condemnation" be reaffirmed, that they continue to be included in the Borough of Bound Brook's Redevelopment Area 1, and that they remain subject to the applicable provisions of the adopted Redevelopment Plan for this area, and other applicable regulations, as amended.

Table 7 summarizes the application of the various redevelopment criteria to each of the parcels in the Study Area, plus the alley.

Table 7 – Applicability of Area in Need of Redevelopment Criteria to Study Area Parcels and Alley

		Арр	licabil	ity of	Area	in Ne	ed of I	Redev	elopr	ment Criterion
Block	Lot	(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	Subsection 3
10	4	NA	NA	NA	NA	✓	√	NA	✓	NA
10	5	NA	NA	NA	NA	✓	✓	NA	✓	NA
10	9	NA	NA	NA	NA	✓	✓	NA	✓	NA
10	10	NA	NA	NA	NA	√	✓	NA	✓	NA
10	18	NA	NA	NA	NA	√	✓	NA	✓	NA
10	19	NA	NA	NA	NA	✓	✓	NA	✓	NA
10	20	NA	NA	NA	NA	√	√	NA	√	NA
alle	У	NA	NA	NA	NA	NA	NA	NA	✓	✓

APPENDIX A

Professional Qualifications for Carlos Rodrigues, FAICP / PP

Carlos Rodrigues is a Princeton, NJ based urban designer, professional planner, writer and educator with over 35 years of active engagement in the planning field.

His current planning practice represents the Federal Government, State Government, Local Governments, real estate developers, property owners, environmental groups, religious congregations, neighborhood groups and civic organizations involved in (re)development and preservation projects of merit.

He has taught graduate and undergraduate planning courses and studios at the Bloustein School of Planning and Public Policy at Rutgers, in the Landscape Architecture Department at Rutgers and in the Graduate Planning School at Columbia University.

He has worked in senior management positions in the private, public and non-profit sectors, including 10 years with the New Jersey Office of State Planning / Office of Smart Growth; as director of the Princeton planning practice at Looney Ricks Kiss Architects; as a Vice President and New Jersey Director with Regional Plan Association; and as head of Land Use and Regulatory Affairs with the New Jersey Builders Association.

He is a charter member of the Congress for the New Urbanism and a recipient of its 2001 Charter Award; a past President of the American Planning Association – New Jersey Chapter and current chair of its Urban Design Committee; a past board member of Preservation New Jersey and of the Society for American City and Regional Planning History; and past Chair of the Princeton Township Zoning Board of Adjustment.

He was inducted as a Fellow of the American Institute of Certified Planners in 2016. He is currently assisting the Institute with re-writing the AICP admissions exam. He is also assisting the Planning Accreditation Board — which is tasked with the accreditation process of planning programs at American universities — with a re-examination of its accreditation standards, with an emphasis on diversity, equity and inclusivity.

He is the editor of the fourth edition of the <u>Complete Guide to Planning in New Jersey</u>, released by the American Planning Association – New Jersey Chapter in the Summer of 2018.

A more detailed account of his bona-fides can be found at http://www.rodriguesurbandesign.com/index.html

BOROUGH OF BOUND BROOK County of Somerset

RESOLUTION 2021-165

RESOLUTION OF THE BOROUGH COUNCIL OF THE BOROUGH OF BOUND BROOK AUTHORIZING AND DIRECTING THE PLANNING BOARD OF THE BOROUGH OF BOUND BROOK TO UNDERTAKE A PRELIMINARY INVESTIGATION TO EXAMINE WHETHER CERTAIN PROPERTIES, IN PARTICULAR BLOCK 10, LOTS 4, 5, 9, 10, 18, 19 AND 20, INCLUDING THE ADJACENT PUBLIC ALLEY, ALL AS SHOWN ON THE BOROUGH TAX MAPS, LOCATED ON MOUNTAIN AVENUE, MAIDEN LANE AND EAST MAIN STREET IN THE BOROUGH OF BOUND BROOK, NEW JERSEY, QUALIFY TO BE DETERMINED AN AREA IN NEED OF REDEVELOPMENT, SPECIFICALLY A CONDEMNATION REDEVELOPMENT AREA, PURSUANT TO N.J.S.A. 40A:12A-1 ET SEQ.

WHEREAS, the Mayor and Borough Council of the Borough of Bound Brook (the "Borough") has previously adopted a resolution in January 2000 designating a certain area with the Borough, which includes Area 1, otherwise known as the Downtown Redevelopment Area, as an area in need of redevelopment pursuant to the <u>Local Redevelopment and Housing Law</u>, <u>N.J.S.A.</u> 40A:12A-1 et seq.; and

WHEREAS, the basis of the January 2000 area in need of redevelopment designation is now 21 years old and needs to be reevaluated based on various factual and legal issues;

WHEREAS, the Borough has identified certain properties located at 209, 217 and 219 East Main Street; 11, 15 & 17 Maiden Lane and 16 & 18 Mountain Avenue, specifically Lots 4, 5, 9, 10, 18, 19 and 20 in Block 10, as delineated on the Borough tax map attached hereto and made part of this resolution (the "Properties"), to be reevaluated for designation as an area "in need of redevelopment", pursuant to the Local Redevelopment and Housing Law, N.J.S.A. 40A:12A-1 et seq.; and

WHEREAS, before an area may be declared in need of redevelopment, it is legally necessary for the adoption of a resolution authorizing the Borough Planning Board to undertake a preliminary investigation to determine whether the proposed area/properties meets the criteria for designation as a redevelopment area pursuant to N.J.S.A. 40A:12A-5; and

WHEREAS, the Borough desires that the Borough Planning Board undertake an examination as to whether the Properties may be deemed "an area in need of redevelopment"; and

WHEREAS, the Borough hereby states that any redevelopment area determination shall authorize the municipality to use all those powers provided by the <u>Local Redevelopment and Housing Law</u> for use in a redevelopment area, including the use of eminent domain (hereinafter referred to as a "Condemnation Redevelopment Area"); and

WHEREAS, the notice of any hearing to be conducted by the Borough Planning Board with regards to this Resolution shall specifically state that a Condemnation Redevelopment Area determination shall authorize the municipality to exercise the power of eminent domain to acquire the Properties.

NOW, THEREFORE, BE IT RESOLVED by the Mayor and Borough Council that the Borough Planning Board is hereby directed and authorized to examine whether the properties located at 209, 217 and 219 East Main Street; 11, 15 & 17 Maiden Lane and 16 & 18 Mountain Avenue, specifically Lots 4, 5, 9, 10, 18, 19 and 20 in Block 10, as delineated on the tax map attached hereto and made part of this resolution, should be determined "an area in need of redevelopment" pursuant to Local Redevelopment and Housing Law, N.J.S.A. 40A:12A-1 et seq.

BE IT FURTHER RESOLVED THAT the Borough hereby states that any Condemnation Redevelopment Area determination shall authorize the municipality to use all those powers provided by the <u>Local Redevelopment and Housing Law</u> for use in a redevelopment area, including the use of eminent domain.

BE IT FURTHER RESOLVED THAT the notice of any hearing to be conducted by the Planning Board with regards to this Resolution shall specifically state that a Condemnation Redevelopment Area determination shall authorize the municipality to exercise the power of eminent domain to acquire any properties in the delineated area.

BE IT FURTHER RESOLVED, that this resolution shall take effect immediately.

Attest:

Jasmine D. Mathis, Borough Clerk

Date of Adoption: July 27, 2021

Mayor Pobert P. Fazor

28 32 30	EXTERIOR WALL FINISH Code Exterior Wall Finish Codes 1 = Grooved Plywood dr Equiv. 2 = Wood Siding or Equiv. 3 = Cement Block or Equiv. 4 = Till-up Concrete Panels or	
	Equiv. 5 = Common Brick on Block or Equiv. 6 Face Brick on Wood Sheathing or Equiv. 7 = Face Brick on Block or Equiv. 8 = Common Brick on Reinf. Conc. or Equiv. 9 = Face Brick on Reinf. Conc. or Equiv. 10 = Precast Con. Panels with Expose Aggregate or Equiv. 11 = Metal and Class Curtain Walls or Fouly. 12 = Stone or Equiv. 13 = Limestone or Equiv.	Heating/Cooling Unit Type Codes 1.4 Hot Mater 2 = Forced Hot Air 3 = Unit Heaters 1.2 Central Cooling 5 = Package Cooling 6 = Central Combined 7 = Package Combined 4576 / Heating/Cooling Quality Codes 1 = Low 1.2 Average 5 = High Boiler Present for Type 1 Unit 0 = No 1 = Yes
0n OBSOLESCENCE \$\frac{1}{4}\$ + Econ. Obsol. \text{ %} \t	2 13 2 2 2 2 2 2 2 2 2	Building Unit Floor Area Rate Coat Use Code Code Code Q1. Floor Area Rate Coat [1] [32] [33] [34] [45] [45] [45] [2] [54] [55] [56] [56] [56] [56]
The Code and Shell Type Codes 101 = Lt. Wood Frame 102 = Heavy Timber 201 = Month Shell Type Codes 101 = Lt. Wood Frame 102 = Heavy Timber 201 = Month Shell Type Codes 102 = Reinf. Conc. 105 = Steel 106 = Fireproof Steel 107 = Lt. Steel with Galvanized Steel Exterior 108 = Lt. Steel with Enameled Steel or Aluminum Exterior 109 = Lt. Steel with Enameled Steel or Aluminum Exterior 109 = Lt. Steel with Enameled Sandwich Panel Exterior 110 = Bent. with Mond Floor 112 = Dock High Foundation 123 = Low Quality	50 52 53 ±	ing Base r Adjustm ing Predo
Service Station 124 = Below Average Quality Service Station 125 = Average Quality Service Station 126 = Above Average Quality Service Station 127 = Good Quality Service Station 133 = Low Quality Specialty Bldg. 134 = Below Average Quality Specialty Bldg. 135 = Average Quality Specialty Bldg. 136 = Above Average Quality Specialty Bldg. 137 = Good Quality Specialty Bldg. 145 = Garden Apartments Shell Segment Quality Godes 1 = Low 3 Average 5 = High	2 33 ± ± ± ± ± ± ± ± ± ± ±	otal (
Sty/light Ground Area Perimeter 2 4 38 2 26 0 44 36 56 28 56 52 58 56 58 58 58 58 58 58	INTERIOR FINISH Card Code [2.2.0] Interior Finish Codes (1) Apt Avg. Size 300 s.f. 400 s.f. 500 s.f. 600 s.f. 700 s.f. 800 s.f. 900 s.f. 1000 s.f. and over 2 = Apt. Utility Area 3 = Hotel or Equiv. 4 = Small Off. or Equiv. 5 = Large Open Offices or Equiv. 6 = Prof. Off. or Equiv. 7 = Clinics o. Equiv. 8 = Large Retail Stores or Equiv. (9)= Retail Stores or Equiv. 10 = Banks or Equiv. 11 = Warehouse 12 = Light Mfg. Area 13 = Heavy Mfg. Area Quality Codes 1 = Low 2 = Bplow Average (3 = Average 4 = Above Average 5 = High	Fix. 30 35 15 15 15 15 15 15 15
135 38 444 134	Average Sq. Feet per Apartment Units 30	Type

1	STANDARD BUILDING ACCESSORIES DATA	BUILDING SKETCH Scale 1 [] =	
1930 194 195	30-31 32-35 36-41 42-47 48 Rate Factor -	\ <u>\</u>	
Part 20		٠,٤	
The relative formation formation and the relative formation format	1		
1			
1		9	•
10 10 10 10 10 10 10 10		•	>
PAPE 370 may be the state of th			
Proof of the state		•	0
PANAL STATE OF THE CONTRICT OF		(40)	
1		25/8	4
PAGE 1 STATE OF THE STATE OF TH			*
PAGE 3770 THE STREET OF THE ST			
10 10 10 10 10 10 10 10		6	
The Britain Accessories being a superior of the superior of th		•	
PAGE 370 TREATH TO SECOND TO SECOND THE STATE AND THE STATE AND THE SECOND TH	ard Building Accessories		
	Seq. Acces. STANDARD EXTERIOR ACCESSORIES DATA	4	
PAVE 3700 25	10-31 32-35 36-41 42-47 48 Rate Factor Cond.		
Segretar Accessories Total Control Accessories DATA Segretar Accessories Total Cost Segretar Acce	3.790	88	
		•	
State of the state		1 1	
Section Accessories Total Depocalated Cost Section Factor Section Se		Width Length Height Ground Area	Building Description
		2 Jan 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
Sec. Special Control Accessories Total Cost. Sec. Special Cost.		X	
Sec. SPECIAL EXTENDS ACCESSORIES DATA Sec. Special Cost Specia		××	
See Special Cost S		, , , , , , , , , , , , , , , , , , ,	
The first of the f		X	
Conversion facessories Total Depreciated Cost Conversion factor Conversion faces ories Total Depreciated Cost Special Exterior Accessories Total Cost Special Exterior Finish Finish Total Cost Special Exterior Finish Finish Total Cost Special Exterior Finish Total Cost Specia		X	
Conversion Factor Seq. Seq. Seq. Seq. Secretaring factor Seq. Seq		Х	
Seq. Seq. Description Descri		X	
ard Exterior Accessories Total Depreciated Cost Conversion Factor Conversion Factor Conversion Factor Seq. Special Exterior Accessories Total Cost Seq. Special Exterior Accessories Total Cost Special Cost Special Value Special Cost Special Cos		, , , , , , , , , , , , , , , , , , ,	
Seq. Special Cost Special Cost Conversion Factor Seq. Special Cost		X	
1. Structural Shell Base Cost Conversion Factor Section Accessories Total Cost Section Accessories DATA Section Accessories Total Cost Section Accessories DATA Section Accessories DATA Section Full Value Section Full Value Section Total Cost Section Access Section Acce			
2. Exterior Finish Total Cost and Exterior Accessories Total Cost Seq. SPECIAL EXTERIOR ACCESSORIES DATA Bos. Description Bos. Special Cost Anting/Cooling Total Cost Industrial Unit Heaters Total Cost Anting/Cooling Total Cost Industrial Unit Heaters Total Cost Special Cost Special Cost Special Cost Special Cost Cost Conversion Finish Total Cost Cost Cost Cost Cost Finish Total Cost Cost Cost Cost Cost Cost Cost Finish Total Cost Cost Cost Cost Cost Cost Cost Cost	Standard Exterior Accessories Total Depreciated Cost	Structural Shell Base Cost	
SPECIAL EXTERIOR ACCESSORIES DATA Seq. Specification Description Description Description Open. Full Value Specification Specification To Sprinkler System Total Specification Specification To Sprinkler System Total Specification Specification To Sprinkler System Total Specification Specification Cost Conversion Factor Final Net Condition Depreciated Building Cost Specificated	Cost Conversion Factor	Exterior Finish Total	Rents
Seq. Special Exterion Accessories bata No. 32-56 Special Installation To Sprinkler System Total Special Installation To Sprinkler System Total Standard Bldg. Access. 1975 Replacement Cost COST CONVERSION FACTOR Replacement Cost New Final Net Condition Oppreciated Building Co	Standard Exterior Accessories Total Cost	Interior Finish Total Heating/Cooling Total	
30-31 Description 6. Electrical Installation 7. Sprinkler System Total 8. Standard Bldg. Access. 1975 Replacement Cost COST CONVERSION FACTOR Replacement Cost New Final Net Condition 9. Exterior Access. Total	560.	Industrial Unit Heaters Total	
7. Sprinkler System Total 7. Sprinkler System Total 8. Standard Bldg. Access. 1975 Replacement Cost COST CONVERSION FACTOR Replacement Cost New Final Net Condition 9. Exterior Access. Total	No. Description	Plumbing Fixtures Total Cost	
Standard Bldg. Access. 1975 Replacement Cost COST CONVERSION FACTOR Replacement Cost New Final Net Condition Depreciated Building Co	20.00	Electrical Installation Total	
1975 Replacement Cost COST CONVERSION FACTOR Replacement Cost New Final Net Condition Depreciated Building Co		Standard Bldg. Access.	
COST CONVERSION FACTOR Replacement Cost New Final Net Condition Depreciated Building Co Exterior Access, Total		Replacement Cost	
Replacement Cost New Final Net Condition Depreciated Building Co		COST CONVERSION FACTOR	
Depreciated Building Co		Replacement Cost Nev	
Exterior Access. Total		Depreciated Building Cost	
		Exterior Access. Total	

Building Value Amount SUMMARY Date Building No. Building 4 STORAGE UNITS (2NB FL) Total Land tand Value Description of Work Total NOTES ら のかよのたろ Appeal Decision Adjusted Unit Value 46 <u>Unit Codes</u> 1 = Front Feet 2 = Square Feet 3 = Acreage 4 = Site <u>Influence Factor Codes</u> 1 = Depth Factor 2 = Frontage Factor 3 = Backlot Factor 4 = Triangle Factor ,30 or ,60 5 = Corner Lot Factor Total Land Value 47 Building 42 Influence Factors Permit # 394 MAIL CERT. MAIL REG. NOT REQ. OWNER 3,47 LAND DATA Exempt SC/VET 45 7 5 7 7 7 7 浱 9.6 5.5 37 二子 28 30 57 51 77 40 Total Code Code Source of Information 1 = Owner 2 = Spouse 3 = Tenant 4 = Agent 5 = Other Unit Value 55 30 Land Assessment (decimal if 48 acres) SALES VERIFICATION DATA Type of Sale 1 = Land 2 = Building 3 = Land and Building Area IDENTIFICATION DATA STAFF CONTROL DATA 15-17 MAIDEN LANE Source 1 = Buyer 2 = Seller 3 = R.T. Fee 4 = Agent Building 6 = Estimate 7 = Refusal Backlot Standard Depth 6 = Topography Factor 10 4 BOUND BROOK Interior Inspection 0 = No 1 = Yes Setback Validity 0 = Not Valid 1 = Valid 9 Permanent Improvement Review Code Ratio Number of Principal Buildings Enumeration Date Month/Year Permanent Land Review Code Appraisal Date Month/Year Depth Review Date Month/Year Sales Date Month/Year Sales Ratio Sales Price frontage 32 Enumerated By Appraised By Reviewed By Salgs Price Card Code Card Code Zone 30

COMMERCIAL BUILDING DATA 28	[2] Card Code Exterior Wall Statsh Codes 1 = Grooved Plywood or Panix, 22 wood Stding	
Predominant Shell Type Predominant Use Type 1 = Apt. 2 John. 3 = Indus. 35 Overall Quality 1 = Low 2 - Below Avg. 35 Avg. 4 - Above Avg. 5 = H.gh 37 Year Built Condition 1 = Poor 2 = Fair (3)= Normal 4 = Good 5 = Excel.		Building Use Type Codes 1 = Apt. 2 = Corm. 3 = Indust. Healing/Cooling Unit Type Codes 1 = Not Water 2 = Forced Hot Air 3 = Unit Heaters 4 = Central Cooling 5 = Package Cooling 6 = Central Combined 7 = Package Combined Heating/Cooling Quality Codes 1 = Low 3 = Average 5 = High Boiler Present for Type 1 Unit 0 = No 1 = Yes
on OBSOLESCENCE (\$\frac{1}{2}\) (15 (15) (15) (15) (15) (15) (15) (15)	Quality Codes 1 = Low (3). Average 5 = High W/D Type Q1. Wall Area Rate Factor Cost	lding Unit Code Code Q1
Physical Net Condition * Final Net Condition The Condition Final Net Condition STRUCTURAL SHELL Structural Shell Type Codes 101 = Lt. Wood Frame 102 = Heavy Timber 103 = Masonry Load Bearing 104 = Reinf. Conc. 105 = Steel 106 = Fireproof Steel 107 = Lt. Steel with Galvanized Steel Exterior 108 = Fireproof Steel Exterior 108 = Fireproof Steel Fireproof	12 13 14 15 15 15 15 15 15 15	L2 L3 L4 L5 S6 L5 L5 L5 L5 L5 L5 L5 L
Insulated Sandwich Panel Exterior Incommentaries of the property of the Sant. with Wood Floor 112 = Dock High Foundation 123 = Low quality Service Station 124 = Below Average Quality Service Station 125 = Average quality Service Station 126 = Above Average quality Service Station 127 = Good quality Service Station 131 = Low quality Service Station 127 = Good quality Service Station 133 = Low quality Service Station 127 = Good quality Service Station 133 = Low quality Service Station 127 = Good quality Service Station 137 = Good quality Specialty Bidg. 136 = Above Average quality Specialty Bidg. 137 = Good quality Specialty Bidg. 145 = Garden Apartments Shell Segment Quality Godes 1 = Low Ash Average 5 = High	Card Code 30 32 33	Industrial Unit Heaters Small Ind. Ht. Med. Ind. Ht. Large Ind. Ht. Unit Heaters Total Cost Splumbing Fixture Quality Codes 1 = Low 3 = Average 5 = High
55y/let Ground Area Perimeter 25 6 2 6 28 26 78 88 26 82 28 88 29 88 84 29 88 29 88 20 88 20 88 20 88 20 88 20 88 20 88	ndsh 700 s	Number Q1. Rate Cout
155 38 44 14 15 15 15 15 15 15	Cost Start Code Cost Cost	Type

	15/51 (b) 34 (d)	320	Segment Width Length Height Ground Area Perimeter Building Description 25/AL 36x 24 (5 469) 15/52 9x x	1. Structural Shell Base Cost 2. Exterior Finish Total Cost 3. Interior Finish Total Cost 4. Heating/Cooling Total Cost Industrial Unit Heaters Total Cost	5. Plumbing Fi 6. Electrical 7. Sprinkler S 8. Standard Bl 1975 Repla COST CONVER Replacement Final Net C Depresiate G 9. Exterior A 10. TOTAL VALUE
Code No. Code Measure One Measure Two Q1. 28 30-31 32-35 8644 864 877 (4) 878 (1) 64		Standard Building Accessories Total Cost Card Seq. Acces. STANDARD EXTERIOR ACCESSORIES DATA Final Code No. Code Measure One Measure Two QL. 28 30-31 32-35 36-11 H42-17 48 Rate Factor Cond. Cond.			Code No. 28 30-31 92-56 92-57 Notice Mo.

	LA 2752 2452 HEATING/COOLING	Codes 1 = Apt. 2 - Comm. 3 = Indust. It Type Codes 1 = Hot Water 2 = Forced High Air 3 = Central Cooling 5 = Package Cooling 5 = Central Stage Combined Asiaty Codes 1 = Low 3 A Average 5 = High	O a No la Yes		ing/Cooling Adjusted Cost Indust Num I Ind. Ht. 64 Ind. Ht. 69 Le Ind. Ht. 74 Heaters Total Cost	PLUMBING FIXTURE Quality Codes 1 = Low 3 Average 5 = High Number Q1. Rate Cost Apt. Fix. 30 12 41 Ind. Fix. 42 47 Plumbing Total Cost	Electrical installation Light Intensity = Minimum 2	trical Installation Total Cost SPRINKLER Code 140 Sprinkler System Base Cost rkler System Total Cost
	Card Code , \$6 14 EXTERIOR WALL FINISH 28	1) Finish Codes 1/* Grooved Plymood or Equiv. 2 = Wood Siding 3 = Cement Block or Equiv. 4 = Tilt-up Concrete Panels or Common Brick/on Block or Equiv. 6 = Face Brick on Wood or Equiv. 7 Face Brick on Block or Equiv. 8 = Common Brick Conc. or Equiv. 9 = Face Brick on Reinf. Conc. or Equiv. 10 =	Precast Con. Panels with Expose Aggregate or Equiv. 11 - Metal and Glass Curtain Walls or Equiv. 12 - Stone or Equiv. 13 - Limestone or Equiv. 14 - Marble or Equiv. 15 - Polished Granite or Equiv. 16 - Store Front Quality Codes 1 - Low A Average 5 - Migh		72 72 32 32 42 42	Exterior Wall Total Cost Standard Exterior Wall Total Cost INTERIOR FINISH Card Code 2752 2452 Interior Finish Codes 1 = Mpt Avg. Size 300 s.f. 400 s.f. 500 s.f. 600 s.f. 700 s.f. 800 s.f. 900 s.f. 1000 s.f. and over 2 = Apt. Utility Area is Hotel or Equiv. (L) Small Off. or Equiv. 5 = Large Open Offices on Foniv	1 Stores or Equiv. 9 = Retail St. 11 - Marchouse (22 Light Mg. A. 11 - Low 2 = Below Average (3) 4 30 2 nt Floor Area + Number of Apartme 9. Feet per Apartment	34 36 37
Owner	Street Address COMMERCIAL BUILDING DATA 28	Building Number Predominant Shell Type Predominant Use Type 1 = Apt. (2) Comm. 3 = Indus. Solverall Quality 1 = Low 2 = Below Avg. (3) Avg. 4 = Above Avg. 5 = High Tear Built Preserved to the properties of	Condition 1 - Poor 2 - Fair 3 - Normal L - Good 5 - Excel. Effective Age in Years 100% - (Eff. Age Dep \$ Obser. Phys. Cond. \$) - Physical Net Condition 08501E50ENGE	100% - (Func. Obsol.	Fireproof Steel 107 = Lt. Steel with Galvanized Steel Exterior 108 = Lt. Steel with Enameled Steel or Aluminum Exterior 109 = Lt. Steel with Insulated Sandwich Panel Exterior 110 = Bsmt. with Conc. Floor 111 = Bsmt. with Wood Floor 112 = Dock High Foundation 123 = Low Quality Service Station 124 = Below Average Quality Service Station 125 = Average Quality Service Station 125 = Average Quality Service Station 127 = Good Quality Service Station 137 = Low Quality Specialty Bldg. 134 = Below Average Quality Specialty Bldg. 137 = Average Quality	Specialty Bidg. 145 - Above Average quality Specialty Bidg. 145 - Garden Apartments ment Quality Codes 1 - Low 3. Average 5 - High mt. Q1	55 53 38 56 53 38 56 53 38 56 53 38 56 53 56 55 56 56 56 56 56 56 56 56 56 56 56	Scruttural Shell Base Cost Roof Z-Heavy Times 6-Enam Steel 3-Sti. Deck 4-Concrete 8-Precast Conc.

Building Description Rents Scale 1 13 = 20 25kr Perimeter (3) 15/51 <u>(a)</u> Ground Area 4750 BUILDING SKETCH 2067 0-1 BUILDING VALUATION SUMMARY Standard Bldg. Access. Total Cost (+) Industrial Unit Heaters Total Cost Electrical Installation Total Cost Height 00 Plumbing Fixtures Total Cost Sprinkler System Total Cost 9. Exterior Access. Total Cost Interior Finish Total Cost Heating/Cooling Total Cost Structural Shell Base Cost Exterior Finish Total Cost Depreciated Building Cost Length COST CONVERSION FACTOR 1975 Replacement Cost Replacement Cost New Final Net Condition Width % m 4 ٥. ۶ 7. Depr. Full Value 59-67 COSt Final Quality Net Factor Cond. Quality + Factor -STANDARD BUILDING ACCESSORIES DATA SPECIAL EXTERIOR ACCESSORIES DATA STANDARD EXTERIOR ACCESSORIES DATA Rate Standard Exterior Accessories Total Depreciated Cost 48 1380 Description 32-58 Measure Two 42-47 7 Reasure One Heasure Two Standard Exterior Accessories Total Cost Standard Building Accessories Total Cost of 4 x 36 2752 8×6 480 2300 76 Measure One 36-41 S DG-FAM Cost Conversion factor Seq. Acces.
No. Code
30-31 32-35 5705 PA09 BVOI BVOS 4803 12 BO4 1003 PVBS Seq. No. 30-31 Code Code Card

	HEATING/COOLING	ding C.	Unit Heaters 4 = Central Cooling 5 = Package Combined 7 = Package Combined Heating/Cooling Quality Codes 1 = Low 3 Aver Boller Present for Type 1 Unit 0 = No 1 = Yes		Heating/Cooling Base Cost Type 1 Boiler Adjustment Factor Heating/Cooling Adjustment Class Quality Factor Heating/Cooling Adjusted Cost	Small Ind. Ht. 64 Number Rate Cost Large Ind. Ht. 69 Unit Heaters Total Cost Unit Heaters Total Cost	11ty 1 1 1 1 1 1 1 1 1	Ind.
	Card Code EXTENIOR WALL FINISH 5348	Exterior Wall Finish Godes 1 = Grooved Plymood or Equiv. 2 = Wood Siding or Equiv. 3 = Cement Block or Equiv. T Tiltup Concrete Panels or	Ext.	3 = Limeston Equiv. (A6) W/D e Factor	50 52 53 69	7.0 7.2 7.3	f. 400 d over div. 5 clinic or Equ. 13 = H rage 4 rage 4 rits	Type Q1, Floor Area Rate Cost 24
Owner	COMPERCIAL BUILDING DATA Card Code 28	Number nt Shell Type	1 = Apt.	. cond.	Physical Net Cond.	It. Steel with Enameled Steel or Aluminum Exterior 109 = Lt. Steel with Insulated Sandwich Panel Exterior 110 = Bsmt. with Gonc. Floor 111 = Bsmt. with Mood Floor 112 = Dock High Foundation 123 = Low Quality Service Station 124 = Below Average Quality Service Station 125 = Average Quality Service Station 125 = Average Quality Service Station 137 = Good Quality Service Station 137 = Good Quality Service Station 133 = Low Quality Service Station 137 = Good Quality Service Station 133 = Low Quality Specialty Bldg. 134 = Below Average Quality Specialty Bldg. 137 = Average Quality Specialty Bldg. 137 = Good Onlity Shorialty Bldg. 137 = Good Onlity Shorialty Bldg. 137 = Good Onlity Shorialty Bldg. 137 = Good	Shell Segment Quality Codes 1 - Low 3. Average 5 - High Segment Quality Codes 1 - Low 3. Average 5 - High Segment Quality Codes 1 - Low 3. Average 5 - High Segment Quality Codes 1 - Low 3. Average 5 - High Code Code Code Code Code Code Code Code	Segmt. WR Factor Rate Factor Cost O

TANDARD BUILDING ACCESSORIES DATA	BUILDING SKETCH Scale 1 Cl =
t	
	•
	82 (8)
	• • • • • • • • • • • • • • • • • • • •
and Building Accessories Total Cost	
30-31 30-35 30-41 42-47 48 Rate Factor	S2
	Segment Width Length Height Ground Area Perimeter Building Description
	×××
	X
	X
	, , , , , , , , , , , , , , , , , , ,
	X
	, , , , , , , , , , , , , , , , , , ,
	1 1
Standard Exterior Accessories Total Depreciated Cost	1. Structural Shell Base Cost 2. Exterior Floich Total Fore
Standard Etterior Brosconies Total Cost	Interior Finish Total Cost
SPECIAL EXTERIOR ACCESSORIES NAVA	
Card Seq. Code No. Description 0epr. Full Value 28 30-31	industrial Unit Heerers Total Cost S. Plumbing Fixtures Total Cost
	o. Electrical Installation Total Cost 7. Sprinkler System Total Cost
	Standard B
	1975 Replacement Cost COST CONVERSION FACTOR
	Replacement Cost New
	Final Net Condition Depreciated Building Cost
	9. Exterior Access, Total Cost

Omer		
Street Address		
		Card Code 4 ALTINO/COLLING 28
Building Number 30	Exterior Wall Finish Codes 1 = Grooved Plymood or Equiv. (2.4 Wood Siding or Fourity 3 = Communt Block or Fourity 7 Till un Communts Brands or	Building Use Type Codes 1 = Apt. (2) Comm. 3 = Indust.
Predominant Use Type 1 " Apt. 2 "Comm. 3 " Indus.	Common Brick on Block or Equiv.	Heating/Cooling Unit Type Codes/ The Hot Mater 2 = Forced Hot Air 3 =
Overall Quality 1-low 2-Below Avg 3Avg. 4- Above Avg 5. High	ace Brick on Block or Equiv. θ = Common B	4 = central coulding 7 = rackage coulding Package Combined
Condition Door 2 Frie 2 Normal Condition	on Reinf. Conc. or Equiv. 9 " Face Brick on Reinf. Conc. or Equiv. 10 = Precast Con. Panels with Expose Aggregate or Equiv. 11 " Metal and Class	1 = Low 3 Average 5 = High
Effective Age in Years	Curtain Walls or Equiv. 12 - Stone or Equiv. 13 - Limestone or Equiv.	Boller Present for Type 1 Unit U = No 1 = les
% Obser. Phys. Cond %)	14 - Marble or Equiv. 15 - Polished Granite or Equiv. 26 Store Front	Building Unit Use Code Code 01. Floor Area Rate Cont
- Physical Net Condition OBSOLESCENCE	T = TON O WEI #86	34
100% - (Func. Obsol. % + Econ. Obsol. %)	Type Q1. Wall Area Rate F	
= Obsol. Net Condition Physical Net Cond. % x Obsol. Net Cond. %	132 1331	
Net Condition	[27] [27] [07]	53 54 55 56
Card Code STRUCTURAL SHELL	50 52 53	Heating/Cooling Base Cost
Shell Type Codes 101 = Lt. Wood Frame 102 = Heavy Timber		Type 1 Boiler Adjustment Factor
10; = Masonry Load Bearing 104 = Meini. Conc. 10; = Steel 100 = Fireproof Steel 107 = Lt. Steel with Galvanized Steel Exterior 108 =		Heating/Cooling Predominant Class Quality Factor
Lt. Steel with Enameled Steel or Aluminum Exterior 109 . Lt. Steel with	70 72 73	meaving/couling Augusted Cost Industrial Unit Heaters
Insulated Sandwich Panel Exterior 110 = Bsmt. with Conc. Floor 111 =	+1	Number Rate Cost
Bant: With Mood Floor LLZ = Lock figh Foundation LZ = LOW Quality Samples Station 12, = Relow Average Obality Service Station 125 =	rd Code	
Average Quality Service Station 126 * Above Average Quality Service	 	Med. Ind. Ht. 69
Station 127 = Good Quality Service Station 133 = Low Quality Specialty	[77]	otal C
Bldg. 134 = Below Average Quality Specialty Bldg. 135 = Average Quality Specialty Bldg. 136 - Above Average Quality Specialty Bldg. 137 = Good	50 52 53	5 PLUMBING FIXTURES
Quality Specialty Bldg. 145 = Garden Apartments		
Shell Segment Quality Codes 1 = Low 3 Average 5 = High	rior Wall Total Cost	Plumbing Fixture Quality Codes 1 = Low 3 Average 5 = High
Segmt. Q1 Type Sty/Hgt Ground Area	Card Code	Number
2 30 31 32 (01) 35 726 38 7.0 76 44 7.0 50 11 11 11 12 12 12 12 12 12 12 12 12 12	Finish Codes 1 - Apt Avg. Size 300 s.f. 400 s.f. 500 s.	30
d Code	600 s.f. 700 s.f. 800 s.f. 900 s.f. 1000 s.f. and over 2 = Apt. Utility	Tud. Fix. 42
31 32 1 (1 35 7 38 20 92	Area 3 * Motel or Equiv. 4 * Small Off. or Equiv. 5 * Large Open Offices or Equiv. 6 * Prof. Off. for Equiv. 7 * Clinics of Equiv. 8 *	Total Cost
[48] [49] [50] . [53] . [56] . [62]	Large Retail Stores or Equiv. 19 Retail Stores or Equiv. 10 - Banks	ET ECTRICAL TACEALI ANTON
32 35 38 444	Warehouse 12 = Light Mfg. Area 13 =	t Intensity 1 = Mini
49 50 53 56 62	Quality Codes 1 = Low 2 = Below Average (3 p Average 4 = Above Average	Quality codes 1 = low 3/ Average 5 = High
d Code	Gross Apartment Floor Area + Number of Apartment Units	Type Floor Area Ql. Rate Cost
30 31 34 50 50 50 50 444 62 62 62 62 62 62 62 62 62 62 62 62 62	* Average Sq. Feet per Apartment	Apt. 4.9 56 56
	Type Q1. Floor Area Rate Cost	65
Segmit, WR Factor Rate Factor Cost	36 37	trical Installation Total Cost
	11 17 171	SPRINKLAR SKSTEN
	156 157 158	ity Codes 1 = Low 3 = Average 5 = High
	[29] [99] [79]	Type Floor Area QL Hate Cost Apt. [30]
	Card Code	38
Structural Shell Base Cost	33	Ind. 40
Roof (July Mood 5-Galv. Steel	Interior Finish Total Cost	Sprinkler System Quality Factor
		Upit NIVACE IN SUCCES COOK
A STATE OF THE PROPERTY OF THE	The state of the s	

Building Description Scale 1 [] = Perimeter BUILDING SKETCH 7 BUILDING VALUATION SUMMARY Ground Standard Bldg. Access. Total Cost (±) Industrial Unit Heaters Total Cost Electrical Installation Total Cost Plumbing Fixtures Total Cost Sprinkler System Total Cost Exterior Access. Total Cost Structural Shell Base Cost Exterior Finish Total Cost Interior Finish Total Cost Heating/Cooling Total Cost Depreciated Building Cost Length COST CONVERSION FACTOR 1975 Replacement Cost Replacement Cost New Final Net Condition Width - 2 K 4 š . Depr. Full Value 59-67 COST Cost Final Quality Net Factor Cond. Quality + Factor -STANDARD BUILDING ACCESSORIES DATA SPECIAL EXTERIOR ACCESSORIES DATA STANDARD EXTERIOR ACCESSORIES DATA Rate Standard Exterior Accessories Total Depreciated Cost Description 32-58 Heasure Two 42-47 Measure THO Standard Exterior Accessories Total Cost Standard Building Accessories Total Cost 2002 Measure One 36-41 Heasure One Cost Conversion Factor Seq. Acces.
No. Code
30-31 32-35 FA02 Acces. Code Seq. 30-31 86.4 20.4 Code 28 Card

HEATING/COOLING heating/cooling	12 12 13 14 14 15 15 15 15 15 15	170e Floor Area Q1 Rate Cost
Finish Codes 1 = Grooved Plywood of Equiv. (5) = Cement Block or Equiv. (4 = Till-up Concrete Common Brick on Block or Equiv. (5) Face Brick : Equiv. 7 = Face Brick on Block or Equiv. 8 = nnc. or Equiv. 9 = Face Brick on Reinf. Conc. on Panels with Expose Aggregate or Equiv. 11 = HM is or Equiv. 12 = Stone or Equiv. 13 = Limeston or Equiv. 13 = Polished Granite or Equiv. (7)	Type Q1 Mall Area Rate Factor Cost 20 12 13 Mall Area Rate Rat	64 66 67
Street Address Card Code Building Number Predominant Shell Type Predominant Use Type 1 = Apt. 2 Comm. 3 = Indus. Overall Quality 1 = Low 2 = Below Avg(5.Avg. u = Above Avg. 5 = High Year Built Condition 1 = Poor 2 = Fair 3 Normal u = Cood 5 = Excel. Effective Age in Years 100% - (Eff. Age Dep	n obsoltscence \$\frac{\pi}{\pi} + \text{Econ. Obsolt.} \$\frac{\pi}{\pi}\$\) \[\frac{\pi}{\pi} + \text{Econ. Obsolt.} \frac{\pi}{\pi}\) \[\frac{\pi}{\pi} + \text{Econ. Obsolt.} \text{Neil.} \$\frac{\pi}{\pi}\) \[\frac{\pi}{\pi} + \text{Econ. Obsolt.} \text{Neil.} \text{Cond.} \text{100} \] \[\frac{\pi}{\pi} + \text{Steel with Calvanized Steel of Steel or Aluminum Exterior not Exterior 100 = Bsmt. with 112 = Dock High Foundation 12 = Below Average Quality Specialty Blds. \text{Lock High Foundation 12} = \text{Lock High Foundation 13} = \text{Lock High High Foundation 13} = Lock	Structural Shell Base Cost Roof (Art. Wood 5-Galv. Steel 2-Heavy Timber 6-Enam. Steel 3-Stl. Deck 4-Concrete 8-Precast Conc.

BUILDING SKETCH Scale 10 =	200 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		· · · · · · · · · · · · · · · · · · ·		50	Segment Width Length Height Ground Area. Perimeter Building Description $25/8$ x $+700$	×××		X	1. Structural Shell Base Cost			5. Plumbing F 6. Electrical	COST CONCESSION FACTOR	Final Net Condition Depreciated Building Co	9. Exterior Access. Total Cost
Card Seq. Acces. STANDARD BUILDING ACCESSORIES DATA Code Neasure One Neasure Two Q1. 28 30-31 32-35 36-41 42-47 48 Rate Factor - Cost CARON. 28 30-31 22-35 36-41 40-47 48 Rate Factor - Cost				Stendard Building Accessories Total Cost Gard Seq. Acces. Code No. Code Resure One Measure Two ed. 20 50-31 32-35 30-41 4-47 46 Rate Factor Cond.						Standard Exterior Accessories Total Depreciated Cost	Cost Conversion Factor	Seq.	Code No. 28 30-31 Depr. Full Value 32-58			


Owner		
. Address		
CONPERCIAL BUILDING DATA	Card Code	HEATING/COOLING
: PL	Mall Finish Codes 1 = Grooved Plywood of Equiv. 2 = Wood	Card Code (Cook State Codes 1 Act Com 2 1 Tedans
32	or Equiv. 3 = Cement Block or Equiv. 4 = Tilty Concrete Panels or	Heating/Cooling Unit Type Codes 1 = Not Water 2 = Forced Not Air
Predominant Use Type 1 * Apt. (2 x Comn. 3 = Indus.)5	Equiv. 5 = Common Brick on Block or Equiv. (6 y Face Brick on Wood	e Cooling
7. TE	on Reinf. Conc. or Equiv. 9 = Face Brick on Reinf. Conc. or Equiv. 10 =	Combined 7 - Package Combined
Condition 1 * Poor 2 * Fair 3 Normal 4 * Good 5 * Excel.	Precast Con. Panels with Expose Aggregate or Equiv. 11 = Metal and Glass	Boiler Present for Type 1 Unit 0 = No 1 = Yes
	Curtain Walls or Equiv. 12 = Stone or Equiv. 13 = Limestone or Equiv.	
100% - (Eff. Age Dep	Quality Codes 1 = Low / Average 5 = High	Unit Code Qi
OBSOLESCENCE	M/D	31 32 33 34
A + Econ. Upsol.	170 132 13 Mall Affea Rate Factor Cost	12 13 14 15
Physical Net Cond. % x Obsol. Net Cond. %		
Met Condition	40 42 43	53 54 55 56
Card Code Sinucional Shall	50 52 53	Heating/Cooling Base Cost
102 * Heavy Timber	-	Type 1 Boiler Adjustment Factor
103 = Masonry Load Bearing 104 = Reinf. Conc. 105 = Steel 106 = Figurance Cteel 107 = 11 - Cteel with Galuminad Steel Extension 108 =	60 62 63	Heating/Cooling Predominant Class Quality Factor
Lt. Steel with Enameled Steel or Aluminum Exterior 109 = Lt. Steel with	70 72 73	Heating/Gooling Adjusted Cost
Insulated Sandwich Panel Exterior 110 * Bsmt. with Conc. Floor '111 =		Number Rate Coet
Bsmt. with Wood Floor 112 . Dock High Foundation 123 . Low Quality	rd Code	2004
Service Station 124 = Below Average Quality Service Station 125 = Average Outlier Sandon 125 =	30 32 33	
Station 127 = Good Quality Service Station 133 = Low Quality Specialty	07 173 173	Large Ind. Ht. 74
Bldg. 134 = Below Average Quality Specialty Bldg. 135 = Average Quality		Unit Heaters Total Cost
Specialty Bldg. 136 - Above Average Quality Specialty Bldg. 137 a Good	20, 52 53	PLUMBING FIXTURES
Quality Specialty bidg. 145 = vargen Apartments Shell Segment Quality Codes 1 = Low (3) = Average 5 = High \(\circ\) (7)	Exterior Wall Total Cost	Card Code 28 Dlumbing Fixture Chality Codes = Iow (3 Average 5 = High
	INTERIOR FINISH	10
31 32 (6) 35 24	Interior Firsts Codes 1 - And 400 the Code of con c con c	Apt. Fix. 30 30 35
150 (0.1 531 . 20 156 2,04 621	600 5.6. 700 5.6. 800 5.6. 900 5.6. 1000 5.6. and over 2 = Apt. Utility	36
30 31 32 0 135 (238 524 44	Area 3 = Motel or Equiv. A. Small Off. or Equiv. 5 = Large Open	Ind. Fix. 42
69 50 53 53	quiv. 6 * Prof. Off. or Equiv. 7 * Clinics o.	Flumbing Total Cost
d Code	or Fourty. (17) Warehouse 12 - Light MC Area 13 - Means Mc Area	ELECTRICAL INSTALLATION
1 30 31 32 (1 35 & 38 6 60 60 60 60	Quality Codes 1 * Low 2 * Below Average 3 * Average 4 * Above Average	LABIT INTERBILLY I = Manaman
Gode	* INCL FIN BSMT	
32 35 38 44	Gross Apartment Floor Area + Number of Apartment Units	Floor Area
48 49 50 , 53 , 56 , 62	weekage off teet per phasement and teet age of the same and the same a	57 6734
Quality Apt. Sormt WR Earton Cost.	Type q1	Ind. 65 72
(A)	34 36 37	Electrical Installation Total Cost
	47 97 77	7 SPRINKLER SYSTEM
	54 56 57	ty Codes 1 = Lou 3 = Average 5 = High
	29 99 179	Type Floor Area Ol Rate Cost
	+	38
Structural Shell Base Cost	[30] [32] [33] ZB	Ind. [46]
		Sprinkler System Quality Factor
7-Heavy Timber 0-Enam, Steel 3-Stl. Oeck 7-Insul, Panels 4-Contrate Rapecast Cont.	Interior Finish Total Cost	Sprinkler System Total Cost.
- 1		

BUILDING SKETCH Scale 1 Cl =		9/5/87	9 9 52	5/8		ent width Length Height Ground A	15/8 × × 604 / 524	28.22	 XX		8011	al Shell Base Finish Total	5. Interior Finish Total Cost 4. Heating/Cooling Total Cost	, v, v,	7. Sprinkler System Total Cost 8. Standard Bldg. Access. Total	1975 Replacement Cost COST CONVERSION FACTOR	Replacement Cost New	Depreciated Building Cost
Card Seq. Acces. Code No. Code Measure One Measure Two Qi. 28 30-31 32-35 36-41 42-47 48 Rate Factor -	1970 1970 1970 1970 1970 1970 1970 1970			Standard Building Accessories Total Cost	Card Seq. Acces. STANDARD EXTERIOR ACCESSORIES DATA Final Code No. Code Measure Two Ql. Quality Net 28 30-31 32-35 36-41 A.A.7 48 Rate Factor Cond. Cost							Standard Exterior Accessories lotal Depreciated Cost Cost Conversion Factor	Standard Exterior Accessories Total Cost	Card Seq. Code No. 28 30-31 32-58 SPECIAL EXTENIOR ACCESSORIES DATA Description 32-58 Sp. 67				

COMMERCIAL-INDUSTRIAL PROPERTY RECORD CARD

Bound Brook Revitalization Partnership Ray Mikell Bound Brook Revitalization Partnership Ray Mikell Downtown Manager Bound Brook, NJ 08805 T32-667-3939 Manager Manage	COMMERCIAL-INDUSTRIAL PROPERTY RECORD CAPD IDENTIFICATION DATA Permit #
Ray Mikell Sauditing Bound Boundain Avenue	323
SEBOUND SEBILICING SEBOUND SEBOUND SOUND T32-667-3939 T32-667-3939 T32-667-3939 T32-667-3939 MOTES NOTES SUMMAY TOTAL LEAD TOTAL	90000
Manager@downtownboundbrook.com — 1 APT — 1 APT	
All CERT. APPT All CERT. APPT Building No. Building Adjusted	
NOTES - DOWNTOWN BOUND BROOK REVITALIZATION PARTNERS - I APPT ALLCERT ALCERT ALCERT NOTEO OTHEO. 3	32
ALCERT. ALLEGT. ALL REG. WHER OTREG. 30 or .60 S = corner Lat Factor Adjusted 34 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	
ALLCERT. Adjusted 34 45 44 44 Unit value Land value Total Land value Designa Building Land Building	8
ALL CERT. ALL REG. ANN FAR. AND TREG. Building No. Building And Unit Value Land Land] L
ALL CERT. ALL REG. WMER OTREO. 10 or .60 5 = corner Lot Factor Suhhary Suhhary Adjusted Adjusted Adjusted Adjusted Adjusted Total Land Value Total Land Value Total Land Value Total Land Value Building Land Building Land Building]
AIL REG. OT REC. AVNER OT REC. A) SUMMARY Building No. Building Land Land Building No. Building Building No. Building Building No. Building Building No. Building	8
OT REO. 1.30 or .60 5 = Carner Lot Factor Lence Factors Adjusted Adjusted Land Land Land Land Land Building SUHMARY Building Land Land Land Building Land Building Building Building	445
Building No. Building 36 41 44 Adjusted 36 41 44 Adjusted 19 1 Appeal Decision Total Land Value Total Land Value Total Land Value Land L	46 LAND
Influence Factors	iangle Fac
23 36 41 44 Unit Value Land Value Exempt	
Total Land Value S Building Land Total	-
Total Land Value Total Land Value Appeal Decision S Building Land Total	-
Total Land Value or Appeal Decision S Building Land Total	
S Building Land Total	-
Land	S E
Pand	
Building	

Омпет		
Street Address COMMERCIAL BUILDING DATA	HATTER MAIN STATES	
	Card Code	Card Code 380 HEATING/COLLING
Building Number 30 Predominant Shell Tone	Exterior Wall Finish Codes 1 " Grooved Plywood or Equiv. 2 " Wood Siding	Use Type Codes 1 = Apt (2) Comm. 3 = Indust.
1 * Apt. 22 Comm. 3 = Indus.	Equiv. 5 = Common Brick on Block or Equiv. 6 9 Face Brick on Wood	Heating/Cooling Unit Type Codes (1) Hot Water 2 = Forced Hot Air 3 =
Overall quality 1-low 2-Below Ave 77 Nvg. 4-Above Ave 5-High	Sheathing or Equiv. 7 = Face Brick on Block or Equiv. 8 = Common Brick	Combined 7 - Package Combined
Condition 1 - Poor 2 - Fair 3 - Normal 1 - Cood 6 - Even	on Reinf. Conc. or Equiv. 9 * Face Brick on Reinf. Conc. or Equiv. 10 * Precast Con. Panels with Expose Aggregate or Equiv. 11 * Metal and Class	ling Quality Codes 1 = Low 3 Average 5 = High
	Curtain Walls or Equiv. 12 = Stone or Equiv. 13 = Limestone or Equiv.	
% Obser. Phys. Cond%)	14 " Marble or Equiv. 15 " Polished Granite or Equiv. 16 " Store Front Onality Codes 1 " Low 3 h Average 5 " High	Building Unit Use Code Code Q1. Floor Area Rate Cost
DESCENCE OBSOLESCENCE	Q/N	100
100% - (Func. Obsol. % + Econ. Obsol. %)	41. Wall Area Rate	2
Physical Net Cond. % x Obsol. Net Cond. %		
Final Net Condition STRUCTURAL SHELL	3	120 121 120 120 121 121 122 1
Card Code Structural Shell Type Codes 101 = Lt. Wood Frame 102 = Heavy Timber	[50] [52] [53]	Heating/Cooling Base Cost Twoe 1 Boller Adjustment. Factor
103 = Masonry Load Bearing 104 = Reinf. Conc. 105 = Steel 106 =	(60 62 63	Heating/Cooling Predominant Class Quality Factor
Fireproof Steel 107 = Lt. Steel with Galvanized Steel Exterior 108 =	70 72 73	Heating/Cooling Adjusted Cost
Insulated Sandwich Panel Exterior 110 = Bsmt. with Conc. Floor 111 =		Industrial Unit Heaters Number Rate Cost
Bsmt. with Wood Floor 112 = Dock High Foundation 123 = Low Quality	rd Code	
Service Station 124 = Below Average Quality Service Station 125 = Average Quality Service	290 132 333 (1)	
Station 127 = Good Quality Service Station 133 = Low Quality Specialty	70 73 73	Large Ind. nc. (4)
Bldg. 134 * Below Average Quality Specialty Bldg. 135 * Average Quality Specialty Bldg. 136 * Above Average Quality Specialty Bldg. 137 * Good	T	F. PLIMRING FIXMINES
Quality Specialty Bldg. 145 = Garden Apartments		Card Code
Shell Segment Quality Codes 1 " Low 3 " Average 5 " High	Exterior Wall Total Cost	Plumbing Fixture Quality Codes 1 " Low 3 Average 5 " High
Segmt. Q1. Type Sty/ligt Ground Area Perimeter	Card Code 1880 28	Number Q1. Rate Cost
49 50 53 56 56	Interior Finish Codes (1 A Apt Avg. Size 300 s.f. 400 s.f. 500 s.f.	36
Card Code 28 28 2 20 11 12 20 11 15 20	Area 3 * Notel or Equiv. (4) Small Off. or Equiv. 5 * Large Open	Ind. Fix. 42
4.9 50 53 56 62	Off. or Equiv. 7 = Clinics o.	Plumbing Total Cost
d Code	Large Metail Stores or Equiv. 9 = Metail Stores or Equiv. 10 = Banks or Equiv. 11 = Marehouse 12 = Light NTe. Area 13 = Heavy Mfg. Area	6 ELECTRICAL INSTALLATION
30 31 32 35 38 144 48 49 50 53 56 62	es 1 * LON 2 4	
d Code	S = High 380	Type Floor Area Ol Rate Cost
30 31 32 35 38 44 48 49 50 53 56 62		149 380 56
Ouality Apt.	Tyne 01, Floor Area Bate Cost	Ind. (65)
Segmit, MR Factor Rate Factor Cost	36 37	trical Installation Total Cost
	-	7 SPRINGER SYSTEM
		2
	24 56 57	Quality Codes 1 = Lon 3 = Average 5 = High Tyre Floor Area Ol. Bate Code
	[7]	30 37 4000
	Card Code	Comm. 38 45 15
tural Shell Base Cos	30 32 33 4	nkler System Base Cost
Roof (1-At. Wood 5-Galv. Steel Z-Heavy Timber 6-Enam. Steel 3-St. Dock 7-Inbul. Panels	Interior Finish Total Cost	Sprinkler System Quality Factor Sprinkler System Total Cost
- 1		



Owner Street Address COMMERCIAL BUILDING DATA Card Code 28	Card Code 3051 EXTENIOR WILL FINISH 2036 2E	HEATING (COOLUNG
	all Finish Codes 1 . Grooved Plywood or Equiv. (2) Wood . 3 . Cement Block or Equiv. 4 . Tilt-up Concrete Panel	Card Code Card Code Building Use Type Codes 1 = Apt. 2 = Comm. 3 = Indust. Heating/Cooling Unit Type Codes 1 = Hot Water 2 = Forced Hot Air 3 =
fredominant Use 1ype 1 - Apt. (F J Comn. 3 - Indus. 3) Overall Quality 1-Low 2-Below Avg 3/Avg. 4-Above Avg 5-High Year Built Opposertiation	Equiv. 5 = Common Brick on Block or Equiv. 6 = Face Brick on Wood Sheathing or Equiv. 7 = Face Brick on Slock or Equiv. 8 = Common Brick on Reinf. Conc. or Equiv. 9 = Face Brick on Reinf. Conc. or Equiv. 10 =	e Cooling 6 = Central rage 5 = High
Fair 3 Normal 4 = Good 5	Precast Con. Panels with Expose Aggregate or Equiv. 11 - Metal and Glass Curtain Walls or Equiv. 12 - Stone or Equiv.	l = Yes
8. Cond	14 - Narbie or equiv. 15 = Folished Grante or Equiv. 16 = Store Front Quality Codes 1 = Low 37 Average 5 = High	Building Unit Use Code Code Code Q1. Floor Area Rate Cost
	Type Q1. Wall Area Rate Factor Cost	77
Final Net Condition STRUCTURAL SHELL	[7]	[53] [54] [55]
Structural Shell Type Codes 101 × Lt. Wood Frame 102 = Heavy Timber	52	Heating/Cooling Base Cost Type 1 Boiler Adjustment Factor
loy = masonry Load Dealing Liu = menni conc. Loy = Sceel 100 = Fireproof Steel 107 = Lt. Steel with Galvanized Steel Exterior 108 = Lt. Steel with Enameled Steel or Aluminum Exterior 109 = Lt. Steel with	12 13 14 15 15 15 15 15 15 15	Heating/Cooling Fredominant Class Quality Factor Heating/Cooling Adjusted Cost
Insulated Sandwich Panel Exterior 110 = Bsmt. with Conc. Floor 111 = Bsmt. with Wood Floor 112 = Dock High Foundation 123 = Low Quality	and Code	
Service Station 124 = Below Average quality Service Station 125 = Average Quality Service Station 126 = Above Average Quality Service	32 33 1	
Station 127 = Good Quality Service Station 133 = Low Quality Specially Bldg. 134 = Below Average Quality Specialty Bldg. 135 = Average Quality	12 13 14 15 15 17 17 17 17 17 17	barga ind. Nr. (74)
Specialty Bldg. 136 = Above Average Quality Specialty Bldg. 137 = Good Quality Specialty Bldg. 145 = Garden Apartments	52 53	5 PLIMBING FIXTURES Card Code DON £ 28
1 = LOW 3 A Aver	Exterior Wall Total Cost Interior Finish	γ
22 22 10 3 25 1 28 38 14 10 10 10 10 10 10 10 10 10 10 10 10 10	Card Code Interior Finish Codes 1 - Apt Avg. Size 300 s.f. 400 s.f. 500 s.f.	35
Card Code 28 30 31 32 35 38 44	BOX s.f. 900 s.f. 1000 s.f. and over 2 * Apt. Utili Equiv. 4 * Small Off. or Equiv. 5 * Large Open	175 To 1
	Offices or Equiv. 6 - Prof. Off. or Equiv. 7 - Clinics o. Equiv. 8 - Large Retail Stores or Equiv. 9 - Retail Stores or Equiv. 10 - Banks	ELECTRICAL INSTALLATION
32 35 38 44 50 53 56 62	or Equiv. (1) - Warehouse 12 = Light Mfg. Area 13 = Heavy Mfg. Area Quality Codes 1 - Low 2 = Below Average	Light Intensity (12 Minimum 2 = Adequate 3 = Bright 48 Quality Codes, 1 = Iow (3) Average 5 = High
'u' Code	r of Apartment Units	Floor Area
95 [25] 96 [67]	q. Feet per Apartment	57 4773
Segmt. WR Quality Rate Factor Cost	Type Q1. Floor Area Rate Cost	Ind. 95 172 Electrical Installation Total Cost
	27 97	SPRING
	1	tty Codes 1 = Low 3 = Average 5 Floor Area
	Card Code	Apt. 20 37 45 45 45 11nd. 46 53
Ö	20 32 33	nkler System Base Cost nkler System Quality Factor
7-fleavy Timber 6-Enam. Steel 1-fle. Deck 7-Insul. Panels 4-Concrete 8-Precast Conc.	Interior Finish Total Cost	Sprinkler System Total Cost

Coat See, Acces. Coat No. Coat Measure one Measure to 01. Many Dead of the Coat Seed of t	15/51 15/5	let ton
Cand Seq. Code No. Description 32-56 Depr. Full Value	4. Heating/Cooling Total Industrial Unit Heater S. Plumbing Fixtures Total 6. Electrical Installation 7. Sprinkler System Total 8. Standard Bldg. Access. 1975 Replacement Cost COST CONVERSION FACTOR Replacement Cost New Final Net Condition Depreciated Building (9. Exterior Access. Total	

Somerset Bound Brook	Property Record C	Card 10/12/21	L 06:54 PM
Block: 10 Lot: 4 Qualifier: Card: 1		Last Sale:	12/30/20 for \$575,000
JAX MAIDEN LN, LLC	Units: 1 Nbhd:	Model:	VCS: BR
15-17 MAIDEN LANE	SFLA: 0 Floor:	Bldg Name:	Map Page:
BOUND BROOK, NJ 08805	Prop Class: 4A Occupancy:	Zoning:	Year Built: 1915/1915
	Bldg Class: 10	Addtl Lot:	NC Interior GOOD
	Bldg Desc: 2SB	Land Dim: 50X135	NC Exterior GOOD
15-17 MAIDEN LANE	Info By: AT DOOR	Style:	NC Layout GOOD
Main Building 0	(no sketch thumbnail)		(no house picture)
Attached Items Value 0			
Add/Deduct Value 0			
Base Replacement Cost 0			
Cost Conversion Factor 1.80			
Replacement Cost New 0			
Net Condition 0.70			
Market Adjustment 1.00			
Appraised Value 0			
Detached Items Value 21,407			
Total Land Value 288,500			Room Count
Total Improvement Value 21,407			B 1 2 3 4 T
Total Value 309,907			iving 0 0 0 0 0 0
Valuation Summary			ining 0 0 0 0 0 0
Computed Override Summary	1		itchen0 0 0 0 0 0
Land 288,500 288,500 288,500			ath 0 0 0 0 0 0
Improv 21,400 179,400 179,400			ed 0 0 0 0 0 0
Total 467,900 467,900	1		ec 0 0 0 0 0 0
Floor Area (footprint)			en 0 0 0 0 0 0
First Uppr Half		ĮT	otal 0 0 0 0 0 0
Item Bsmnt Floor Floor Story Attic	-		
Totals 0 0 0 0 0			
SqFt Living Area Sketch Areas			
Item Area Description Sq Ft	-		
First Floor 0 Upper Floor 0	Dwelling Detail	Sales History	
Upper Floor 0 Half Story 0	Element Description	•	ok-Page Price NU
Fin Attic 0	Bldg Class 10	JAX MAIDEN LN, LLC 12/30/20 073	
Living Bsmnt 0	Type	SCHWALL, CHARLIE & PANNI 06/04/14 067	′
Unfin Area (-) 0	Yr Built 1915/1915	MAIDEN HOLDING LLC, 06/04/13 066	· ·
Total Area 0	Height	GOMERO, RODOLFO & SOLED 08/10/07 060	,
Attached Items	Style	00,10,07 000	200,000
Seg Item Area	Roof Type		
Total Area 0	Roof Mat.		
Detached Items	Bsmnt/Fin		
Desc Area Rate Const QF Cond Value	Fireplace NONE		
DET. GAR. 1,540 16 3,069 1.00 0.35 17,476	<u> </u>	Assessment History	
DET. GAR. 198 16 3,069 1.00 0.35 3,931		Year Class Land Imp	prov Net
Miscellaneous Write Ins	1	2022 4A 288,500 179,	
Desc Number Desc Value		2021 4A 288,500 179,	
	1	2020 4A 273,500 179,	
		2019 4A 248,500 179,	
		2018 4A 247,500 179,	
			,
		Open Permits	
		Date Number Descriptio	n Value
	L		

Somerset Bound Brook			Property Record (Card		10/1	2/21 06:54 PM		
Block: 10 Lot: 5 Qualifier	r: Card: 1					Last 9	Sale: 07/01/92 for	sLast S	ale: 07
TRUPPELLI, PHYLLIS	Carari	Units:	1 Nbhd:		Model:		VCS:	BR	,
11 MAIDEN LANE		SFLA:	0 Floor:		Bldg Name:		Map Page	:	
BOUND BROOK, NJ 08805		Prop Class:	4A Occupancy:		Zoning:	B2	Year Built	: 1910	/1910
·		Bldg Class:	10		Addtl Lot:		NC Interio	r GOO	D
		Bldg Desc:			Land Dim:	55X141	NC Exteri	or G00	D
11 MAIDEN LANE		Info By:	AT DOOR		Style:		NC Layou	t G00	D
Main Building	0	(no sketo	ch thumbnail)				(no house	picture)	
Attached Items Value	0								
Add/Deduct Value	0								
Base Replacement Cost	0								
Cost Conversion Factor	1.80								
Replacement Cost New	0								
Net Condition	0.70								
Market Adjustment	1.00								
Appraised Value	0								
Detached Items Value	20,020								
Total Land Value	308,300						Room Coun		
Total Improvement Value	20,020						B 1		4 T
Total Value	328,320						Living 0 0		0 0
Valuation Summ	•						Dining 0 0		0 0
Computed Over	,						Kitchen 0		0 0
Land 308,300 308,	•						Bath 0 0		0 0
Improv 20,000 279,	'						Bed 0 0		0 0
Total 588,000	588,000						Rec 0 0		0 0
Floor Area (footp	,						Den 0 0 Total 0 0		0 0
	Jppr Half						Total 0 0	0 0	0 0
Totals 0 0	loor Story Attic								
SqFt Living Area	Sketch Areas								
-	scription Sq Ft								
First Floor 0	scription 34 rt								
Upper Floor 0		Dwelling D	etail		Sales His	story			
Half Story 0		Element	Description	Owner	Suics III.	Date	Book-Page	Price	NU
Fin Attic 0		Bldg Class	<u> </u>	TRUPPELLI	I. PHYLLIS		01863-00316	. 1100	01
Living Bsmnt 0		Type			.,	3,,01,32	11005 00510		71
Unfin Area (-) 0		Yr Built	1910/1910						
Total Area 0		Height	,						
Attached Items		Style							
	Area	Roof Type							
Total Area	0	Roof Mat.			Assessm	nent History			
Detached Items		Bsmnt/Fin		Year Clas		Land	Improv		Net
Desc Area Rate Co	onst QF Cond Value	Fireplace	NONE	2022 4A	308		279,700	58	88,000
	069 1.00 0.35 20,020	•		2021 4A			279,700		88,000
Miscellaneous	Write Ins			2020 4A			325,700		9,000
Desc Number Des				2019 4A			325,700		4,000
•				2018 4A	266	6,500	325,700	59	2,200
				Open		Permi	ts		
				Date	Number				Value
	l					2 0001	F		

Somerset Bound Brook	Property Record C	Card 10/12	2/21 06:54 PM
Block: 10 Lot: 9 Qualifier: Card: 1		Last S.	ale: 09/21/09 for \$180,000Last
SKILL COMPUTING & TRADING, LLC	Units: 1 Nbhd:	Model:	VCS: BR
14 SUMMERVILLE ROAD	SFLA: 0 Floor:	Bldg Name:	Map Page:
BASKING RIDGE NJ 07920	Prop Class: 4A Occupancy:	Zoning:	Year Built: 1910/1910
5.0.0.0.0000000000000000000000000000000	Bldg Class: 10	Addtl Lot:	NC Interior GOOD
	Bldg Desc: 2SB	Land Dim: 25X99	NC Exterior GOOD
210 EACT MAIN CTREET	1 -		
219 EAST MAIN STREET Main Building 0	Info By: AT DOOR	Style:	NC Layout GOOD
3	(no sketch thumbnail)		(no house picture)
Attached Items Value 0			
Add/Deduct Value 0			
Base Replacement Cost 0			
Cost Conversion Factor 1.80			
Replacement Cost New 0			
Net Condition 0.70			
Market Adjustment 1.00			
Appraised Value 0			
Detached Items Value 0			
Total Land Value 142,125			Room Count
Total Improvement Value 0			
·			
Total Value 142,125	4		Living 0 0 0 0 0 0
Valuation Summary			Dining 0 0 0 0 0 0
Computed Override Summary			Kitchen0 0 0 0 0 0
Land 142,100 142,100 142,100			Bath 0 0 0 0 0 0
Improv 58,700 58,700			Bed 0 0 0 0 0 0
Total 200,800 200,800			Rec 0 0 0 0 0 0
Floor Area (footprint)			Den 0 0 0 0 0 0
First Uppr Half			Total 0 0 0 0 0 0
Item Bsmnt Floor Floor Story Attic			
Totals 0 0 0 0 0			
SqFt Living Area Sketch Areas			
Item Area Description Sq Ft			
First Floor 0			
	Duralling Datail	Calaa History	
Upper Floor 0	Dwelling Detail	Sales History	D 1 D D: NU
Half Story 0	Element Description	Owner Date	Book-Page Price NU
Fin Attic 0	Bldg Class 10	SKILL COMPUTING & TRADING, 09/21/09	
Living Bsmnt 0	Type	BINIEK, STANLEY JR. & EL 02/01/88	01672-00243 92,000
Unfin Area (-) 0	Yr Built 1910/1910		
Total Area 0	Height		
Attached Items	Style		
Seg Item Area	Roof Type		
Total Area 0	Roof Mat.		
Detached Items	Bsmnt/Fin	Assessment History	
Desc Area Rate Const QF Cond Value	Fireplace NONE		Improv Net
	Theplace NONE		•
Desc Number Desc Value	-		58,700 200,800
			80,500 211,400
			80,500 194,900
		2018 4A 114,400	80,500 194,900
	1		
		Open Permit	·s
		Open Permit Date Number Descri	

Somerset Bound Brook	Р	roperty Record C	ard	10/	12/21 06:54 PM	
Block: 10 Lot: 10 Qualifier: Card: 1				Lact	: Sale: 03/11/09 fo	r \$226 0001 act
PANADERIA LA REINA LLC	Units:	L Nbhd:		Model:	VCS:	BR
87 HARRISON AVE) Floor:		Bldg Name:	Map Page	
NORTH PLAINFIELD, NJ 07060	Prop Class: 4			Zoning:	Year Built	
NORTH FAINTIEED, NS 07000	Bldg Class: 3			Addtl Lot:	NC Interi	,
	Bldg Desc: 2			Land Dim: 26X99		or GOOD
217 EAST MAIN STREET	_	AT DOOR		Style:	NC Layou	
Main Building 0		thumbnail)		Style.	(no house	
Attached Items Value 0	(110 SKELCI	thannbhan)			(110 110ust	e picture)
Add/Deduct Value 0						
Base Replacement Cost 0						
Cost Conversion Factor 1.80						
Replacement Cost New 0						
Net Condition 0.70						
Market Adjustment 1.00						
Appraised Value 0						
Detached Items Value 0						
Total Land Value 142,125					Room Cour	nt
Total Improvement Value 0					B 1	2 3 4 T
Total Value 142,125					Living 0 0	0 0 0 0
Valuation Summary	1				Dining 0 0	0 0 0 0
Computed Override Summary					Kitchen 0 0	0 0 0 0
Land 142,100 142,100 142,100					Bath 0 0	0 0 0 0
Improv 17,900 17,900					Bed 0 0	0 0 0 0
Total 160,000 160,000					Rec 0 0	0 0 0 0
Floor Area (footprint)	1				Den 0 0	0 0 0 0
First Uppr Half	1				Total 0 0	0 0 0 0
Item Bsmnt Floor Floor Story Attic	1					
Totals 0 0 0 0 0	1					
SqFt Living Area Sketch Areas						
Item Area Description Sq Ft						
First Floor 0						
Upper Floor 0	Dwelling De	tail		Sales History		
Half Story 0	Element [Description	Owner	Date	Book-Page	Price NU
Fin Attic 0	Bldg Class 3	10	PANADERIA LA	REINA LLC 03/11/0	9 06201-01700	226,000 26
Living Bsmnt 0	Type		SWERDLOW, JA	ACOB 11/25/8	7 01660-00812	87,000
Unfin Area (-) 0	Yr Built	1910/1910		·		
Total Area 0	Height					
Attached Items	Style					
Seg Item Area	Roof Type					
Total Area 0	Roof Mat.					
Detached Items	Bsmnt/Fin			Assessment History		
Desc Area Rate Const QF Cond Value	Fireplace I	NONE	Year Class	Land	Improv	Net
Miscellaneous Write Ins	1		2022 4A	142,100	17,900	160,000
Desc Number Desc Value	1		2021 4A	142,100	17,900	160,000
Desc Number Desc Value	1		2020 4A	130,900	37,500	168,400
Desc Number Desc Value			2019 4A	114,400	37,500	151,900
Desc Number Desc Value						
Desc Number Desc Value			2018 4A	114,400	37,500	151,900
Desc Number Desc Value			2018 4A	114,400	37,500	151,900
Desc Number Desc Value			2018 4A	114,400	37,500	151,900
Desc Number Desc Value			2018 4A	114,400	37,500	151,900
Desc Number Desc Value			2018 4A	114,400	37,500	151,900
Desc Number Desc Value						151,900
Desc Number Desc Value			Open Date	Perr		151,900 Value

Somerset Bound Brook	Property Record (Card 10/12/21 06:54 PM
Block: 10 Lot: 18 Qualifier: Card: 1		Last Sale: 01/05/95 for \$25,000Last Sa
A & G MAC INC C/O A MACCHIAVERNA	Units: 1 Nbhd:	Model: VCS: BR
238 GRANT AVENUE	SFLA: 0 Floor:	Bldg Name: Map Page:
SEASIDE HEIGHTS, NJ 08751	Prop Class: 4A Occupancy:	Zoning: B-2 Year Built: 1910/1910
	Bldg Class: 10	Addtl Lot: NC Interior GOOD
	Bldg Desc: 2SB	Land Dim: 27X97 NC Exterior GOOD
16 MOUNTAIN AVENUE	Info By: AGENT	Style: NC Layout GOOD
Main Building 0	(no sketch thumbnail)	(no house picture)
Attached Items Value 0		
Add/Deduct Value 0		
Base Replacement Cost 0		
Cost Conversion Factor 1.80		
Replacement Cost New 0		
Net Condition 0.70		
Market Adjustment 1.00		
Appraised Value 0		
Detached Items Value 0		
Total Land Value 99,700		Room Count
Total Improvement Value 0		B 1 2 3 4 T
Total Value 99,700		Living 0 0 0 0 0 0
Valuation Summary		Dining 0 0 0 0 0 0
Computed Override Summary		Kitchen 0 0 0 0 0 0
Land 99,700 99,700 99,700		Bath 0 0 0 0 0 0
Improv 116,400 116,400		Bed 0 0 0 0 0 0
Total 216,100 216,100]	Rec 0 0 0 0 0 0
Floor Area (footprint)		Den 0 0 0 0 0 0
First Uppr Half		Total 0 0 0 0 0
Item Bsmnt Floor Floor Story Attic]	
Totals 0 0 0 0 0		
SqFt Living Area Sketch Areas		
Item Area Description Sq Ft		
First Floor 0		
Upper Floor 0	Dwelling Detail	Sales History
Half Story 0	Element Description	Owner Date Book-Page Price NU
Fin Attic 0	Bldg Class 10	A & G MAC INC C/O A MACCHIA 01/05/95 01996-00530 25,000 10
Living Bsmnt 0	Туре	
Unfin Area (-) 0	Yr Built 1910/1910	
Total Area 0	Height	
Attached Items	Style	
Seg Item Area	Roof Type	
Total Area 0	Roof Mat.	Assessment History
Detached Items	Bsmnt/Fin	Year Class Land Improv Net
Desc Area Rate Const QF Cond Value	Fireplace NONE	2022 4A 99,700 116,400 216,100
Miscellaneous Write Ins		2021 4A 99,700 116,400 216,100
Desc Number Desc Value	4	2020 4A 92,200 135,300 227,500
		2019 4A 79,700 135,300 215,000
		2018 4A 81,000 134,000 215,000
		Open
		Open Permits
		Date Number Description Value


Somerset Bound Brook		Prope	rty Record C	Card		10/12	2/21 06:54	PM		
Block: 10 Lot: 19 Qualifier: Card: 1						Last S	Sale: 05/31/10	6 for \$	185.0	00Last
18 MOUNTAIN AVE LLC	Units:	1	Nbhd:		Model:		VCS:		BR	
PO BOX 190	SFLA:	0	Floor:		Bldg Name:		Map P	age:		
BOUND BROOK, NJ 08805	Prop Class:	4A	Occupancy:		Zoning:		Year E	_	191	0/1910
,	Bldg Class:		7		Addtl Lot:		NC In		GOO	•
	Bldg Desc:					0X95		terior		
18 MOUNTAIN AVENUE	Info By:	AGEN	Т		Style:		NC La		GOO	
Main Building 0	(no sketo				00,00			ouse p		
Attached Items Value 0	(110 SKCC	zir cirari	ibrian)				(110 110	ouse p	iccai c	,
Add/Deduct Value 0										
Base Replacement Cost 0										
Cost Conversion Factor 1.80										
Replacement Cost New 0										
Net Condition 0.70										
Market Adjustment 1.00	1						1			
Appraised Value 0	1						1			
Detached Items Value 0	1									
Total Land Value 179,250							Room C			
Total Improvement Value 0	1							1 2		4 T
Total Value 179,250							Living 0	0 0	0	0 0
Valuation Summary							Dining 0	0 0	0	0 0
Computed Override Summary							Kitchen0	0 0	0	0 0
Land 179,300 179,300 179,300							Bath 0	0 0	0	0 0
Improv 65,800 65,800							Bed 0	0 0	0	0 0
Total 245,100 245,100							Rec 0	0 0	0	0 0
Floor Area (footprint)							Den 0	0 0	0	0 0
First Uppr Half							Total 0	0 0	0	0 0
Item Bsmnt Floor Floor Story Attic										
Totals 0 0 0 0 0										
SqFt Living Area Sketch Areas										
Item Area Description Sq Ft										
First Floor 0										
Upper Floor 0	Dwelling D	etail			Sales Histo	rv				
Half Story 0	Element	Descri	intion	Owner	Suics misco	Date	Book-Page		Price	e NU
Fin Attic 0	Bldg Class		ption	18 MOUNTAIN	AVELLC		06879-0063	1		00 26
Living Bsmnt 0	Type	10			SPYRIDON & PH					00 20
Unfin Area (-) 0	Yr Built	1910/	1010	I OURNARAS, S	א זוייסטוז א דו	03/22/02	03120-0039	7	03,0	00 10
		1910/	1910							
	Height									
Attached Items	Style									
Seg Item Area	Roof Type									
Total Area 0	Roof Mat.				A 0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.	t Lliote	<u> </u>			
Detached Items	Bsmnt/Fin	NG:-			Assessmen	,				
Desc Area Rate Const QF Cond Value	Fireplace	NONE		Year Class		nd	Improv			Ne
Miscellaneous Write Ins	1			2022 4A	179,3		65,800			45,100
Desc Number Desc Value	1			2021 4A	179,3		65,800			45,100
	1			2020 4A	168,0		90,000			58,000
	1			2019 4A	149,3		90,000			39,300
	1			2018 4A	125,0	00	90,000		2	15,000
				Open		Permi	ts			
	1			Date	Number	Descr				Value
				Juice	Halliber	Desci				Value

		Property Record C	Card	10/1	.2/21 06:54 PM	
Block: 10 Lot: 20 Qualifier: Card: 1				Last 9	Sale: 08/21/99 for	\$90,000Last Sa
A&G MAC INC C/O A. MACCHIAVERNA	Units:	1 Nbhd:		Model:	VCS:	BR
238 GRANT AVE	SFLA:	0 Floor:		Bldg Name:	Map Page	:
SEASIDE HEIGHTS, NJ 08751	Prop Class:	4A Occupancy:		Zoning:	Year Built	
1, 1111	Bldg Class:	• • •		Addtl Lot:	NC Interio	
	_	GARAGES		Land Dim: 95X95	NC Exterio	
209 EAST MAIN STREET	Info By:	AGENT		Style:	NC Layout	
Main Building 0		ch thumbnail)		50,.51	(no house	
Attached Items Value 0	(110 Sites	ch chambhan,			(no nouse	piccurcy
Add/Deduct Value 0						
Base Replacement Cost 0						
Cost Conversion Factor 1.80						
Replacement Cost New 0						
Net Condition 1.00						
Market Adjustment 1.00					1	
1					1	
					1	
Detached Items Value 110,637					Da C	
Total Land Value 253,500					Room Count	
Total Improvement Value 110,637					B 1	2 3 4 T
Total Value 364,137					Living 0 0	0 0 0 0
Valuation Summary					Dining 0 0	0 0 0 0
Computed Override Summary					Kitchen 0 0	0 0 0 0
Land 253,500 253,500 253,500					Bath 0 0	0 0 0 0
Improv 110,600 1,900 1,900					Bed 0 0	0 0 0 0
Total 255,400 255,400					Rec 0 0	0 0 0 0
Floor Area (footprint)					Den 0 0	0 0 0 0
First Uppr Half					Total 0 0	0 0 0 0
Item Bsmnt Floor Floor Story Attic						
Totals 0 0 0 0 0						
SqFt Living Area Sketch Areas						
Item Area Description Sq Ft						
First Floor 0						
First Floor 0 Upper Floor 0	Dwelling D	Petail		Sales History		
	Dwelling D Element	Detail Description	Owner	Date	Book-Page	Price NU
Upper Floor 0	_	Description		· · · · · · · · · · · · · · · · · · ·		Price NU 90,000 07
Upper Floor 0 Half Story 0	Element	Description		Date		
Upper Floor 0 Half Story 0 Fin Attic 0	Element Bldg Class	Description		Date		
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0	Element Bldg Class Type	Description 10		Date		
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0	Element Bldg Class Type Yr Built	Description 10		Date		
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0 Total Area 0	Element Bldg Class Type Yr Built Height	Description 10		Date		
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0 Total Area 0 Attached Items	Element Bldg Class Type Yr Built Height Style	Description 10		Date		
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0 Total Area 0 Attached Items Seg Item Area	Element Bldg Class Type Yr Built Height Style Roof Type	Description 10		Date C/O A. MACCHIAV08/21/99		
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0 Total Area 0 Attached Items Seg Item Area Total Area 0 Detached Items	Element Bldg Class Type Yr Built Height Style Roof Type Roof Mat.	Description 10	A&G MAC INC	Date C/O A. MACCHIAV08/21/99 Assessment History Land	02260-00121 Improv	90,000 07 Net
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0 Total Area 0 Attached Items Seg Item Area Total Area 0 Detached Items Desc Area Rate Const QF Cond Value	Element Bldg Class Type Yr Built Height Style Roof Type Roof Mat. Bsmnt/Fin Fireplace	Description 10 0000/0000	A&G MAC INC Year Class 2022 4A	Date C/O A. MACCHIAV08/21/99 Assessment History Land 253,500	02260-00121 Improv 1,900	90,000 07 Net 255,400
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0 Total Area 0 Attached Items Seg Item Area Total Area 0 Detached Items Desc Area Rate Const QF Cond Value DET. GAR. 2,112 16 3,069 1.25 0.65 53,973	Element Bldg Class Type Yr Built Height Style Roof Type Roof Mat. Bsmnt/Fin Fireplace	Description 10 0000/0000	Year Class 2022 4A 2021 4A	Date C/O A. MACCHIAV08/21/99 Assessment History Land 253,500 253,500	Improv 1,900 1,900	90,000 07 Net 255,400 255,400
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0 Total Area 0 Total Area 0 Total Area 0 Detached Items Desc Area Rate Const QF Cond Value DET. GAR. 2,112 16 3,069 1.25 0.65 56,666 DET. GAR. 2,227 16 3,069 1.25 0.65 56,666	Element Bldg Class Type Yr Built Height Style Roof Type Roof Mat. Bsmnt/Fin Fireplace	Description 10 0000/0000	A&G MAC INC Year Class 2022 4A	Date C/O A. MACCHIAV08/21/99 Assessment History Land 253,500 253,500 242,300	Improv 1,900 1,900 26,500	90,000 07 Net 255,400 255,400 268,800
Upper Floor 0 Half Story 0 Fin Attic 0 Living Bsmnt 0 Unfin Area (-) 0 Total Area 0 Attached Items Seg Item Area Total Area 0 Detached Items Desc Area Rate Const QF Cond Value DET. GAR. 2,112 16 3,069 1.25 0.65 53,973 DET. GAR. 2,227 16 3,069 1.25 0.65 56,666	Element Bldg Class Type Yr Built Height Style Roof Type Roof Mat. Bsmnt/Fin Fireplace	Description 10 0000/0000	Year Class 2022 4A 2021 4A 2020 4A	Date C/O A. MACCHIAV08/21/99 Assessment History Land 253,500 253,500	Improv 1,900 1,900	90,000 07 Net 255,400 255,400
Upper Floor	Element Bldg Class Type Yr Built Height Style Roof Type Roof Mat. Bsmnt/Fin Fireplace	Description 10 0000/0000	Year Class 2022 4A 2021 4A 2020 4A 2019 4A 2018 4A	Date C/O A. MACCHIAV08/21/99 Assessment History Land 253,500 253,500 242,300 223,500 221,300	Improv 1,900 1,900 26,500 26,500 28,700	Net 255,400 255,400 268,800 250,000
Upper Floor	Element Bldg Class Type Yr Built Height Style Roof Type Roof Mat. Bsmnt/Fin Fireplace	Description 10 0000/0000	Year Class 2022 4A 2021 4A 2020 4A 2019 4A	Date C/O A. MACCHIAV08/21/99 Assessment History Land 253,500 253,500 242,300 223,500 221,300 Perm	Improv 1,900 1,900 26,500 26,500 28,700	Net 255,400 255,400 268,800 250,000




PRELIMINARY INVESTIGATION

Block 10, Lots 1–20 Bound Brook, New Jersey October 2021



BLOCK 10, LOT 1






Address	24 Mountain Avenue
Owner	U.S. Post Office
Class	15F
Tenant	U.S. Post Office
Condition	Good
Comments	2-story brick building; 73x135 IRR lot

BLOCK 10, LOT 2






Address	212-214 East Second Street
Owner	Bonilla, Jose A
Class	2
Tenants	NA
Condition	Good
Comments	2-story 4,160 SF building built in 1875 on 0.1194 acres; 50'x104' lot

BLOCK 10, LOT 3








·	
Address	218 East Second Street
Owner	Mamani, Jesenia
Class	2
Tenants	NA
Condition	Fair
Comments	2-story 1,248 SF brick building built in 1884 on 0.0293 acres; 15'x85' lot

BLOCK 10, LOT 3.01









Address	220 East Second Street
Owner	Mamani, Ana M
Class	2
Tenants	NA
Condition	Fair
Comments	2-story 1,248 SF brick building built in 1884 on 0.032 acres; 16'x87' lot








Address	222 East Second Street
Owner	Acevedo, Jose, Rosalia & Julia
Class	2
Tenants	NA
Condition	Poor - deteriorating façade, porch roof and gutter disrepair
Comments	2-story 1,248 SF brick building built in 1884 on 0.032 acres; 16'x87' lot








Address	224 East Second Street
Owner	Narvaez, Eduardo
Class	2
Tenants	NA
Condition	Fair
Comments	2-story 1,248 SF brick building built in 1884 on 0.032 acres; 16'x87' lot








Address	226 East Second Street
Owner	De Hermoza, Victoria Zarate
Class	2
Tenants	NA
Condition	Fair
Comments	2-story 1,248 SF brick building built in 1884 on 0.032 acres; 16'x87' lot








Address	228 East Second Street
Owner	Ianniello, Rose
Class	2
Tenants	NA
Condition	Fair
Comments	2-story 1,248 SF brick building built in 1884 on 0.032 acres; 16'x87' lot








Address	230 East Second Street
Owner	Hermoza, Elio & Felicitas Vila
Class	2
Tenants	NA
Condition	Fair
Comments	2-story 1,248 SF brick building built in 1875 on 0.032 acres; 16'x87' lot









Address	232 East Second Street
Owner	Castro-Fernandez, Alexander
Class	2
Tenants	NA
Condition	Good
Comments	2-story 1,248 brick building built in 1875 on 0.0379 acres; 19'x87' lot





Address	15-17 Maiden Lane
Owner	Schwall, Charlie & Pannia Michele
Class	4A
Tenants	T&R Insulation and Firestop, Sole's Barber Shop
Condition	Fair
Comments	2-story brick building built in 1915 on 0.155 acres; 50'x135' lot








Address	11 Maiden Lane
Owner	Truppelli, Phyllis
Class	4A
Tenants	Graphic Concepts
Condition	Poor – front stairs in disrepair, rear building has structural issues
Comments	2-story brick/stucco building built in 1910 on 0.178 acres; 55'x141' lot








Address	225-231 East Main Street
Owner	Casa Morales, LLC
Class	4A
Tenants	Shiny Angel Jewelry, Lara Communications LLC – Cricket Wireless, The
	Allongo Law Firm, LLC, Saray Boutique & Tailor, Bonnie Decorators,
	Strategic Staffing Solution, One Way Nutrition
Condition	Poor – plywood at corner door, corner of building damaged, misc. disrepair
Comments	1-story building on 0.1148 acres; 50'x100' lot


BLOCK 10, LOT 7 & 8








Address	223 East Main Street
Owner	AHA Holding Group LLC
Class	4A
Tenant	World Supermarket
Condition	Good
Comments	2-story brick building built in 1964 on 0.1136 acres; 50'x99' lot









Address	219 East Main Street
Owner	Skill Computing & Trading, LLC
Class	4A
Tenants	Vacant
Condition	Poor – in need of maintenance and repair
Comments	2-story building built in 1910 on 0.0568 acres; 25'x99' lot









Address	217 East Main Street
Owner	Panaderia La Reina LLC
Class	4A
Tenants	Vacant
Condition	Poor – in need of maintenance and repair
Comments	2-story building built in 1910 on 0.0591 acres; 26'x99' lot








Address	215 East Main Street
Owner	Hamilton Bound LLC
Class	4A
Tenants	Patricia Sabor Casero & Deli, Pet Spaw, 2 nd floor residential
Condition	Good
Comments	2-story brick building built in 1910 on 50x107 IRR lot, includes Lot 12








Address	213 East Main Street
Owner	Hamilton Bound LLC
Class	4A
Tenants	AiT USA Institute, 2 nd floor residential
Condition	Poor – needs exterior maintenance
Comments	2-story building; included in lot size of Block 10, Lot 11

BLOCK 10, LOT 13 & 14









Address	211 East Main Street
Owner	211 East Main St, LLC
Class	4A
Tenants	El Palacio
Condition	Good
Comments	2-story brick building built in 1972 on 0.1517 acres; 56'x118' lot






Address	205-207 East Main Street
Owner	Gerber, Eleanor C/O Lilaine, Inc.
Class	4A
Tenants	Latino Minimarket, 2 nd floor residential
Condition	Good
Comments	2-story building built in 1900 on 0.1245 acres; 48'x113' lot






Address	201-203 East Main Street
Owner	Casa Morales LLC
Class	4A
Tenants	MG Beauty Salon & Barber Shop, Flowers Ethan, Melissa's Bakery-El Chilaquil, 2 nd and 3 rd floor residential
Condition	Good
Comments	3-story building built in 1910 on 0.1409 acres; 52'x118' lot









Address	14 Mountain Avenue
Owner	Berghahn, Walter
Class	4A
Tenants	<u>Unknown</u>
Condition	Fair
Comments	2-story brick building built in 1910 on 0.0476 acres; 25'x83' lot






Address	16 Mountain Avenue
Owner	A&G Mac Inc C/O A Macchiaverna
Class	4A
Tenants	Lasered Effects LLC Trophies & Awards, 2 nd floor residential
Condition	Fair
Comments	2-story brick building built in 1910 on 0.0601 acres; 27'x97' lot





Address	18 Mountain Avenue
Owner	18 Mountain Ave LLC
Class	4A
Tenants	Downtown Bound Brook Revitalization Partnership
Condition	Fair
Comments	2-story brick building built in 1910 on 0.109 acres; 50'x95' lot





Address	209 East Main Street
Owner	A&G Mac Inc C/O A Macchiaverna
Class	4A
Tenants	E&N Towing
Condition	Poor –in need of maintenance and repair
Comments	1-story garages on a 95'x95' lot consisting of 0.2072 acres

cation Address	Block Lot	Owner Name	Owner Address	Issue Date	Compliance (Statute	Statute Number	Statute Source	Issuing Officer	Summons Number
5-17 MAIDEN LANE	10	4 SCHWALL, CHARLIE & PANNIA MICHELE	16 OBERT DR	3/3/20	3/10/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
7 MAIDEN LANE	10	4 SCHWALL, CHARLIE & PANNIA MICHELE	16 OBERT DR	3/16/18	3/30/18 Z21 - Land Use-Zoning Permits Required	Z 21	Zoning Chp 21	Leticia Rodriguez	
5-17 MAIDEN LANE	10	4 SCHWALL, CHARLIE & PANNIA MICHELE	16 OBERT DR	6/16/20	6/23/20 17-20.5 Disposal of Garbage		20.5 Property Maintenance Chp 17	Tyler Gronau	
1 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	4/6/17	4/28/17 Defacement of property	302.9 Defacement of	property Building Officials and Code Administrators (BOCA) 2000	Joe Costa	
1 MAIDEN LANE		5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	8/31/20	9/7/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
1 MAIDEN LANE		5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	3/8/21	3/14/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
1 MAIDEN LANE			11 MAIDEN LANE	3/15/21	3/22/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
1 MAIDEN LANE		5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	3/22/21	3/29/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	13549
1 MAIDEN LANE		5 TRUPPELLI, PHYLLIS	38 BEECHTREE ROAD	5/13/20	5/20/20 17-20.5 Disposal of Garbage		20.5 Property Maintenance Chp 17	Tyler Gronau	
1 MAIDEN LANE		5 TRUPPELLI, PHYLLIS	38 BEECHTREE ROAD	5/20/20	5/27/20 17-20.5 Disposal of Garbage		20.5 Property Maintenance Chp 17	Tyler Gronau	
1 MAIDEN LANE		5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	8/31/20	9/7/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
19 EAST MAIN STREET		9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	9/22/20	9/29/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
19 EAST MAIN STREET		9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	10/1/20	10/8/20 17-14.10. Defacement of property.		14.1 Property Maintenance Chp 17	Tyler Gronau	
19 EAST MAIN STREET		9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	9/22/20	9/29/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
19 EAST MAIN STREET 19 EAST MAIN STREET		9 SKILL COMPUTING & TRADING, LLC 9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD 14 SUMMERVILLE ROAD	6/9/21 3/8/21	6/16/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris 3/15/21 17-20.4 Appliances. Furniture. Mattresses. Discarded Items		20.1 Property Maintenance Chp 17 20.4 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	13775
19 EAST MAIN STREET		9 SKILL COMPUTING & TRADING, LLC 9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD 14 SUMMERVILLE ROAD	3/8/21	3/15/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items 3/15/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17 20.4 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	13603
19 EAST MAIN STREET		9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	3/9/21	3/15/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items 3/22/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17 20.4 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	13603
19 EAST MAIN STREET		9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	3/22/21	3/29/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items 3/29/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17 20.4 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	
17 EAST MAIN STREET			217 E MAIN STREET	8/3/17	8/16/17 17-20.4 Appliances, Furniture, Mattresses, Discarded Items 8/16/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individua	el.	26.3 Property Maintenance Chp 17 26.3 Property Maintenance Chp 17	Joe Costa	
17 EAST MAIN STREET			217 E MAIN STREET	9/8/17	9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Responsible Individual 9/8/17-26.3 Registration of Responsible Individual 9/8/17-26.3 Registration of Responsible I		26.3 Property Maintenance Chp 17 26.3 Property Maintenance Chp 17	Joe Costa	10345
17 EAST MAIN STREET			217 EAST MAIN STREET	1/6/18	1/31/18 17-16.25 Duty to Remove Snow & Ice.		16.25 Property Maintenance Chp 17	Eric Mickelsen	10343
17 EAST MAIN STREET			217 E MAIN STREET	5/23/19	5/31/19 17-24.1Duties of owners and tenants.		24.1 Property Maintenance Chp 17	Jose Nieves	11691
17 EAST MAIN STREET			217 E MAIN STREET	5/15/19	5/21/19 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Joe Costa	11643
17 EAST MAIN STREET			217 E MAIN STREET	5/15/19	5/29/19 17-30.3 Registration of Vacant Commercial Unit		30.3 Property Maintenance Chp 17	Joe Costa	1104.
17 EAST MAIN STREET		10 PANADERIA LA REINA LLC	87 HARRISON AVE	2/19/21	5/21/21 14-7.3 Requirements for refuse containers. c.	14-7.3 c. Fence	Building & Construction Chp 14	Jose Nieves	
17 EAST MAIN STREET	10	10 PANADERIA LA REINA LLC	87 HARRISON AVE	2/19/21	5/21/21 14-7.3 Requirements for refuse containers, c.	14-7.3 c. Fence	Building & Construction Chp 14	Jose Nieves	
17 EAST MAIN STREET	10	10 PANADERIA LA REINA LLC	87 HARRISON AVE	9/22/20	9/29/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
17 EAST MAIN STREET	10	10 PANADERIA LA REINA LLC	87 HARRISON AVE	6/3/21	6/24/21 17-26.5 Registration Fees		26.5 Property Maintenance Chp 17	Jose Nieves	13750
17 EAST MAIN STREET	10	10 PANADERIA LA REINA LLC	87 HARRISON AVE	6/9/21	6/16/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	13774
17 EAST MAIN STREET	10	10 PANADERIA LA REINA LLC	87 HARRISON AVE	3/22/21	3/29/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	13548
B MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	7/29/19	8/27/19 17-22.20 Smoke Detection System		22.2 Property Maintenance Chp 17	Jose Nieves	
B MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	7/29/19	8/27/19 17-22.6 Key Lock Bedroom Doors Not Permitted		22.6 Property Maintenance Chp 17	Jose Nieves	
B MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	3/11/20	3/18/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	12734
B MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	3/11/20	3/18/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	3/3/20	3/10/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	7/29/19	8/28/19 5:10-19.2a 1-7 Multiple dwellings	5:10-19.2a 1-7	NJAC 5:10	Jose Nieves	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	18 MOUNTAIN AVENUE	1/14/19	2/11/19 5:10-1:10a Bureau inspections	1.10a	NJAC 5:10	Douglas Kowalsky	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	10/7/20	10/14/20 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	10/7/20	10/14/20 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	13343
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	10/14/20	10/21/20 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	6/9/21	6/16/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris	3-1 10	20.1 Property Maintenance Chp 17	Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	6/9/21	6/16/21 3-1.10 Storage of tires.		Police Chp 3	Tyler Gronau	13779
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	4/14/21	4/21/21 3-1.10 Storage of tires.	3-1.10	PoliceChp 3	Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	4/14/21	4/21/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC 19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	3/10/21 4/14/21	3/17/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items	3-1.10	20.4 Property Maintenance Chp 17 Police Chp 3	Tyler Gronau	13608
B MOUNTAIN AVENUE B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC 19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	4/14/21	4/21/21 3-1.10 Storage of tires. 4/21/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items	3-1.10	20.4 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	1360
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC 19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	4/14/21	4/21/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items 4/21/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.4 Property Maintenance Chp 17 20.1 Property Maintenance Chp 17		1360)
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC 19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	4/14/21	4/21/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris 4/21/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17 20.1 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	1360
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC 19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	4/14/21	4/21/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris 4/22/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17 20.1 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	13600
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC 19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	4/14/20	4/22/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris 4/13/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17 20.1 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	4/22/20	5/6/20 3-1.10 Storage of tires.	3-1.10	20.1 Property Maintenance Cnp 17 Police Chp 3	Tyler Gronau Tyler Gronau	
B MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190 PO BOX 190	4/22/20		3-1.10	20.1 Property Maintenance Chp 17	Tyler Gronau Tyler Gronau	
B MOUNTAIN AVENUE D9 EAST MAIN STREET			238 GRANT AVE	4/22/20 8/3/17	5/6/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris 8/16/17 17-26.3 Registration of Vacant Properties: Designation of Responsible Individu.	al.	20.1 Property Maintenance Chp 17 26.3 Property Maintenance Chp 17	Tyler Gronau Joe Costa	
09 EAST MAIN STREET		20 A&G MAC INC C/O A. MACCHIAVERNA or responsible party		9/8/17	9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual 9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual		26.3 Property Maintenance Chp 17 26.3 Property Maintenance Chp 17	Joe Costa	10347
09 EAST MAIN STREET		20 A&G MAC INC C/O A. MACCHIAVERNA OF responsible party	238 GRANT AVE	3/8/21	3/15/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris	a	20.1 Property Maintenance Chp 17 20.1 Property Maintenance Chp 17	Tyler Gronau	1347

Permit Number	Permit Issue Date	Control Number	Location Address	Block	Lot	
20-0255	11/16/20	C-20-0436	15-17 MAIDEN LANE		10	4
18-0153	6/20/18	C-18-0252	15-17 MAIDEN LANE - 17 Maiden Lane		10	4
16-0141	3/24/16	C-16-0148	15-17 MAIDEN LANE		10	4
16-0137	3/22/16	C-16-0141	15-17 MAIDEN LANE		10	4
15-0096	2/13/15	C-15-0032	15-17 MAIDEN LANE - 17 MAIDEN LANE - Pellegrini		10	4
15-0008	1/9/15	C-15-0004	15-17 MAIDEN LANE		10	4
14-0567	12/4/14	C-14-0818	15-17 MAIDEN LANE		10	4
12-0237	5/22/12	C-12-0219	15-17 MAIDEN LANE		10	4
11-0391	9/8/11	C-11-0484	15-17 MAIDEN LANE		10	4
10-0140	3/19/10	C-10-0169	15-17 MAIDEN LANE		10	4
07-0429	5/11/07	C-07-02673	15-17 MAIDEN LANE		10	4
21-0204	9/2/21	C-21-0283	10 MAIDEN LANE		10	5
18-0134+A	7/10/18	C-18-0290	11 MAIDEN LANE		10	5
18-0134	6/1/18	C-18-0135	11 MAIDEN LANE		10	5
18-0087	4/6/18	C-18-0142	11 MAIDEN LANE		10	5
09-0326	8/27/09	C-09-0373	11 MAIDEN LANE - Graphic Concepts		10	5
07-0566	5/19/07	C-07-02812	11 MAIDEN LANE		10	5
07-0262	4/29/07	C-07-02463	11 MAIDEN LANE		10	5
13-0338	8/22/13	C-13-0419	219 EAST MAIN STREET		10	9
12-0081	2/22/12	C-12-0041	219 E.MAIN ST		10	9
12-0008	1/4/12	C-12-0006	219 E.MAIN ST		10	9
10-0409	5/11/10	C-10-0490	219 E.MAIN ST		10	9
10-0399	5/6/10	C-10-0473	219 E.MAIN ST		10	9
10-0200	3/21/10	C-10-0239	219 E.MAIN ST		10	9
09-0471	12/4/09	C-09-0545	219 E.MAIN ST		10	9
09-0449	11/16/09	C-09-0526	219 E.MAIN ST		10	9
09-0412	10/26/09	C-09-0479	219 E.MAIN ST - Skill Computing & Trading LLC		10	9
09-0339	9/11/09	C-09-0406	219 E.MAIN ST		10	9
09-0331	9/3/09	C-09-0386	219 E.MAIN ST - Stan's Shoe Shack		10	9
09-0317	8/18/09	C-09-0362	219 E.MAIN ST - Stan's Shoe Shack		10	9
07-0517	5/15/07	C-07-02764	219 E.MAIN ST		10	9
10-0487	7/6/10	C-10-0579	217 E. MAIN ST.		10	10
07-0558	5/19/07	C-07-02803	217 E. MAIN ST.		10	10
11-0180	6/18/11	C-11-0223	16 MOUNTAIN AVE.		10	18

11-0091	4/1/11 C-11-0113	16 MOUNTAIN AVE 1st Floor- Lasered Effects LLC	10	18
08-0065+E	1/5/11 C-10-0847	16 MOUNTAIN AVE.	10	18
08-0065+D	11/9/10 C-10-0823	16 MOUNTAIN AVE.	10	18
08-0065+B	9/7/10 C-10-0663	16 MOUNTAIN AVE.	10	18
08-0065+C	9/7/10 C-10-0664	16 MOUNTAIN AVE.	10	18
08-0065+A	1/16/09 C-09-0005	16 MOUNTAIN AVE.	10	18
08-0065	2/27/08 C-08-00069	16 MOUNTAIN AVE.	10	18
15-0453	9/9/15 C-15-0332	18 MOUNTAIN AVENUE	10	19
14-0375	7/15/14 C-14-0558	18 MOUNTAIN AVENUE	10	19
20060381	11/20/06	18 MOUNTAIN AVENUE	10	19
20060375	11/14/06	18 MOUNTAIN AVE.	10	19
200300182	6/26/06	18 MOUNTAIN AVENUE	10	19
20060172	5/26/06	18 MOUNTAIN AVENUE	10	19
20060113	4/7/06	18 MOUNTAIN AVENUE	10	19
10-0043	2/11/10 C-10-0053	209 E. MAIN ST.	10	20
09-0120	4/9/09 C-09-0125	209 E. MAIN STDi'America	10	20
07-0559	5/19/07 C-07-02805	209 E. MAIN ST.	10	20
20040057	3/3/04	209 EAST MAIN STREET	10	20

Application Date	Application Status	Subcodes U	Work Type	Work Desci
	Certificate (CCO) Issued	BPEF	(None)	CCO Inspec
	CA and Close Date Issued	BPEF	Alteration	·
	CCO and Close Date Issued	BPEF	Alteration	
	CA and Close Date Issued	Р	Alteration	
1/30/15		Е	Alteration	
	CA and Close Date Issued	В	Alteration	
11/25/14	Certificate (CO) Issued	BPEF	Alteration	
5/22/12	Voided	BPEF	Alteration	
9/8/11	CA and Close Date Issued	E	Alteration	
3/19/10	CA and Close Date Issued	E	Alteration	
5/11/07	Closed with Date	E	Alteration	
9/2/21	Certificate (CCO) Issued	BPEF	(None)	
7/10/18	Finals Passed	E	Alteration	
3/26/18	Finals Passed	EF	Alteration	
3/29/18	CA and Close Date Issued	В	(None)	
8/25/09	CA and Close Date Issued	P	Alteration	
5/19/07	Closed with Date	PEF	Alteration	BOILER REP
4/29/07	Closed with Date	E	Alteration	
8/16/13	Closed with Date	E	Alteration	
1/26/12	Closed with Date	E	Alteration	
1/3/12	CA and Close Date Issued	PEF	Alteration	REPLACEME
5/11/10	Closed with Date	PEF	Alteration	
5/1/10	CA and Close Date Issued	В	Alteration	
3/21/10	CA and Close Date Issued	E	Alteration	
	CA and Close Date Issued	E	Alteration	
11/14/09	CA and Close Date Issued	В	Alteration	
10/26/09	CCO and Close Date Issued	BPEF	Alteration	
	CA and Close Date Issued	PΕ	Alteration	
	CCO and Close Date Issued	BPEF	Alteration	
8/18/09	CA and Close Date Issued	В	Demolition	REMOVAL C
	CA and Close Date Issued	Р		REPLACEME
	CA and Close Date Issued	E	Alteration	
	Closed with Date	E	Alteration	
6/18/11	CA and Close Date Issued	Е	Alteration	ENTRANCE:

4/1/11	CCO and Close Date Issued	BPEF	Alteration
11/23/10	CA and Close Date Issued	EF	Alteration
11/8/10	CA and Close Date Issued	В	Alteration
8/26/10	CA and Close Date Issued	BPEF	Alteration
8/26/10	CA and Close Date Issued	BEF	Alteration
1/6/09	CA and Close Date Issued	BEF	Alteration
2/25/08	CO and Close Date Issued	BPEF	Alteration
7/1/15	CCO and Close Date Issued	BPEF	Alteration
7/15/14	CCO and Close Date Issued	BPEF	Alteration
11/20/06		BE	Alteration
11/14/06	Closed with Date	В	Alteration
6/26/06			(None)
5/26/06		Р	Alteration
4/7/06		BPF	Alteration
2/8/10	CA and Close Date Issued	В	Alteration
4/9/09	CCO and Close Date Issued	BPEF	Alteration
5/19/07	Closed with Date	E	Alteration
3/3/04	CA and Close Date Issued	Р	Alteration

Work Description Comments

All necessary Zoning Permits and applicable construction permits must be obtained and approved before this space can be occupied and or used.

CCO Inspections for Offices for Firestop/Insulation. 17 Maiden Lane, T&R Insulation and Firestop.

CCO Inspections for Tenant, Nila Nicholas, Candy with a Twist.

Install 1 hand sink & 1-3 bay sink, 1 floor drain.

Low -voltage Burglar Alarm.

Remove & replace roof @ Garage.

Converting 2nd floor of building into 2 new 2 bedroom apartments.

CCO INSPECTION FOR STUDIO, BOOK STORE & INTERNET RENTAL

REPLACE ELECTRICAL PANELS DUE TO FLOOD

REPLACE PANELS DUE TO FLOOD

REPLACE PANEL DUE TO FLOOD

CCO INSPECTION FOR BARBER SHOP

INSTALL (1) RECEPTACLE

Install fire alarm system for windowless basement

iNSTALL 15'4 x 8'3" INNER WALL"

Sewer repair

LACEMENT REPLACEMENT WATER HEATER

REPLACE BREAKERS IN THE PANEL DUE TO THE FLOOD

CONNECTION TO INSTALL A CYCLE CONTROL BOX ON AN EXISTING AC UNIT

WIRE FURNACE ON 1ST FLOOR

ENT FURNACE

REPLACE FURNACE

INSTALL NEW WALL MOUNTED SIGN

REPLACE BREAKERS IN PANEL DUE TO FLOOD

Add two receptacles, one for cash register & one for vending machine.

MINOR FRAMING FOR WINDOWS, CLOSET AND REMOVE NON BEARING WALL

CCO Inspections to open Retail Store - DOLLA SMART

ELECTRIC WATER HEATER

CCO Inspections for Resale of Building. Retail Use

)F 275 TANK IN BASEMENT

ENT FURNACE

INSTALL FUSED DISCONNECT IN THE BASEMENT & PANEL ON 1ST. FLOOR

REPLACE BREAKERS IN PANEL DUE TO FLOOD

INSTALL 2 150 SERVICES

CCO Inspections for Retail Store on 1st. floor. Trophies & Awards, Uniforms & Embroidery.

ADD SMOKE DETECTOR TO SYSTEM

ENCLOSURE OF EXISTING STAIRWAY

CONVERT 2ND FLOOR OFFICE INTO A LIVING UNIT

DUCTWORK, EXTRA ELECTRICAL & SMOKE DETECTORS ON 2ND FLOOR

ENCLOSED STAIR CASE FOR 2ND EXIT

2ND FLOOR APARTMENT

CCO Inspections, 18 Mountain Ave.. Tenant: BBRP Downtown Business Improvement Office.

CCO FOR THRIFT STORE

INSTALL NEW AWNING
CCO INSPECTIONS FOR RETAIL STORE - Buy Gold, Repair watches, sell perfumes, used electronics, tools, passport photos.
REPLACE PANEL DUE TO FLOOD

Checklist St To	otal Const Al	lteration (Owner Name	Owner Address	Owner Address 2
Complete			SCHWALL, CHARLIE & PANNIA MICHELE	14 OBERT DR	
Complete	4	4	SCHWALL, CHARLIE & PANNIA MICHELE	16 OBERT DR	
Complete	4	4	Charlie Schwall & Michele Pannia	15-17 MAIDEN LANE	
Complete	3,500	3,500	Charlie Schwall & Michele Pannig	15-17 MAIDEN LANE	
Complete	2,231	2,231	Maiden Holding LLC	Box470	
Complete	1,800	1,800	Charlie Schwall	941 East Main Street	
Complete	36,000	36,000	Charlie Schwall	941 East Main Street	
Complete	4	4	GOMERO, RODOLFO & SOLEDAD	15-17 MAIDEN LANE	
Complete	900	900	GOMERO, RUDOLAFO	15-17 MAIDEN LANE	
Complete	900	900	REDINGTON, ELINOR S.	2286 BROOKSIDE DRIVE	
Complete	1,200	1,200	REDINGTON, ELINOR S.	2286 BROOKSIDE DRIVE	
Complete			GERARDO MELENDEZ	301-307 EAST MAIN ST.	
Complete	95	95	TRUPPELLI, PHYLLIS	38 BEECHTREE ROAD	
Complete	3,000	3,000	TRUPPELLI, PHYLLIS	38 BEECHTREE ROAD	
Complete			TRUPPELLI, GERALD	38 BEECHTREE ROAD	
Complete	4,500	4,500	TRUPPELLI, PHYLLIS	38 BEECHTREE RD	
Complete	16,700	16,700	TRUPPELLI, PHYLLIS	38 BEECHTREE RD	
Complete	600	600	TRUPPELLI, PHYLLIS	38 BEECHTREE RD	
Complete	200	200	SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	
Complete	600	600	SKILL COMPUTER & TRADING	14 sOMERVILLE ROAD	
Complete	1,100	1,100	KINNY, SCOTT	14 SOMERVILLE ROAD	
Complete	3,700	3,700	SKILLS COMPUTING & TRADING LLC.	14 SOMERVILLE ROAD	
Complete	2,000	2,000	SKILLS COMPUTING & TRADING COMPANY	14 SOMERVILLE ROAD	
Complete	300	300	SKILL COMPUTING & TRADING LLC.	14 SIMERVILLE ROAD	
Complete	300	300	Skill Trade & Computing, LLC	219 East Main Street	
Complete	1,600	1,600	SKILL TRADING AND COMPLUTING	14 SOMMERVILLE ROAD	
Complete	4	4	Anina Shen	14 Somerville Rd.	
Complete	1,250	1,250	BINIEK, STANLEY JR. & ELOISE	409 HOLLYWOOD AVENUE	
Complete	4	4	BINIEK, STANLEY JR. & ELOISE	409 HOLLYWOOD AVENUE	
Complete	675	675	BINIEK, STANLEY JR. & ELOISE	409 HOLLYWOOD AVENUE	
Complete	1,800	1,800	BINIEK, STANLEY JR. & ELOISE	409 HOLLYWOOD AVENUE	
Complete	1,400	1,400	ORTIZ, GUSTAVO	428 DARROW AVENUE	
Complete	600		SWERDLOW, JACOB	311 WEST UNION AVENUE	
Complete	6,400	6,400	A & G MAC INC	60 DAYTON AVENUE	

Complete	4	4	A & G MAC INC	60 DAYTON AVENUE
Complete	370	370	A & G MAC INC	60 DAYTON AVENUE
Complete	550	550	A & G MAC INC	60 DAYTON AVENUE
Complete	7,000	7,000	A & G MAC INC	60 DAYTON AVENUE
Complete	8,585	8,585	A & G MAC INC	60 DAYTON AVENUE
Complete	14,250	14,250	A & G MAC INC	60 DAYTON AVENUE
Complete	32,600	32,600	A & G MAC INC	60 DAYTON AVENUE
Complete	4	4	POURNARAS, SPYRIDON & PHYLLIS	570 WINSOR STREET
Complete	4	4	POURNARAS, SPYRIDON & PHYLLIS	570 WINSOR STREET
Complete	1,250		Marc Kissel Tenant	18 MOUNTAIN AVENUE
Complete	3,200		Spyridon Pournaras	18 MOUNTAIN AVE.
Complete	400		Spyridon Pournaras	18 MOUNTAIN AVENUE
Complete	400		Spyridon & Phyllis Pournaras	18 MOUNTAIN AVENUE
Complete	1,580		Spyridon Pournaras	18 MOUNTAIN AVENUE
Complete	1,500	1,500	A&G MAC INC	60 DAYTON AVE
Complete	4	4	MELLADAM, LLC.	517 LOYNS
Complete	13,200	13,200	A&G MAC INC	60 DAYTON AVE
Complete	300	300	Latino's View	209 EAST MAIN STREET

Owner City	Owner Zipcode	Owner Cell Owner Tele Applicant N Applicant & Applicant C Applicant Z A	nnlicant (Closure Cor F	Permit Is U
RARITAN	8869	OBERTS MA 15-17 MAIL BOUND BR(8805	ppriodite colosure corr	FALSE
RARITAN	8869			FALSE
BOUND BROOK	8805			FALSE
BOUND BROOK	8805			FALSE
BOUND BROOK	8805		Leticia, Roc	FALSE
Bridgewater	8807	(732) 648-3680	,	FALSE
Bridgewater	8807	(732) 648-3680		FALSE
BOUND BROOK	8805	,	Leticia, Roc	FALSE
BOUND BROOK	8805		•	FALSE
MARTINSVILLE	8836			FALSE
MARTINSVILLE	8836			FALSE
BOUND BROOK	8805	JOAQUIN A 10 MAIDEN BOUND BR(8805		FALSE
WEST CALDWELL	7006			TRUE
WEST CALDWELL	7006			FALSE
WEST CALDWELL	7006			FALSE
WEST CALDWELL	7006			FALSE
WEST CALDWELL	7006			FALSE
WEST CALDWELL	7006			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
Bound Brook	8805			FALSE
BASKING RIDGE	7920			FALSE
Basking Ridge		(908) 456-4 (908) 901-0566		FALSE
LONG BRANCH	7740			FALSE
LONG BRANCH	7740			FALSE
LONG BRANCH	7740			FALSE
LONG BRANCH	7740			FALSE
PLAINFIELD	7060			FALSE
BOUND BROOK	8805			FALSE
SOMERSET	8873			FALSE

CONTENCET	0073		FALCE
SOMERSET	8873		FALSE
SOMERSET	8873		TRUE
SOMERSET	8873		FALSE
BOUND BROOK	8805		FALSE
BOUND BROOK	8805		FALSE
		Imported fr	FALSE
SOMERSET	8873		FALSE
IRVINGTON	7111		FALSE
SOMERSET	8873		FALSE
		Imported fr	FALSE

0	FALSE	FALSE
0	FALSE	FALSE

0	FALSE	FALSE
0	FALSE	FALSE

```
1/5/21 OBERTS MA 15-17 MAIDEN LANE
11/16/20
 6/13/18 11/13/18
 3/24/16
           6/4/18
 3/16/16
           4/5/16
 1/30/15 10/20/20
 1/5/15 1/15/15
11/25/14 10/20/20
 5/22/12 10/20/20
 9/8/11 10/20/20
 3/19/10 10/20/20
 5/11/07 4/11/14
 9/2/21 10/20/21 JOAQUIN A 10 MAIDEN (929) 485-5
 7/10/18 7/12/18
 3/26/18 7/12/18
 3/29/18
           5/1/18
 8/25/09 12/18/09
 5/19/07
          5/19/07
 4/29/07
          4/29/07
 8/16/13
          5/8/14
 1/26/12 2/22/12
 1/3/12
          5/8/14
 5/11/10 5/11/10
 5/1/10 10/31/11
 3/21/10
           5/8/14
 12/1/09 12/7/09
11/14/09
          5/8/14
10/26/09
         12/7/09
 9/10/09
          9/15/09
 9/3/09
          9/30/09
 8/18/09 8/28/09
 5/15/07
         7/22/08
 7/5/10
         7/29/10
          6/12/07
 5/19/07
           8/3/11
 6/18/11
```

4/1/11	5/19/11
11/23/10	6/16/11
11/8/10	6/16/11
8/26/10	6/16/11
8/26/10	6/16/11
1/6/09	6/16/11
2/25/08	6/16/11
7/1/15	9/22/15
7/15/14	8/7/14
2/8/07	2/8/07
2/8/07	4/21/16
2/8/07	2/8/07
2/8/07	2/8/07
2/8/07	2/8/07
2/8/10	4/20/10
4/9/09	11/7/18
5/19/07	6/8/07
2/8/07	11/7/18

Tenant Cell AgentID	Agent Namı Agent Addr	Agent City	Agent State	Agent ZipCo	Agent Telep Agent Fax	Agent Repri R	emoved	Is Non UCC Is	Template
15,160	OBERTS MAIDEN LLC	BOUND BRO	NJ	08805-		Professiona	FALSE	FALSE	FALSE
14,103	SCHWALL, (16 OBERT D	RARITAN	NJ	08869-		Owner	FALSE	FALSE	FALSE
13,063	Charlie Sch 15-17 MAII	BOUND BRO	NJ	08805-		Owner	FALSE	FALSE	FALSE
13,057	JEFF BURKE P.O. Box 19	Bound Broo	NJ	08805-	(732) 469-5189	Professiona	FALSE	FALSE	FALSE
12,288	DEFENDER : 27 Horsene	FAIRFIELD	NJ	07004-	(609) 297-8103	Professiona	FALSE	FALSE	FALSE
12,261	PRECISION 941 EAST N	BRIDGEWA	NJ	08807-	(732) 302-5 (732) 302-5	Professiona	FALSE	FALSE	FALSE
12,250	Charlie Sch 941 East Ma	Bridgewate	: NJ	08807-	(732) 648-3680	Owner	FALSE	FALSE	FALSE
10,513	OSCAR CESI 13 EAST SEC	BOUND BRO	NJ	08805-	(908) 986-6650	Professiona	FALSE	FALSE	FALSE
9,989	ARIES ELECT 654 Metapo	BOUND BRO	NJ	08805-		Professiona	FALSE	FALSE	FALSE
8,856	ACTIVE ELE(51 GREENB	NO. PLAINF	: NJ	07060-	(908) 698-7966	Professiona	FALSE	FALSE	FALSE
6,660	Norseman (5 Ilene Cou	Hillboroug	NJ	-	(908) 359-2227	Professiona	FALSE	FALSE	FALSE
748 15,475	JOAQUIN AI 10 MAIDEN	BOUND BRO	NJ	08805-	(929) 485-5748	Professiona	FALSE	FALSE	FALSE
14,134	SUDIA ELEC 2024 AMW	SOMERSET	NJ	08873-	(732) 873-0657	Professiona	FALSE	FALSE	FALSE
14,008	Affordable 601 Route	Hillsborou	NJ	08844-	(908) 229-3219	Other	FALSE	FALSE	FALSE
14,014	JUAN S HO! 337 ELM ST	STIRLING	NJ	07980-		Professiona	FALSE	FALSE	FALSE
8,485	ABSOLUTE (115 E11TH	ROSELLE	NJ	-	(908) 259-9800	Professiona	FALSE	FALSE	FALSE
6,793	AA PRO PLL 906 LINCOL	MIDDLESEX	NJ	08846-	(732) 563-1988	Professiona	FALSE	FALSE	FALSE
6,472			NJ	-		Owner	FALSE	FALSE	FALSE
11,292	P. R. SANDE 100 PARK D	VOORHEES	NJ	08043-	(856) 429-3086	Professiona	FALSE	FALSE	FALSE
10,368	DeWitt Van 365 Talmag	Bound Broo	NJ	08805-	(732) 356-0211	Professiona	FALSE	FALSE	FALSE
10,302	SCHAIBLES 241 VAN SY	HAMPTON	NJ	08827-		Professiona	FALSE	FALSE	FALSE
9,168	Next Gener 20 Maiden	Bound Broo	NJ	08805-	(732) 537-1441	Professiona	FALSE	FALSE	FALSE
9,147	SKILLS CON 14 SOMERV	BASKING RI	l NJ	07920-		Owner	FALSE	FALSE	FALSE
8,921	DESIGN ELE 22 HOWAR	NO. PLAINF	: NJ	-	(908) 561-6404	Professiona	FALSE	FALSE	FALSE
8,654	DeWitt Van 365 Talmag	Bound Broo	NJ	08805-	(732) 356-0211	Professiona	FALSE	FALSE	FALSE
8,634	SKILL TRAD 14 SOMME	BASKING RI	l NJ	07920-		Owner	FALSE	FALSE	FALSE
8,586	Anina Shen 14 Somervi	Basking Rid	l NJ	07920-	(908) 901-0566	Owner	FALSE	FALSE	FALSE
8,515	William Jar P.O. Box 24	Bound Broo	NJ	08805-	(732) 469-0582	Professiona	FALSE	FALSE	FALSE
8,496	BINIEK, STA 409 HOLLY	LONG BRAN	NJ	07740-		Owner	FALSE	FALSE	FALSE
8,472	T.R. Wenige P.O.775	Green Broo	NJ	08812-		Professiona	FALSE	FALSE	FALSE
6,745	JRC SERVICI 435 UNION	MIDDLESEX	NJ	-	(732) 560-1978	Professiona	FALSE	FALSE	FALSE
9,254	Power Solu 444 Lincoln	Middlesex	NJ	08846-	(732) 356-7 (732) 356-7	Professiona	FALSE	FALSE	FALSE
6,784	ALLEN GRO 102 HOLYW	SOMMERSE	NJ	-		Professiona	FALSE	FALSE	FALSE
9,801	SANTONAS 1 CUMBERL	HILLSBORO	NJ	08844-	(908) 359-4 (908) 359-5	Professiona	FALSE	FALSE	FALSE

9,640	A & G MAC 60 DAYTON SOMERSET	NJ	08873-		Owner	FALSE	FALSE	FALSE
9,501	DAYTON IM 31 DAYTON DENVILLE	NJ	07834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
9,480	DAYTON IM 31 DAYTON DENVILLE	NJ	07834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
9,334	DAYTON IM 31 DAYTON DENVILLE	NJ	07834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
9,335	DAYTON IM 31 DAYTON DENVILLE	NJ	07834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
8,145	DAYTON IM 31 DAYTON DENVILLE	NJ	07834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
7,630	DAYTON IM 31 DAYTON DENVILLE	NJ	07834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
12,562	POURNARA 570 WINSC BOUND BRO	NJ	08805-		Owner	FALSE	FALSE	FALSE
11,983	Douglas W€ 225 North ، Manville	NJ	08835-		Other	FALSE	FALSE	FALSE
49		NJ	-		Owner	FALSE	FALSE	FALSE
60		NJ	-		Owner	FALSE	FALSE	FALSE
249		NJ	-		Owner	FALSE	FALSE	FALSE
282		NJ	-		Owner	FALSE	FALSE	FALSE
345		NJ	-		Owner	FALSE	FALSE	FALSE
8,745	KAPPA AWI 12 WASHIN PLAINFIELD	NJ	07060-	(908) 755-0531	Owner	FALSE	FALSE	FALSE
8,596	MELLADAN 517 LYONS IRVINGTON	NJ	07111-		Professiona	FALSE	FALSE	FALSE
6,786	SOLE ELECT 201 HILLSII PISCATAWA	NJ	08854-	(732) 235-0062	Professiona	FALSE	FALSE	FALSE
1,319		NJ	-		Owner	FALSE	FALSE	FALSE

Created By	Residential	DCA Fee Exe	DCA Fee Ov	Total DCA Fee
Leticia Rod	Residential			1
Joanne Awt	Residential			1
Leticia Rod	Residential			1
Leticia Rod	Residential			6
Leticia Rod	Residential			4
Leticia Rod	Residential			3
Leticia Rod	Residential			68
	Non Reside	ntial		1
	Non Reside	Yes		
	Non Reside	Yes		
	Non Reside	Yes		
Leticia Rod	Residential			1
Leticia Rod	Residential			
Leticia Rod	Residential			6
Leticia Rod	Residential			1
	Non Reside	ntial		8
	Non Reside	Yes		
	Non Reside	Yes		
Leticia Rod	Residential			1
	Non Reside	ntial		1
	Non Reside	ntial		2
	Non Reside	Yes		
	Non Reside	ntial		3
	Non Reside	Yes		
	Non Reside	ntial		1
	Non Reside	ntial		3
	Non Reside	ntial		1
	Non Reside			2
	Non Reside	ntial	Yes	1
	Non Reside	ntial		
	Residential		Yes	
	Non Reside	ntial		2
	Residential	Yes		
	Non Reside	ntial		11

	Non Residential		1	
			1	
	Non Residential			
	Non Residential		1	
	Residential		12	
	Residential		14	
	Non Residential		19	
	Residential		44	
Leticia Rod	Residential		1	
Jim Ayotte	Residential		1	
	Non Residential	Yes	2	
	Residential	Yes	4	
	Residential	Yes	1	
	Non Residential	Yes	1	
	Non Residential	Yes	2	
	Non Residential		3	
	Non Reside Yes			
	Non Reside Yes			
	Non Residential	Yes		

Location Address	Registration Type	Is Active	Residential Multi	i Fee Total	Block	Lot
15-17 MAIDEN LANE	Rental Building 1-2 Fam	TRUE	2	400	10	4
217 EAST MAIN STREET	VACANT	TRUE		500	10	10
16 MOUNTAIN AVENUE	Rental Building 1-2 Fam	TRUE	1	250	10	18
18 MOUNTAIN AVENUE	Rental Building 1-2 Fam	TRUE	1	250	10	19

Owner Nam Owner Add Owner Cell Owner Ema Agent Nam Agent Addr Agent Telep Agent Cell Agent Emai

 SCHWALL, 16 OBERT DR
 SCHWALL, 16 OBERT D (732) 648-3680

 PANADERIA 222 EAST MAIN ST.
 PANADERIA 222 EAST N (732) 469-4114

 A & G MAC 238 GRANT AVENUE
 A & G MAC 238 GRANT (386) 214-7897

 18 MOUNT, PO BOX 190
 18 MOUNT, PO BOX 191 (732) 690-8085

Building Manager Name Building Manager Adc Building Manager Email

SCHWALL, CHARLIE & PANNIA MICHELE 16 OBERT DR
PANADERIA LA REINA LLC 222 EAST MAIN ST.
A & G MAC INC C/O A MACCHIAVERNA 238 GRANT AVENUE

18 MOUNTAIN AVELLC PO BOX 190

Location Address	Block Lot	Owner Name	Owner Address	Issue Date	Compliance (Statute	Statute Number	Statute Source	Issuing Officer	Summons Number
15-17 MAIDEN LANE	10	4 SCHWALL, CHARLIE & PANNIA MICHELE	16 OBERT DR	3/3/20	3/10/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
17 MAIDEN LANE	10	4 SCHWALL, CHARLIE & PANNIA MICHELE	16 OBERT DR	3/16/18		Z21	Zoning Chp 21	Leticia Rodriguez	
15-17 MAIDEN LANE	10	4 SCHWALL, CHARLIE & PANNIA MICHELE	16 OBERT DR	6/16/20	6/23/20 17-20.5 Disposal of Garbage	:	20.5 Property Maintenance Chp 17	Tyler Gronau	
11 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	4/6/17		302.9 Defacement of prop	erty Building Officials and Code Administrators (BOCA) 2000	Joe Costa	
11 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	8/31/20	9/7/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
11 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	3/8/21	3/14/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
11 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	3/15/21	3/22/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
11 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	3/22/21	3/29/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	13549
11 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	38 BEECHTREE ROAD	5/13/20	5/20/20 17-20.5 Disposal of Garbage		20.5 Property Maintenance Chp 17	Tyler Gronau	
11 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	38 BEECHTREE ROAD	5/20/20	5/27/20 17-20.5 Disposal of Garbage		20.5 Property Maintenance Chp 17	Tyler Gronau	
11 MAIDEN LANE	10	5 TRUPPELLI, PHYLLIS	11 MAIDEN LANE	8/31/20	9/7/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
219 EAST MAIN STREET	10	9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	9/22/20	9/29/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
219 EAST MAIN STREET	10	9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	10/1/20	10/8/20 17-14.10. Defacement of property.		14.1 Property Maintenance Chp 17	Tyler Gronau	
219 EAST MAIN STREET	10	9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	9/22/20	9/29/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
219 EAST MAIN STREET	10	9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	6/9/21	6/16/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	13775
219 EAST MAIN STREET	10	9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	3/8/21	3/15/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
219 EAST MAIN STREET	10	9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	3/9/21	3/15/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items	:	20.4 Property Maintenance Chp 17	Tyler Gronau	13603
219 EAST MAIN STREET	10	9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	3/15/21	3/22/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
219 EAST MAIN STREET	10	9 SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	3/22/21	3/29/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC or responsible party	217 E MAIN STREET	8/3/17	8/16/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual		26.3 Property Maintenance Chp 17	Joe Costa	
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC or responsible party	217 E MAIN STREET	9/8/17	9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual		26.3 Property Maintenance Chp 17	Joe Costa	10345
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	217 EAST MAIN STREET	1/6/18	1/31/18 17-16.25 Duty to Remove Snow & Ice.		5.25 Property Maintenance Chp 17	Eric Mickelsen	
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	217 E MAIN STREET	5/23/19	5/31/19 17-24.1Duties of owners and tenants.		24.1 Property Maintenance Chp 17	Jose Nieves	11691
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	217 E MAIN STREET	5/15/19	5/21/19 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Joe Costa	11643
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	217 E MAIN STREET	5/15/19	5/29/19 17-30.3 Registration of Vacant Commercial Unit		30.3 Property Maintenance Chp 17	Joe Costa	
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	87 HARRISON AVE	2/19/21		14-7.3 c. Fence	Building & Construction Chp 14	Jose Nieves	
217 EAST MAIN STREET	10	10 PANADERIA LA REINA LLC	87 HARRISON AVE	2/19/21		14-7.3 c. Fence	Building & Construction Chp 14	Jose Nieves	
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	87 HARRISON AVE	9/22/20	9/29/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	87 HARRISON AVE	6/3/21	6/24/21 17-26.5 Registration Fees		26.5 Property Maintenance Chp 17	Jose Nieves	13750
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	87 HARRISON AVE	6/9/21	6/16/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	13774
217 EAST MAIN STREET		10 PANADERIA LA REINA LLC	87 HARRISON AVE	3/22/21	3/29/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	13548
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	7/29/19	8/27/19 17-22.20 Smoke Detection System		22.2 Property Maintenance Chp 17	Jose Nieves	
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	7/29/19	8/27/19 17-22.6 Key Lock Bedroom Doors Not Permitted		22.6 Property Maintenance Chp 17	Jose Nieves	
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	3/11/20	3/18/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	12734
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	3/11/20	3/18/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	3/3/20	3/10/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	7/29/19		5:10-19.2a 1-7	NJAC 5:10	Jose Nieves	
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	18 MOUNTAIN AVENUE	1/14/19		1.10a	NJAC 5:10	Douglas Kowalsky	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	10/7/20	10/14/20 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	10/7/20	10/14/20 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	13343
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	10/14/20	10/21/20 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	6/9/21	6/16/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	6/9/21	6/16/21 3-1.10 Storage of tires.	3-1.10	Police Chp 3	Tyler Gronau	13779
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVE LLC	PO BOX 190	4/14/21		3-1.10	Police Chp 3	Tyler Gronau	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	4/14/21	4/21/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	3/10/21	3/17/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	4/14/21	4/21/21 3-1.10 Storage of tires.	3-1.10	Police Chp 3	Tyler Gronau	13608
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	4/14/21	4/21/21 17-20.4 Appliances, Furniture, Mattresses, Discarded Items		20.4 Property Maintenance Chp 17	Tyler Gronau	13607
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	4/14/21	4/21/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	4/14/21	4/21/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	13606
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	4/14/20	4/22/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE	10	19 18 MOUNTAIN AVELLC	PO BOX 190	4/3/20	4/13/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	4/22/20		3-1.10	Police Chp 3	Tyler Gronau	
18 MOUNTAIN AVENUE		19 18 MOUNTAIN AVELLC	PO BOX 190	4/22/20	5/6/20 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	
209 EAST MAIN STREET		20 A&G MAC INC C/O A. MACCHIAVERNA or responsible party	238 GRANT AVE	8/3/17	8/16/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual		26.3 Property Maintenance Chp 17	Joe Costa	
209 EAST MAIN STREET	10	20 A&G MAC INC C/O A. MACCHIAVERNA or responsible party	238 GRANT AVE	9/8/17	9/8/17 17-26.3 Registration of Vacant Properties; Designation of Responsible Individual		26.3 Property Maintenance Chp 17	Joe Costa	10347
209 EAST MAIN STREET	10	20 A&G MAC INC C/O A. MACCHIAVERNA	238 GRANT AVE	3/8/21	3/15/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	13604
209 EAST MAIN STREET	10	20 A&G MAC INC C/O A. MACCHIAVERNA	238 GRANT AVE	4/8/21	4/15/21 17-20.1 Accumulation of Rubbish, Garbage, Trash and Debris		20.1 Property Maintenance Chp 17	Tyler Gronau	

Permit Number	Permit Issue Date	Control Number	Location Address	Block	Lot	
20-0255	11/16/20	C-20-0436	15-17 MAIDEN LANE		10	4
18-0153	6/20/18	C-18-0252	15-17 MAIDEN LANE - 17 Maiden Lane		10	4
16-0141	3/24/16	C-16-0148	15-17 MAIDEN LANE		10	4
16-0137	3/22/16	C-16-0141	15-17 MAIDEN LANE		10	4
15-0096	2/13/15	C-15-0032	15-17 MAIDEN LANE - 17 MAIDEN LANE - Pellegrini		10	4
15-0008	1/9/15	C-15-0004	15-17 MAIDEN LANE		10	4
14-0567	12/4/14	C-14-0818	15-17 MAIDEN LANE		10	4
12-0237	5/22/12	C-12-0219	15-17 MAIDEN LANE		10	4
11-0391	9/8/11	C-11-0484	15-17 MAIDEN LANE		10	4
10-0140	3/19/10	C-10-0169	15-17 MAIDEN LANE		10	4
07-0429	5/11/07	C-07-02673	15-17 MAIDEN LANE		10	4
21-0204	9/2/21	C-21-0283	10 MAIDEN LANE		10	5
18-0134+A	7/10/18	C-18-0290	11 MAIDEN LANE		10	5
18-0134	6/1/18	C-18-0135	11 MAIDEN LANE		10	5
18-0087	4/6/18	C-18-0142	11 MAIDEN LANE		10	5
09-0326	8/27/09	C-09-0373	11 MAIDEN LANE - Graphic Concepts		10	5
07-0566	5/19/07	C-07-02812	11 MAIDEN LANE		10	5
07-0262	4/29/07	C-07-02463	11 MAIDEN LANE		10	5
13-0338	8/22/13	C-13-0419	219 EAST MAIN STREET		10	9
12-0081	2/22/12	C-12-0041	219 E.MAIN ST		10	9
12-0008	1/4/12	C-12-0006	219 E.MAIN ST		10	9
10-0409	5/11/10	C-10-0490	219 E.MAIN ST		10	9
10-0399	5/6/10	C-10-0473	219 E.MAIN ST		10	9
10-0200	3/21/10	C-10-0239	219 E.MAIN ST		10	9
09-0471	12/4/09	C-09-0545	219 E.MAIN ST		10	9
09-0449	11/16/09	C-09-0526	219 E.MAIN ST		10	9
09-0412	10/26/09	C-09-0479	219 E.MAIN ST - Skill Computing & Trading LLC		10	9
09-0339	9/11/09	C-09-0406	219 E.MAIN ST		10	9
09-0331	9/3/09	C-09-0386	219 E.MAIN ST - Stan's Shoe Shack		10	9
09-0317	8/18/09	C-09-0362	219 E.MAIN ST - Stan's Shoe Shack		10	9
07-0517	5/15/07	C-07-02764	219 E.MAIN ST		10	9
10-0487	7/6/10	C-10-0579	217 E. MAIN ST.		10	10
07-0558	5/19/07	C-07-02803	217 E. MAIN ST.		10	10
11-0180	6/18/11	C-11-0223	16 MOUNTAIN AVE.		10	18

11-0091	4/1/11 C-11-0113	16 MOUNTAIN AVE 1st Floor- Lasered Effects LLC	10	18
08-0065+E	1/5/11 C-10-0847	16 MOUNTAIN AVE.	10	18
08-0065+D	11/9/10 C-10-0823	16 MOUNTAIN AVE.	10	18
08-0065+B	9/7/10 C-10-0663	16 MOUNTAIN AVE.	10	18
08-0065+C	9/7/10 C-10-0664	16 MOUNTAIN AVE.	10	18
08-0065+A	1/16/09 C-09-0005	16 MOUNTAIN AVE.	10	18
08-0065	2/27/08 C-08-00069	16 MOUNTAIN AVE.	10	18
15-0453	9/9/15 C-15-0332	18 MOUNTAIN AVENUE	10	19
14-0375	7/15/14 C-14-0558	18 MOUNTAIN AVENUE	10	19
20060381	11/20/06	18 MOUNTAIN AVENUE	10	19
20060375	11/14/06	18 MOUNTAIN AVE.	10	19
200300182	6/26/06	18 MOUNTAIN AVENUE	10	19
20060172	5/26/06	18 MOUNTAIN AVENUE	10	19
20060113	4/7/06	18 MOUNTAIN AVENUE	10	19
10-0043	2/11/10 C-10-0053	209 E. MAIN ST.	10	20
09-0120	4/9/09 C-09-0125	209 E. MAIN STDi'America	10	20
07-0559	5/19/07 C-07-02805	209 E. MAIN ST.	10	20
20040057	3/3/04	209 EAST MAIN STREET	10	20

Application Date	Application Status	Subcodes U	Work Type	Work Desci
11/16/20	Certificate (CCO) Issued	BPEF	(None)	CCO Inspec
6/13/18	CA and Close Date Issued	BPEF	Alteration	
3/24/16	CCO and Close Date Issued	BPEF	Alteration	
3/16/16	CA and Close Date Issued	P	Alteration	
1/30/15	Voided	Е	Alteration	
1/5/15	CA and Close Date Issued	В	Alteration	
11/25/14	Certificate (CO) Issued	BPEF	Alteration	
5/22/12	Voided	BPEF	Alteration	
9/8/11	CA and Close Date Issued	E	Alteration	
3/19/10	CA and Close Date Issued	Е	Alteration	
5/11/07	Closed with Date	E	Alteration	
9/2/21	Certificate (CCO) Issued	BPEF	(None)	
7/10/18	Finals Passed	E	Alteration	
3/26/18	Finals Passed	EF	Alteration	
3/29/18	CA and Close Date Issued	В	(None)	
8/25/09	CA and Close Date Issued	P	Alteration	
5/19/07	Closed with Date	PEF	Alteration	BOILER REP
4/29/07	Closed with Date	Е	Alteration	
8/16/13	Closed with Date	Е	Alteration	
1/26/12	Closed with Date	Е	Alteration	
1/3/12	CA and Close Date Issued	PEF	Alteration	REPLACEME
5/11/10	Closed with Date	PEF	Alteration	
5/1/10	CA and Close Date Issued	В	Alteration	
3/21/10	CA and Close Date Issued	Е	Alteration	
12/1/09	CA and Close Date Issued	Е	Alteration	
11/14/09	CA and Close Date Issued	В	Alteration	
10/26/09	CCO and Close Date Issued	BPEF	Alteration	
9/10/09	CA and Close Date Issued	PΕ	Alteration	
9/3/09	CCO and Close Date Issued	BPEF	Alteration	
8/18/09	CA and Close Date Issued	В	Demolition	REMOVAL C
5/15/07	CA and Close Date Issued	Р	Alteration	REPLACEME
	CA and Close Date Issued	E	Alteration	
5/19/07	Closed with Date	E	Alteration	
6/18/11	CA and Close Date Issued	E	Alteration	ENTRANCE:

4/1/11	CCO and Close Date Issued	BPEF	Alteration
11/23/10	CA and Close Date Issued	EF	Alteration
11/8/10	CA and Close Date Issued	В	Alteration
8/26/10	CA and Close Date Issued	BPEF	Alteration
8/26/10	CA and Close Date Issued	BEF	Alteration
1/6/09	CA and Close Date Issued	BEF	Alteration
2/25/08	CO and Close Date Issued	BPEF	Alteration
7/1/15	CCO and Close Date Issued	BPEF	Alteration
7/15/14	CCO and Close Date Issued	BPEF	Alteration
11/20/06		BE	Alteration
11/14/06	Closed with Date	В	Alteration
6/26/06			(None)
5/26/06		Р	Alteration
4/7/06		BPF	Alteration
2/8/10	CA and Close Date Issued	В	Alteration
4/9/09	CCO and Close Date Issued	BPEF	Alteration
5/19/07	Closed with Date	E	Alteration
3/3/04	CA and Close Date Issued	Р	Alteration

Work Description Comments

All necessary Zoning Permits and applicable construction permits must be obtained and approved before this space can be occupied and or used.

CCO Inspections for Offices for Firestop/Insulation. 17 Maiden Lane, T&R Insulation and Firestop.

CCO Inspections for Tenant, Nila Nicholas, Candy with a Twist.

Install 1 hand sink & 1-3 bay sink, 1 floor drain.

Low -voltage Burglar Alarm.

Remove & replace roof @ Garage.

Converting 2nd floor of building into 2 new 2 bedroom apartments.

CCO INSPECTION FOR STUDIO, BOOK STORE & INTERNET RENTAL

REPLACE ELECTRICAL PANELS DUE TO FLOOD

REPLACE PANELS DUE TO FLOOD

REPLACE PANEL DUE TO FLOOD

CCO INSPECTION FOR BARBER SHOP

INSTALL (1) RECEPTACLE

Install fire alarm system for windowless basement

iNSTALL 15'4 x 8'3" INNER WALL"

Sewer repair

LACEMENT REPLACEMENT WATER HEATER

REPLACE BREAKERS IN THE PANEL DUE TO THE FLOOD

CONNECTION TO INSTALL A CYCLE CONTROL BOX ON AN EXISTING AC UNIT

WIRE FURNACE ON 1ST FLOOR

ENT FURNACE

REPLACE FURNACE

INSTALL NEW WALL MOUNTED SIGN

REPLACE BREAKERS IN PANEL DUE TO FLOOD

Add two receptacles, one for cash register & one for vending machine.

MINOR FRAMING FOR WINDOWS, CLOSET AND REMOVE NON BEARING WALL

CCO Inspections to open Retail Store - DOLLA SMART

ELECTRIC WATER HEATER

CCO Inspections for Resale of Building. Retail Use

)F 275 TANK IN BASEMENT

ENT FURNACE

INSTALL FUSED DISCONNECT IN THE BASEMENT & PANEL ON 1ST. FLOOR

REPLACE BREAKERS IN PANEL DUE TO FLOOD

INSTALL 2 150 SERVICES

CCO Inspections for Retail Store on 1st. floor. Trophies & Awards, Uniforms & Embroidery.

ADD SMOKE DETECTOR TO SYSTEM

ENCLOSURE OF EXISTING STAIRWAY

CONVERT 2ND FLOOR OFFICE INTO A LIVING UNIT

DUCTWORK, EXTRA ELECTRICAL & SMOKE DETECTORS ON 2ND FLOOR

ENCLOSED STAIR CASE FOR 2ND EXIT

2ND FLOOR APARTMENT

CCO Inspections, 18 Mountain Ave.. Tenant: BBRP Downtown Business Improvement Office.

CCO FOR THRIFT STORE

INSTALL NEW AWNING
CCO INSPECTIONS FOR RETAIL STORE - Buy Gold, Repair watches, sell perfumes, used electronics, tools, passport photos.
REPLACE PANEL DUE TO FLOOD

Checklist St To	otal Const Al	lteration (Owner Name	Owner Address	Owner Address 2
Complete			SCHWALL, CHARLIE & PANNIA MICHELE	14 OBERT DR	
Complete	4	4	SCHWALL, CHARLIE & PANNIA MICHELE	16 OBERT DR	
Complete	4	4	Charlie Schwall & Michele Pannia	15-17 MAIDEN LANE	
Complete	3,500	3,500	Charlie Schwall & Michele Pannig	15-17 MAIDEN LANE	
Complete	2,231	2,231	Maiden Holding LLC	Box470	
Complete	1,800	1,800	Charlie Schwall	941 East Main Street	
Complete	36,000	36,000	Charlie Schwall	941 East Main Street	
Complete	4	4	GOMERO, RODOLFO & SOLEDAD	15-17 MAIDEN LANE	
Complete	900	900	GOMERO, RUDOLAFO	15-17 MAIDEN LANE	
Complete	900	900	REDINGTON, ELINOR S.	2286 BROOKSIDE DRIVE	
Complete	1,200	1,200	REDINGTON, ELINOR S.	2286 BROOKSIDE DRIVE	
Complete			GERARDO MELENDEZ	301-307 EAST MAIN ST.	
Complete	95	95	TRUPPELLI, PHYLLIS	38 BEECHTREE ROAD	
Complete	3,000	3,000	TRUPPELLI, PHYLLIS	38 BEECHTREE ROAD	
Complete			TRUPPELLI, GERALD	38 BEECHTREE ROAD	
Complete	4,500	4,500	TRUPPELLI, PHYLLIS	38 BEECHTREE RD	
Complete	16,700	16,700	TRUPPELLI, PHYLLIS	38 BEECHTREE RD	
Complete	600	600	TRUPPELLI, PHYLLIS	38 BEECHTREE RD	
Complete	200	200	SKILL COMPUTING & TRADING, LLC	14 SUMMERVILLE ROAD	
Complete	600	600	SKILL COMPUTER & TRADING	14 sOMERVILLE ROAD	
Complete	1,100	1,100	KINNY, SCOTT	14 SOMERVILLE ROAD	
Complete	3,700	3,700	SKILLS COMPUTING & TRADING LLC.	14 SOMERVILLE ROAD	
Complete	2,000	2,000	SKILLS COMPUTING & TRADING COMPANY	14 SOMERVILLE ROAD	
Complete	300	300	SKILL COMPUTING & TRADING LLC.	14 SIMERVILLE ROAD	
Complete	300	300	Skill Trade & Computing, LLC	219 East Main Street	
Complete	1,600	1,600	SKILL TRADING AND COMPLUTING	14 SOMMERVILLE ROAD	
Complete	4	4	Anina Shen	14 Somerville Rd.	
Complete	1,250	1,250	BINIEK, STANLEY JR. & ELOISE	409 HOLLYWOOD AVENUE	
Complete	4	4	BINIEK, STANLEY JR. & ELOISE	409 HOLLYWOOD AVENUE	
Complete	675	675	BINIEK, STANLEY JR. & ELOISE	409 HOLLYWOOD AVENUE	
Complete	1,800	1,800	BINIEK, STANLEY JR. & ELOISE	409 HOLLYWOOD AVENUE	
Complete	1,400	1,400	ORTIZ, GUSTAVO	428 DARROW AVENUE	
Complete	600		SWERDLOW, JACOB	311 WEST UNION AVENUE	
Complete	6,400	6,400	A & G MAC INC	60 DAYTON AVENUE	

Complete	4	4	A & G MAC INC	60 DAYTON AVENUE
Complete	370	370	A & G MAC INC	60 DAYTON AVENUE
Complete	550	550	A & G MAC INC	60 DAYTON AVENUE
Complete	7,000	7,000	A & G MAC INC	60 DAYTON AVENUE
Complete	8,585	8,585	A & G MAC INC	60 DAYTON AVENUE
Complete	14,250	14,250	A & G MAC INC	60 DAYTON AVENUE
Complete	32,600	32,600	A & G MAC INC	60 DAYTON AVENUE
Complete	4	4	POURNARAS, SPYRIDON & PHYLLIS	570 WINSOR STREET
Complete	4	4	POURNARAS, SPYRIDON & PHYLLIS	570 WINSOR STREET
Complete	1,250		Marc Kissel Tenant	18 MOUNTAIN AVENUE
Complete	3,200		Spyridon Pournaras	18 MOUNTAIN AVE.
Complete	400		Spyridon Pournaras	18 MOUNTAIN AVENUE
Complete	400		Spyridon & Phyllis Pournaras	18 MOUNTAIN AVENUE
Complete	1,580		Spyridon Pournaras	18 MOUNTAIN AVENUE
Complete	1,500	1,500	A&G MAC INC	60 DAYTON AVE
Complete	4	4	MELLADAM, LLC.	517 LOYNS
Complete	13,200	13,200	A&G MAC INC	60 DAYTON AVE
Complete	300	300	Latino's View	209 EAST MAIN STREET

Owner City	Owner Zipcode	Owner Cell Owner Tele Applicant N Applicant & Applicant C Applicant Z Ap	onlicant (Closure Cor F	Permit Is U
RARITAN	8869	OBERTS MA 15-17 MAIL BOUND BR(8805	spriodire e orosar e cor i	FALSE
RARITAN	8869			FALSE
BOUND BROOK	8805			FALSE
BOUND BROOK	8805			FALSE
BOUND BROOK	8805		Leticia, Roc	FALSE
Bridgewater	8807	(732) 648-3680		FALSE
Bridgewater	8807	(732) 648-3680		FALSE
BOUND BROOK	8805	,	Leticia, Roc	FALSE
BOUND BROOK	8805		,	FALSE
MARTINSVILLE	8836			FALSE
MARTINSVILLE	8836			FALSE
BOUND BROOK	8805	JOAQUIN AI 10 MAIDEN BOUND BR(8805		FALSE
WEST CALDWELL	7006			TRUE
WEST CALDWELL	7006			FALSE
WEST CALDWELL	7006			FALSE
WEST CALDWELL	7006			FALSE
WEST CALDWELL	7006			FALSE
WEST CALDWELL	7006			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
BASKING RIDGE	7920			FALSE
Bound Brook	8805			FALSE
BASKING RIDGE	7920			FALSE
Basking Ridge		(908) 456-4 (908) 901-0566		FALSE
LONG BRANCH	7740			FALSE
LONG BRANCH	7740			FALSE
LONG BRANCH	7740			FALSE
LONG BRANCH	7740			FALSE
PLAINFIELD	7060			FALSE
BOUND BROOK	8805			FALSE
SOMERSET	8873			FALSE

CONTENCET	0073		FALCE
SOMERSET	8873		FALSE
SOMERSET	8873		TRUE
SOMERSET	8873		FALSE
BOUND BROOK	8805		FALSE
BOUND BROOK	8805		FALSE
		Imported fr	FALSE
SOMERSET	8873		FALSE
IRVINGTON	7111		FALSE
SOMERSET	8873		FALSE
		Imported fr	FALSE

0	FALSE	FALSE
0	FALSE	FALSE

FALSE	FALSE
FALSE	FALSE
	FALSE

```
1/5/21 OBERTS MA 15-17 MAIDEN LANE
11/16/20
 6/13/18 11/13/18
 3/24/16
           6/4/18
 3/16/16
           4/5/16
 1/30/15 10/20/20
 1/5/15 1/15/15
11/25/14 10/20/20
 5/22/12 10/20/20
 9/8/11 10/20/20
 3/19/10 10/20/20
 5/11/07 4/11/14
 9/2/21 10/20/21 JOAQUIN A 10 MAIDEN (929) 485-5
 7/10/18 7/12/18
 3/26/18 7/12/18
 3/29/18
           5/1/18
 8/25/09 12/18/09
 5/19/07
          5/19/07
 4/29/07
          4/29/07
 8/16/13
          5/8/14
 1/26/12 2/22/12
 1/3/12
          5/8/14
 5/11/10 5/11/10
 5/1/10 10/31/11
 3/21/10
           5/8/14
 12/1/09 12/7/09
11/14/09
          5/8/14
10/26/09
         12/7/09
 9/10/09
          9/15/09
 9/3/09
          9/30/09
 8/18/09 8/28/09
 5/15/07
         7/22/08
 7/5/10
         7/29/10
          6/12/07
 5/19/07
           8/3/11
 6/18/11
```

4/1/11	5/19/11
11/23/10	6/16/11
11/8/10	6/16/11
8/26/10	6/16/11
8/26/10	6/16/11
1/6/09	6/16/11
2/25/08	6/16/11
7/1/15	9/22/15
7/15/14	8/7/14
2/8/07	2/8/07
2/8/07	4/21/16
2/8/07	2/8/07
2/8/07	2/8/07
2/8/07	2/8/07
2/8/10	4/20/10
4/9/09	11/7/18
5/19/07	6/8/07
2/8/07	11/7/18

Tenant Cell AgentID	Agent Namı Agent Addr	Agent City	Agent State	Agent ZipCo	Agent Telep Agent Fax	Agent Repri R	emoved	Is Non UCC Is	Template
15,160	OBERTS MAIDEN LLC	BOUND BRO	NJ	08805-		Professiona	FALSE	FALSE	FALSE
14,103	SCHWALL, (16 OBERT D	RARITAN	NJ	08869-		Owner	FALSE	FALSE	FALSE
13,063	Charlie Sch 15-17 MAII	BOUND BRO	NJ	08805-		Owner	FALSE	FALSE	FALSE
13,057	JEFF BURKE P.O. Box 19	Bound Broo	NJ	08805-	(732) 469-5189	Professiona	FALSE	FALSE	FALSE
12,288	DEFENDER : 27 Horsene	FAIRFIELD	NJ	07004-	(609) 297-8103	Professiona	FALSE	FALSE	FALSE
12,261	PRECISION 941 EAST N	BRIDGEWA	NJ	08807-	(732) 302-5 (732) 302-5	Professiona	FALSE	FALSE	FALSE
12,250	Charlie Sch 941 East Ma	Bridgewate	: NJ	08807-	(732) 648-3680	Owner	FALSE	FALSE	FALSE
10,513	OSCAR CESI 13 EAST SEC	BOUND BRO	NJ	08805-	(908) 986-6650	Professiona	FALSE	FALSE	FALSE
9,989	ARIES ELECT 654 Metapo	BOUND BRO	NJ	08805-		Professiona	FALSE	FALSE	FALSE
8,856	ACTIVE ELE(51 GREENB	NO. PLAINF	: NJ	07060-	(908) 698-7966	Professiona	FALSE	FALSE	FALSE
6,660	Norseman (5 Ilene Cou	Hillboroug	NJ	-	(908) 359-2227	Professiona	FALSE	FALSE	FALSE
748 15,475	JOAQUIN AI 10 MAIDEN	BOUND BRO	NJ	08805-	(929) 485-5748	Professiona	FALSE	FALSE	FALSE
14,134	SUDIA ELEC 2024 AMW	SOMERSET	NJ	08873-	(732) 873-0657	Professiona	FALSE	FALSE	FALSE
14,008	Affordable 601 Route	Hillsborou	NJ	08844-	(908) 229-3219	Other	FALSE	FALSE	FALSE
14,014	JUAN S HO! 337 ELM ST	STIRLING	NJ	07980-		Professiona	FALSE	FALSE	FALSE
8,485	ABSOLUTE (115 E11TH	ROSELLE	NJ	-	(908) 259-9800	Professiona	FALSE	FALSE	FALSE
6,793	AA PRO PLL 906 LINCOL	MIDDLESEX	NJ	08846-	(732) 563-1988	Professiona	FALSE	FALSE	FALSE
6,472			NJ	-		Owner	FALSE	FALSE	FALSE
11,292	P. R. SANDE 100 PARK D	VOORHEES	NJ	08043-	(856) 429-3086	Professiona	FALSE	FALSE	FALSE
10,368	DeWitt Van 365 Talmag	Bound Broo	NJ	08805-	(732) 356-0211	Professiona	FALSE	FALSE	FALSE
10,302	SCHAIBLES 241 VAN SY	HAMPTON	NJ	08827-		Professiona	FALSE	FALSE	FALSE
9,168	Next Gener 20 Maiden	Bound Broo	NJ	08805-	(732) 537-1441	Professiona	FALSE	FALSE	FALSE
9,147	SKILLS CON 14 SOMERV	BASKING RI	l NJ	07920-		Owner	FALSE	FALSE	FALSE
8,921	DESIGN ELE 22 HOWAR	NO. PLAINF	: NJ	-	(908) 561-6404	Professiona	FALSE	FALSE	FALSE
8,654	DeWitt Van 365 Talmag	Bound Broo	NJ	08805-	(732) 356-0211	Professiona	FALSE	FALSE	FALSE
8,634	SKILL TRAD 14 SOMME	BASKING RI	l NJ	07920-		Owner	FALSE	FALSE	FALSE
8,586	Anina Shen 14 Somervi	Basking Rid	l NJ	07920-	(908) 901-0566	Owner	FALSE	FALSE	FALSE
8,515	William Jar P.O. Box 24	Bound Broo	NJ	08805-	(732) 469-0582	Professiona	FALSE	FALSE	FALSE
8,496	BINIEK, STA 409 HOLLY	LONG BRAN	NJ	07740-		Owner	FALSE	FALSE	FALSE
8,472	T.R. Wenige P.O.775	Green Broo	NJ	08812-		Professiona	FALSE	FALSE	FALSE
6,745	JRC SERVICI 435 UNION	MIDDLESEX	NJ	-	(732) 560-1978	Professiona	FALSE	FALSE	FALSE
9,254	Power Solu 444 Lincoln	Middlesex	NJ	08846-	(732) 356-7 (732) 356-7	Professiona	FALSE	FALSE	FALSE
6,784	ALLEN GRO 102 HOLYW	SOMMERSE	NJ	-		Professiona	FALSE	FALSE	FALSE
9,801	SANTONAS 1 CUMBERL	HILLSBORO	NJ	08844-	(908) 359-4 (908) 359-5	Professiona	FALSE	FALSE	FALSE

9,640	A & G MAC 60 DAYTON SOMERSET NJ	08	8873-		Owner	FALSE	FALSE	FALSE
9,501	DAYTON IM 31 DAYTON DENVILLE NJ	07	7834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
9,480	DAYTON IM 31 DAYTON DENVILLE NJ	07	7834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
9,334	DAYTON IM 31 DAYTON DENVILLE NJ	07	7834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
9,335	DAYTON IM 31 DAYTON DENVILLE NJ	07	7834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
8,145	DAYTON IM 31 DAYTON DENVILLE NJ	07	7834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
7,630	DAYTON IM 31 DAYTON DENVILLE NJ	07	7834-	(973) 625-8624	Professiona	FALSE	FALSE	FALSE
12,562	POURNARA 570 WINSC BOUND BR(NJ	08	8805-		Owner	FALSE	FALSE	FALSE
11,983	Douglas We 225 North Manville NJ	08	8835-		Other	FALSE	FALSE	FALSE
49	NJ	-			Owner	FALSE	FALSE	FALSE
60	NJ	-			Owner	FALSE	FALSE	FALSE
249	NJ	-			Owner	FALSE	FALSE	FALSE
282	NJ	-			Owner	FALSE	FALSE	FALSE
345	NJ	-			Owner	FALSE	FALSE	FALSE
8,745	KAPPA AWI 12 WASHIN PLAINFIELD NJ	07	7060-	(908) 755-0531	Owner	FALSE	FALSE	FALSE
8,596	MELLADAN 517 LYONS IRVINGTON NJ	07	7111-		Professiona	FALSE	FALSE	FALSE
6,786	SOLE ELECT 201 HILLSII PISCATAW/ NJ	08	8854-	(732) 235-0062	Professiona	FALSE	FALSE	FALSE
1,319	NJ	-			Owner	FALSE	FALSE	FALSE

Created By	Residential	DCA Fee Exe	DCA Fee Ov	Total DCA Fee
Leticia Rod	Residential			1
Joanne Awt	Residential			1
Leticia Rod	Residential			1
Leticia Rod	Residential			6
Leticia Rod	Residential			4
Leticia Rod	Residential			3
Leticia Rod	Residential			68
	Non Reside	ntial		1
	Non Reside	Yes		
	Non Reside	Yes		
	Non Reside	Yes		
Leticia Rod	Residential			1
Leticia Rod	Residential			
Leticia Rod	Residential			6
Leticia Rod	Residential			1
	Non Reside	ntial		8
	Non Reside	Yes		
	Non Reside	Yes		
Leticia Rod	Residential			1
	Non Reside	ntial		1
	Non Reside	ntial		2
	Non Reside	Yes		
	Non Reside	ntial		3
	Non Reside	Yes		
	Non Reside	ntial		1
	Non Reside	ntial		3
	Non Reside	ntial		1
	Non Reside			2
	Non Reside	ntial	Yes	1
	Non Reside	ntial		
	Residential		Yes	
	Non Reside	ntial		2
	Residential	Yes		
	Non Reside	ntial		11

	Non Residential		1	
			1	
	Non Residential			
	Non Residential		1	
	Residential		12	
	Residential		14	
	Non Residential		19	
	Residential		44	
Leticia Rod	Residential		1	
Jim Ayotte	Residential		1	
	Non Residential	Yes	2	
	Residential	Yes	4	
	Residential	Yes	1	
	Non Residential	Yes	1	
	Non Residential	Yes	2	
	Non Residential		3	
	Non Reside Yes			
	Non Reside Yes			
	Non Residential	Yes		

Location Address	Registration Type	Is Active	Residential M	ulti Fee Total	Block	Lot
15-17 MAIDEN LANE	Rental Building 1-2 Fam	TRUE	2	400	10	4
217 EAST MAIN STREET	VACANT	TRUE		500	10	10
16 MOUNTAIN AVENUE	Rental Building 1-2 Fam	TRUE	1	250	10	18
18 MOUNTAIN AVENUE	Rental Building 1-2 Fam	TRUE	1	250	10	19

Owner Nam Owner Add Owner Cell Owner Ema Agent Nam Agent Addr Agent Telep Agent Cell Agent Emai

 SCHWALL, 16 OBERT DR
 SCHWALL, 16 OBERT D (732) 648-3680

 PANADERIA 222 EAST MAIN ST.
 PANADERIA 222 EAST N (732) 469-4114

 A & G MAC 238 GRANT AVENUE
 A & G MAC 238 GRANT (386) 214-7897

 18 MOUNT, PO BOX 190
 18 MOUNT, PO BOX 191 (732) 690-8085

Building Manager Name Building Manager Adc Building Manager Email

SCHWALL, CHARLIE & PANNIA MICHELE 16 OBERT DR
PANADERIA LA REINA LLC 222 EAST MAIN ST.
A & G MAC INC C/O A MACCHIAVERNA 238 GRANT AVENUE

18 MOUNTAIN AVELLC PO BOX 190





I Search Again

Go To Sql Statement

CAD Search Results

Incident# Date/Time	Location	Incident Type
19093874 04/13/2019 07:07:28	15-17 MAIDEN	911
0 / 10 / 1 = 0	LANE	ABND/HANGUP
18221690 09/11/2018 18:01:14	15-17 MAIDEN LANE	FIRE ALARM
17263398 11/22/2017 14:24:12	15-17 MAIDEN LANE	FIRE ALARM
$\frac{17030725}{17:59:20} \frac{02/08/2017}{17:59:20}$	15-17 MAIDEN LANE	FIRE ALARM
17011354 01/15/2017 16:31:03	15-17 MAIDEN LANE	OVERDOSE
14156344 09/01/2014 13:21:29	15-17 MAIDEN LANE	FIRE ALARM

SQL Statement Used in Search

select distinct cadinclog.incnum, cadinclog.dtreceived, cadinclog.stnum, cadinclog.stname1, cadinclog.inctype, nbrincidents.incnum pincnum, nf5incidents.incnum fincnum from cadinclog, outer nbrincidents, outer nf5incidents where (cadinclog.muncode = 4) and (cadinclog.stnum like "15-17%") and (cadinclog.stname1 like "MAIDEN LA%") and nbrincidents.cadincnum = cadinclog.incnum and nf5incidents.cadincnum = cadinclog.incnum desc;

■ Search Again





■ Search Again

Go To Sql Statement

CAD Search Results

Incident# Date/Time	Location	Incident Type
21082728 03/29/2021 13:58:17	11 MAIDEN	PARKING
13:58:17	LANE	COMPLNT
19057608 03/06/2019 12:46:33	11 MAIDEN	PARKING
19037608 12:46:33	LANE	COMPLNT
15149584 07/18/2015 09:44:53	11 MAIDEN	911 ABND/HANGUP
13149384 09:44:53	LANE	711 ADND/HANGUI
13161388 10/08/2013 01:47:21	11 MAIDEN	911 ABND/HANGUP
13101388 01:47:21	LANE	711 ADIND/ITANGOI
13138912 08/30/2013 15:24:16	11 MAIDEN	911 ABND/HANGUP
15138912 15:24:16	LANE	711 ADIND/ITANGOI
12060215 04/28/2012 19:32:20	11 MAIDEN	WELFARE CHECK
12000213 19:32:20	LANE	WELFARE CHECK

SQL Statement Used in Search

select distinct cadinclog.incnum, cadinclog.dtreceived, cadinclog.stnum, cadinclog.stname1, cadinclog.inctype, nbrincidents.incnum pincnum, nf5incidents.incnum fincnum from cadinclog, outer nbrincidents, outer nf5incidents where (cadinclog.muncode = 4) and (cadinclog.stnum like "11%") and (cadinclog.stname1 like "MAIDEN LA%") and nbrincidents.cadincnum = cadinclog.incnum and nf5incidents.cadincnum = cadinclog.incnum desc;

■ Search Again





■ Search Again

Go To Sql Statement

CAD Search Results

Incident# Date/Time Location **Incident Type** 21205291 08/04/2021 07:42:30 219 E MAIN ST SUSP INCIDENT 21006773 01/09/2021 00:15:21 219 E MAIN ST 911 ABND/HANGUP 20186615 07/27/2020 00:17:48 219 E MAIN ST OPEN DOOR 16291973 12/19/2016 11:10:27 219 E MAIN ST PARKING COMPLNT 16255974 11/03/2016 16:54:54 219 E MAIN ST PARKING COMPLNT 16236086 10/12/2016 15:17:08 219 E MAIN ST PARKING COMPLNT 16214654 09/16/2016 16:42:59 219 E MAIN ST PARKING COMPLNT 16159158 07/14/2016 10:25:42 219 E MAIN ST PARKING COMPLNT 16113162 05/20/2016 11:06:22 219 E MAIN ST PARKING COMPLNT 15274189 12/18/2015 11:30:19 219 E MAIN ST PARKING COMPLNT 15272647 12/16/2015 14:36:09 219 E MAIN ST FOLLOWUP INVEST 15246589 11/13/2015 13:29:26 219 E MAIN ST PARKING COMPLNT 15177488 08/21/2015 11:12:40 219 E MAIN ST PARKING COMPLNT 15168010 08/09/2015 13:15:38 219 E MAIN ST PARKING COMPLNT 15167168 08/08/2015 11:09:05 219 E MAIN ST PARKING COMPLNT 15166438 08/07/2015 13:09:28 219 E MAIN ST PARKING COMPLNT 15136174 07/01/2015 13:01:22 219 E MAIN ST LOCK OUT 15065508 04/06/2015 11:41:27 219 E MAIN ST PARKING COMPLNT 15059991 03/30/2015 21:20:03 219 E MAIN ST PARKING COMPLNT 15053066 03/21/2015 12:13:39 219 E MAIN ST INJURED ANIMAL 15043963 03/09/2015 14:53:10 219 E MAIN ST PARKING COMPLNT 15039610 03/03/2015 10:31:40 219 E MAIN ST PARKING COMPLNT 15038341 03/01/2015 13:29:42 219 E MAIN ST DISORDERLY PRSN 15012296 01/20/2015 11:04:04 219 E MAIN ST PARKING COMPLNT 15008829 01/15/2015 13:19:36 219 E MAIN ST PARKING COMPLNT

```
15006822 01/12/2015 10:59:02 219 E MAIN ST PARKING COMPLNT
14224145 12/16/2014 15:10:26 219 E MAIN ST PARKING COMPLNT
14212086 11/26/2014 10:45:56 219 E MAIN ST PARKING VIOLATI
14194976 10/30/2014 10:56:26 219 E MAIN ST PARKING COMPLNT
14194176 10/29/2014 08:15:43 219 E MAIN ST PARKING COMPLNT
14179276 10/06/2014 10:58:32 219 E MAIN ST PARKING COMPLNT
14160955 09/08/2014 10:43:31 219 E MAIN ST OPEN DOOR
13206288 12/23/2013 15:25:53 219 E MAIN ST PARKING COMPLNT
13196321 12/06/2013 10:30:02 219 E MAIN ST PARKING COMPLNT
13195274 12/04/2013 16:22:03 219 E MAIN ST PARKING COMPLNT
13195138 12/04/2013 12:46:52 219 E MAIN ST PARKING COMPLNT
13195065 12/04/2013 11:07:16 219 E MAIN ST PARKING COMPLNT
13117847 07/24/2013 17:56:50 219 E MAIN ST CITIZEN COMP
13080814 05/23/2013 10:24:05 219 E MAIN ST CITIZEN COMP
13005762 01/11/2013 14:20:12 219 E MAIN ST SOLICITOR
12143982 09/20/2012 10:25:54 219 E MAIN ST PARKING COMPLNT
12143535 09/19/2012 15:22:57 219 E MAIN ST PARKING COMPLNT
12110815 07/25/2012 12:10:25 219 E MAIN ST PARKING COMPLNT
12095100 06/28/2012 11:34:44 219 E MAIN ST FOLLOWUP INVEST
12095097 06/28/2012 11:28:10 219 E MAIN ST CITIZEN COMP
12066075 05/09/2012 14:12:18 219 E MAIN ST PARKING COMPLNT
12059600 04/27/2012 15:03:27 219 E MAIN ST CITIZEN COMP
8015117 02/23/2008 17:30:18 219 E MAIN ST UNWANTED PERSON
8010398 02/07/2008 12:52:06 219 E MAIN ST 911 ABND/HANGUP
7100892 12/21/2007 12:29:09 219 E MAIN ST FALLS
7013192 02/20/2007 09:02:47 219 E MAIN ST PROP DAMAGE
6067872 08/28/2006 09:30:02 219 E MAIN ST BURGLARY
```

select distinct cadinclog.incnum, cadinclog.dtreceived, cadinclog.stnum, cadinclog.stname1, cadinclog.inctype, nbrincidents.incnum pincnum, nf5incidents.incnum fincnum from cadinclog, outer nbrincidents, outer nf5incidents where (cadinclog.muncode = 4) and (cadinclog.stnum like "219%") and (cadinclog.stname1 like "E MAIN%") and

nbrincidents.cadincnum = cadinclog.incnum and nf5incidents.cadincnum = cadinclog.incnum desc;

■ Search Again





▼ Search Again

Go To Sql Statement

CAD Search Results

Location **Incident Type Incident# Date/Time** 19114559 05/06/2019 10:18:19 217 E MAIN ST LOST PROPERTY 18207112 08/26/2018 01:15:28 217 E MAIN ST WELFARE CHECK 16226203 09/30/2016 14:08:43 217 E MAIN ST ASST PUBLIC 16209885 09/11/2016 01:41:15 217 E MAIN ST CODE ENF REF 16126726 06/04/2016 22:55:45 217 E MAIN ST CODE ENF REF 16049724 03/03/2016 13:06:15 217 E MAIN ST PARKING COMPLNT 14096956 06/04/2014 13:09:54 217 E MAIN ST CODE ENF REF 14093441 05/30/2014 12:17:12 217 E MAIN ST CODE ENF REF 12117789 08/06/2012 16:21:55 217 E MAIN ST ANIMAL COMPLNT 12042928 03/28/2012 12:32:07 217 E MAIN ST CODE ENF REF 11098872 08/25/2011 23:16:08 217 E MAIN ST OPEN DOOR 6066327 08/22/2006 17:54:32 217 E MAIN ST FIGHT 5093447 12/09/2005 13:37:34 217 E MAIN ST 911 NON EMERG

SQL Statement Used in Search

select distinct cadinclog.incnum, cadinclog.dtreceived, cadinclog.stnum, cadinclog.stname1, cadinclog.inctype, nbrincidents.incnum pincnum, nf5incidents.incnum fincnum from cadinclog, outer nbrincidents, outer nf5incidents where (cadinclog.muncode = 4) and (cadinclog.stnum like "217%") and (cadinclog.stname1 like "E MAIN%") and nbrincidents.cadincnum = cadinclog.incnum and nf5incidents.cadincnum = cadinclog.incnum desc;

Search Again





■ Search Again

Go To Sql Statement

CAD Search Results

Incident# Date/Time	L	Location		Incident Type
<u>19334371</u> 12/23/2019	19:04:35 2	209 E MAII	N ST	PARKING COMPLNT
17059126 03/16/2017	15:57:43 2	209 E MAII	N ST	FIRE ALARM
15243328 11/09/2015	11:48:27 2	209 E MAII	N ST	PARKING COMPLNT
15243282 11/09/2015	11:06:27 2	209 E MAI	N ST	PARKING COMPLNT
<u>15197567</u> 09/14/2015	12:48:11 2	209 E MAI	N ST	PARKING COMPLNT
14209592 11/22/2014	11:10:42 2	209 E MAI	N ST	PARKING COMPLNT
14096310 06/03/2014	15:30:16 2	209 E MAI	N ST	UNWANTED PERSON
<u>14089331</u> 05/24/2014	17:55:02 2	209 E MAI	N ST	911 ABND/HANGUP
<u>14029837</u> 02/19/2014	13:06:33 2	209 E MAI	N ST	ASST PUBLIC
14000531 01/02/2014	03:47:45 2	209 E MAI	N ST	FIRE ALARM
14000517 01/02/2014	02:10:03 2	209 E MAI	N ST	BURG ALARM BUSN
<u>13210668</u> 12/31/2013	22:24:58 2	209 E MAI	N ST	FIRE ALARM
<u>13183825</u> 11/14/2013	13:59:08 2	209 E MAI	N ST	FOLLOWUP INVEST
<u>13121762</u> 07/31/2013	14:26:01 2	209 E MAI	N ST	ASSIST PD
<u>13116997</u> 07/23/2013	10:34:34 2	209 E MAI	N ST	FOLLOWUP INVEST
<u>13116958</u> 07/23/2013	09:34:22 2	209 E MAI	N ST	SEIZURE
<u>13072503</u> 05/09/2013	18:33:50 2	209 E MAI	N ST	COMMUNITY POLIC
<u>13071889</u> 05/08/2013	15:53:04 2	209 E MAI	N ST	SOLICITOR
<u>13008952</u> 01/17/2013	15:59:18 2	209 E MAI	N ST	911 ABND/HANGUP
<u>13000779</u> 01/02/2013	15:47:48 2	209 E MAI	N ST	FOLLOWUP INVEST
				FOLLOWUP INVEST
<u>12184379</u> 11/26/2012	10:44:26 2	209 E MAI	N ST	FOLLOWUP INVEST
<u>12160261</u> 10/19/2012	14:24:13 2	209 E MAI	N ST	ASSIST PD
<u>12158465</u> 10/16/2012	13:46:22 2	209 E MAI	N ST	FOLLOWUP INVEST
<u>12158347</u> 10/16/2012	10:04:38 2	209 E MAI	N ST	ASST PUBLIC

```
12158324 10/16/2012 09:30:07 209 E MAIN ST ASST PUBLIC
12150046 10/01/2012 11:55:11 209 E MAIN ST DETAIL
12142878 09/18/2012 13:41:55 209 E MAIN ST BURGLARY
12140051 09/13/2012 10:07:48 209 E MAIN ST DETAIL
12085912 06/12/2012 16:48:43 209 E MAIN ST ASSIST PD
12074047 05/23/2012 12:53:02 209 E MAIN ST SUSP INCIDENT
12071749 05/19/2012 14:06:15 209 E MAIN ST STLN PROPERTY
12053856 04/17/2012 11:33:54 209 E MAIN ST DETAIL
12023216 02/17/2012 20:06:36 209 E MAIN ST LOCK OUT
12023162 02/17/2012 17:57:43 209 E MAIN ST ASSIST PD
12000632 01/02/2012 18:56:10 209 E MAIN ST 911 ABND/HANGUP
11126662 10/19/2011 17:14:02 209 E MAIN ST FOLLOWUP INVEST
11107151 09/06/2011 17:08:47 209 E MAIN ST FIRE ALARM
11082971 07/21/2011 11:43:08 209 E MAIN ST FOLLOWUP INVEST
11076151 07/06/2011 15:46:32 209 E MAIN ST 911 ABND/HANGUP
11069804 06/22/2011 13:03:35 209 E MAIN ST FOLLOWUP INVEST
11069744 06/22/2011 11:38:42 209 E MAIN ST FOLLOWUP INVEST
11063948 06/09/2011 18:08:23 209 E MAIN ST ASSIST PD
11051102 05/12/2011 11:30:36 209 E MAIN ST FOLLOWUP INVEST
11013809 02/09/2011 16:55:33 209 E MAIN ST BURG ALARM BUSN
10122535 12/06/2010 11:05:02 209 E MAIN ST THEFT REPORT
10002268 01/08/2010 12:53:34 209 E MAIN ST SICK PERSON
9090898 11/04/2009 17:22:04 209 E MAIN ST DISPUTE
6079414 10/09/2006 14:25:23 209 E MAIN ST BURGLARY
6043879 06/03/2006 12:31:01 209 E MAIN ST 911 ABND/HANGUP
6043877 06/03/2006 12:26:51 209 E MAIN ST 911 ABND/HANGUP
5082185 10/29/2005 14:11:32 209 E MAIN ST DISPUTE
        10/07/2005 10:51:29 209 E MAIN ST 911 ABND/HANGUP
5075658
5035825
        05/19/2005 10:55:29 209 E MAIN ST 911 ABND/HANGUP
```

select distinct cadinclog.incnum, cadinclog.dtreceived, cadinclog.stnum, cadinclog.stname1, cadinclog.inctype, nbrincidents.incnum pincnum, nf5incidents.incnum fincnum from cadinclog, outer nbrincidents, outer

nf5incidents where (cadinclog.muncode = 4) and (cadinclog.stnum like "209%") and (cadinclog.stname1 like "E MAIN%") and nbrincidents.cadincnum = cadinclog.incnum and nf5incidents.cadincnum = cadinclog.incnum desc;

■ Search Again





■ Search Again

Go To Sql Statement

CAD	Search	Results	

Incident# Date/Time	Location	Incident Type
21191193 07/19/2021 15:17:38	16 MOUNTAIN AVE	UNKNOWN PROBLEM
21154584 06/10/2021 12:39:06	16 MOUNTAIN AVE	FOLLOWUP INVEST
21152629 06/08/2021 15:18:23	16 MOUNTAIN AVE	FOLLOWUP INVEST
$\frac{21152465}{12:24:14} \frac{06/08/2021}{12:24:14}$	16 MOUNTAIN AVE	FOLLOWUP INVEST
21151494 06/07/2021 14:37:58	16 MOUNTAIN AVE	FOLLOWUP INVEST
21033897 02/06/2021 11:27:47	16 MOUNTAIN AVE	PARKING COMPLNT
20129735 05/30/2020 21:53:36	16 MOUNTAIN AVE	FIRE ALARM
$\frac{20007128}{15:19:23} \frac{01/08/2020}{15:19:23}$	16 MOUNTAIN AVE	LOCK OUT
19178747 07/12/2019 11:58:42	16 MOUNTAIN AVE	FOUND PROPERTY
19158240 06/21/2019 09:33:30	16 MOUNTAIN AVE	SUSP MV
$\frac{17174318}{11:55:24} \frac{08/04/2017}{11:55:24}$	16 MOUNTAIN AVE	SUSP MV
16297327 12/26/2016 11:27:04	16 MOUNTAIN AVE	THEFT REPORT
16196402 08/26/2016 12:07:46	16 MOUNTAIN AVE	HARASSMENT
03/09/2016	16 MOUNTAIN	

<u>16054834</u> 17:23:20	AVE	PARKING COMPLNT
16022362 01/29/2016 13:12:45	16 MOUNTAIN AVE	DETAIL
$\frac{15252664}{21:05:51}$	16 MOUNTAIN AVE	PARKING COMPLNT
15132396 06/26/2015 16:11:38	16 MOUNTAIN AVE	MATTER RECORD
15093387 05/10/2015 13:47:12	16 MOUNTAIN AVE	PARKING COMPLNT
$\frac{15086009}{07:54:23} \frac{05/01/2015}{07:54:23}$	16 MOUNTAIN AVE	PARKING COMPLNT
$\frac{12104052}{18:30:17} \frac{07/13/2012}{18:30:17}$	16 MOUNTAIN AVE	911 ABND/HANGUP
$\frac{12044396}{09:47:02} \frac{03/31/2012}{09:47:02}$	16 MOUNTAIN AVE	911 ABND/HANGUP
$\frac{11105711}{12:08:06} \frac{09/03/2011}{12:08:06}$	16 MOUNTAIN AVE	PARKING COMPLNT
$\frac{11049118}{16:59:14} \frac{05/07/2011}{16:59:14}$	16 MOUNTAIN AVE	UNKNOWN PROBLEM

select distinct cadinclog.incnum, cadinclog.dtreceived, cadinclog.stnum, cadinclog.stname1, cadinclog.inctype, nbrincidents.incnum pincnum, nf5incidents.incnum fincnum from cadinclog, outer nbrincidents, outer nf5incidents where (cadinclog.muncode = 4) and (cadinclog.stnum like "16%") and (cadinclog.stname1 like "MOUNTAIN%") and nbrincidents.cadincnum = cadinclog.incnum and nf5incidents.cadincnum = cadinclog.incnum desc;

■ Search Again





■ Search Again

Go To Sql Statement

CAD	Search	Results

Incident# Date/Time	Location	Incident Type
$\frac{21145054}{08:42:49} \frac{06/01/2021}{08:42:49}$	18 MOUNTAIN AVE	CODE ENF REF
$\frac{20322853}{07:59:03} \frac{12/15/2020}{07:59:03}$	18 MOUNTAIN AVE	BORO ORDINANCE
$\frac{20265307}{09:03:08} \frac{10/09/2020}{09:03:08}$	18 MOUNTAIN AVE	CODE ENF REF
$\frac{20118217}{13:55:25} \frac{05/18/2020}{13:55:25}$	18 MOUNTAIN AVE	THEFT REPORT
20064649 03/06/2020 18:34:45	18 MOUNTAIN AVE	NOTIFICATION
19302931 11/18/2019 12:37:56	18 MOUNTAIN AVE	FOUND DRUGS
18179741 07/26/2018 17:47:08	18 MOUNTAIN AVE	FOLLOWUP INVEST
$\frac{18178598}{14:48:27} \frac{07/25/2018}{14:48:27}$	18 MOUNTAIN AVE	BURG MV
$\frac{17285405}{18:26:23} \frac{12/20/2017}{18:26:23}$	18 MOUNTAIN AVE	HARASSMENT
$\frac{16262376}{18:37:35} \frac{11/11/2016}{18:37:35}$	18 MOUNTAIN AVE	LOCK OUT
$\frac{16232702}{08:56:39} \frac{10/08/2016}{08:56:39}$	18A MOUNTAIN AVE	FOLLOWUP INVEST
$\frac{16232535}{00:47:18} \frac{10/08/2016}{00:47:18}$	18 MOUNTAIN AVE	DOMESTIC
16196631 08/26/2016 17:07:13	18A MOUNTAIN AVE	MVC
07/14/2016	18 MOUNTAIN	

<u>16159676</u> 18:57:06	AVE	DIFF BREATHING
15255305 11/24/2015 13:59:52	18 MOUNTAIN AVE	ASSIST
15254958 11/24/2015 05:24:23	18 MOUNTAIN AVE	CRIM MISCHIEF
15216831 10/07/2015 22:16:30	18 MOUNTAIN AVE	DOMESTIC
15130767 06/24/2015 16:54:26	18 MOUNTAIN AVE	HIT & RUN
14135517 08/01/2014 12:53:02	18 MOUNTAIN AVE	FOLLOWUP INVEST
14113787 06/29/2014 14:52:02	18 MOUNTAIN AVE	911 MISDIAL
12179952 11/17/2012 15:18:41	18 MOUNTAIN AVE	911 ABND/HANGUP
$\frac{12084138}{12:38:27} \frac{06/09/2012}{12:38:27}$	18 MOUNTAIN AVE	MATTER RECORD
$\frac{11014144}{12:26:03} \frac{02/10/2011}{12:26:03}$	18 MOUNTAIN AVE	HAZARD

select distinct cadinclog.incnum, cadinclog.dtreceived, cadinclog.stnum, cadinclog.stname1, cadinclog.inctype, nbrincidents.incnum pincnum, nf5incidents.incnum fincnum from cadinclog, outer nbrincidents, outer nf5incidents where (cadinclog.muncode = 4) and (cadinclog.stnum like "18%") and (cadinclog.stname1 like "MOUNTAIN%") and nbrincidents.cadincnum = cadinclog.incnum and nf5incidents.cadincnum = cadinclog.incnum desc;

■ Search Again